

REF:

ASSIGNMENT



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

ATTN: Motor Claim Department

Your Ref No:

Claim Type: Third Party

Accident Date: 07/12/2020

TP Veh Reg No: GBJ4660S

Estimate No: ES2000110

Date: 08 Dec 2020

Policy No:

Veh Reg No: YN362K

Make/Model: ISUZU NHR85AUE4A

Chassis No: JAANHR85E97100032

Engine No: 4JJ1774186

Reg. Date: 11/05/2009

Estimate Repair Cost to Vehicle No :YN362K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price	<i>180sn</i>		<i>200</i>	<i>200</i>
1 FRONT TYRE 195R 15C - LH	400.00	1 PC	400.00	✓
2 FRONT WHEEL RIM - LH	780.25	1 PC	780.25	✓
3 REAR TYRE COVER - LH (TOP)	680.15	1 PC	680.15	✓
4 REAR TYRE COVER BRACKET - FRONT	285.00	1 PC	285.00	X
5 REAR TYRE COVER BRACKET - REAR	285.00	1 PC	285.00	X
			2,430.40	2,430.40
Spare Parts	<i>108</i>			
6 FRONT BUMPER	1,450.85	1 PC	1,450.85	✓
7 HEAD LAMP - LH	725.10	1 PC	725.10	✓
8 FRONT SHOCK ABSORBER - LH	435.80	1 PC	435.80	✓
9 FRONT LOWER ARM - LH	550.40	1 PC	550.40	✓
10 FRONT UPPER ARM - LH	550.40	1 PC	550.40	✓
11 FRONT KNUCKLE ARM - LH	508.90	1 PC	508.90	✓
12 FRONT KNUCKLE ARM BEARING - LH	262.60	1 PC	262.60	✓
13 FRONT RACK END - LH	398.50	1 PC	398.50	X
14 STEERING RACK	2,420.50	1 PC	2,420.50	✓
15 FRONT WINDSCREEN WEATHERSTRIP	390.18	1 PC	390.18	X
16 FRONT CORNER PANEL - LH	350.76	1 PC	350.76	X
17 DASHBOARD	1,265.00	1 PC	1,265.00	X
18 FRONT SIGNAL LAMP - LH	296.78	1 PC	296.78	X
19 FRONT FLOORBOARD PANEL - LH	925.00	1 PC	925.00	X
20 FRONT DOOR - LH	1,782.00	1 PC	1,782.00	✓
21 FRONT DOOR HINGES - LH TOP	350.00	1 PC	350.00	X
22 FRONT DOOR HINGES - LH BOTTOM	350.00	1 PC	350.00	X
23 FRONT DOOR WEATHERSTRIP - LH	188.00	1 PC	188.00	✓
24 FRONT DOOR CHECKER - LH	180.00	1 PC	180.00	X
25 FRONT DOOR CHANNEL - LH	140.00	1 PC	140.00	X
26 FRONT DOOR GLASS MOULDING - LH	225.00	1 PC	225.00	X
27 FRONT DOOR REGULATOR GEAR - LH	267.20	1 PC	267.20	✓
28 FRONT DOOR REGULATOR GEAR MOTOR - LH	403.00	1 PC	403.00	✓
29 FRONT DOOR INNER TRIMBOARD - LH	689.60	1 PC	689.60	X
30 FRONT DOOR ARCH GARNISH - LH	394.40	1 PC	394.40	✓
31 FRONT DOOR PILLAR - LH	688.10	1 PC	688.10	X
32 FRONT DOOR WING MIRROR - LH	260.80	1 PC	260.80	X
33 FRONT STEP PANEL - LH	380.15	1 PC	380.15	✓
34 FRONT STEP GARNISH - LH	298.50	1 PC	298.50	✓
35 FRONT WHEEL ARCH PANEL - LH	321.50	1 PC	321.50	✓



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 07/12/2020
TP Veh Reg No: GBJ4660S

Estimate No: ES2000110
Date: 08 Dec 2020
Policy No:
Veh Reg No: YN362K
Make/Model: ISUZU NHR85AUE4A
Chassis No: JAANHR85E97100032
Engine No: 4JJ1774186
Reg. Date: 11/05/2009

Estimate Repair Cost to Vehicle No : YN362K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
36 FRONT WHEEL ARCH GARNISH - LJ	210.00	1 PC	210.00	X
37 STEERING COLUMN SHAFT	855.00	1 PC	855.00	X
38 FRONT DOOR LOCK - LH	420.15	1 PC	420.15	X
39 FRONT DOOR OUTER HANDLE - LH	220.85	1 PC	220.85	X
40 FRONT DOOR KEY LOCK - LH	145.05	1 PC	145.05	X
41 FRONT DOOR STICKER - LH	850.00	1 PC	850.00	180.50
42 FRONT DOOR OUTER MOULDING - LH	185.05	1 PC	185.05	X
43 FRONT DOOR SUN VISOR - LH	85.15	1 PC	85.15	30.50
			20,420.27	20,420.27
Labour				
44 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,600.00	1 JOB	2,600.00	900
45 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,750.00	1 JOB	1,750.00	900
46 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	180.00	1 JOB	180.00	60
47 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	X
48 TO REMOVE/REFIT DASHBOARD TO FACILITIES REPAIRS.	400.00	1 JOB	400.00	X
49 TO REMOVE/REFIT CUSHION SEAT, FLOOR CARPET TO FACILITIES REPAIRS.	260.00	1 JOB	260.00	80
50 TO REMOVE/TRANSFER LH FRONT DOOR MECHANISMS.	150.00	1 JOB	150.00	60
51 TO REMOVE/REPLACE FRONT LH UNDERCARRIAGE LABOUR.	450.00	1 PC	450.00	220
52 TO CHECK WIRING FUNCTIONS.	120.00	1 JOB	120.00	20
			6,110.00	6,110.00

Total SS 28,960.67

Add GST @ 7% 2,027.25

Total Amount Payable SS 30,987.92

TOTAL: SINGAPORE DOLLAR THIRTY THOUSAND NINE HUNDRED EIGHTY SEVEN AND CENTS NINETY TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "without prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE