



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103037

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 29/04/2021
Reference CC4/FCI20013682/R1es3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. XD 8406E
Insured Veh. SHB 4098L
Claim No. D20004964MFSH
Policy No. D-20094922MFSH
Accident Date 03/12/2020
Inspection Date 15/12/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20013682/R1es3q2	
			Date: 29/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4098L	Veh. Inspected	XD 8406E	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20004964MFSH	Excess (\$)	0.00	
Assign From	VIC	Assign Date	10/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	IVECO TRAKKER 13L AUTO	c.c	12882	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WJM3J3SS40C229857	Colour	WHITE	
Odometer	256107 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	315/80 R22.5	AUFINE	8 mm	
L/H Front Tyre	315/80 R22.5	AUFINE	8 mm	
R/H Rear Tyre	315/80 R22.5 (D)	AUFINE	8/8 mm	
L/H Rear Tyre	315/80 R22.5 (D)	AUFINE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2020	Inspection Date	15/12/2020	
Survey held at	WOODLANDS TRANSPORT SERVICE PTE. LTD. 8 GUL CIRCLE SINGAPORE 629564			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 8406E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PLAST FOOTPLATE LHS	CRACKED	773.95	773.95
1	LHS SIE LAMP	CRACKED	78.60	78.60
1	BUMPER LHS	TO REPAIR SEE LABOUR	623.80	-
	LESS 10% DISCOUNT		-	-85.26
			1,476.35	767.29
	<u>LABOUR</u>			
	TO DISMANTLE DAMAGED PARTS AND INSTALL FRONT LHS PLAST FOOTPLATE ,SIDE LAMP AND FRONT BUMPER LHS.TO REALIGNMENT FRONT BUMPER .INCLUSIVE OF THE REPAIR OF BUMPER LHS .		450.00	400.00
			450.00	400.00
	GRAND TOTAL		1,926.35	1,167.29
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				900.00

Report Ref No. CC4/FCI20013682/R1es3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 8406E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XD 8406E

RE-INSPECTION

