



WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 04/12/20 LOCATION: Gul Workshop
VEHICLE NO: XD8406E Q REF No: Q20/12/1178
DRIVER: MOHD ROHIZAT BIN BUANG DEPARTMENT: WTS Lorry Crane Department
ATTENTION TO: ACCIDENT DATE: 03/12/20
PREPARED BY: Chan Soo Lye REF No: JW-1220-51

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	PLAST FOOTPLATE LHS <i>crk</i>	1	773.95	773.95
2	LHS SIDE LAMP ?	1	78.6	78.60
3	BUMPER LHS <i>repair</i>	1	623.8	623.80
Labour Costs				
1	TO DISMANTLE DAMAGED PARTS AND INSTALL FRONT LHS PLAST FOOTPLATE, SIDE LAMP AND FRONT BUMPER LHS. TO RE-ALIGNMENT FRONT BUMPER.	1	450	<i>400</i> 450.00
TOTAL:				1,926.35
Total Amount				SGD 1,926.35

Remarks:

[Signature] 4/12/20
Signature of Workshop Dpt

[Signature] 4/12/20
Signature of Department Head

Signature of Claim Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: