



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ZAINAL BIN AMAT Reg No/Reg Date SMN8037P / 29/08/201 Date In/Mileage 10/12/2020/ 0 Chassis No MMBSTA13AKH002604 Engine No 3A92UHX7789 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	10/12/2020/ 14:30	QUK	282 / Kevin Leong	60593			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								4500.00
REPLACE FRT BUMPER, BONNET, FRT BOTH FENDER, SUPPORT, BODY KIT & AFFECTED AREA					477x6			2700
REPAIR ON BOTH FRT DOOR, BOTH FRT BODY CHASSIS & FRT LH A-PILLAR								3150
E PNT98000								3850.00
PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, BODY KIT, 2 BOTH FRT DOOR, BOTH FRT CHASSIS, FRT LH A-PILLAR & SUPPORT, PANEL					350 x 9			
E PNT88000								120.00
REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								80.00
A 55900099								450.00
TOP UP AIRCON GAS								
A 11900199								450.00
TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR								
A 11900199								450.00
REPLACE ENGINE COMPONENTS								
A 52900099								450.00
REPLACE DASHBOARD ASSY								
A 52900099								450.00
REPLACE STEERING AIRBAG, PASSENGER AIRBAG & ALL SAFETY BELTS								240.00
E PNT88000								80.00
REPLACE FRT WINDSCREEN GLASS								
M SUNDRY								220.00
TO APPLY WINDSCREEN SEALANT								
M SUNDRY								30.00
TO INSTALL FRT WINDSCREEN SOLAR FILM								
A 54900099								120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								640.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								50.00
TO APPLY ZERTONA COATING ON AFFECTED AREA (provide saki approval)								
M SUNDRY								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ZAINAL BIN AMAT Reg No/Reg Date SMN8037P / 29/08/201 Date In/Mileage 10/12/2020/ 0 Chassis No MMBSTA13AKH002604 Engine No 3A92UHX7789 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	10/12/2020/ 14:30	QUK	282 / Kevin Leong	60593				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
SUNDRIES									
M	HEADLAMP ASSY,LH	BR			1.00	663	660.00	23.00	508.20
M	HEADLAMP ASSY,RH	BR			1.00	663	660.00	23.00	508.20
M	LAMP ASSY,FOG,FR LH	X nn			1.00		303.00	23.00	233.31
M	LAMP ASSY,FOG,FR RH	X nn			1.00		303.00	23.00	233.31
M	TANK,WINDSHIELD WASHER	? x nn			1.00		74.00	23.00	56.98
M	HORN	? x nn			1.00		79.00	23.00	60.83
M	CONDENSER ASSY,A/C REFRIGE	BR			1.00	762	758.00	23.00	583.66
M	INSULATOR,ENG MOUNTING	BR			1.00	205	203.00	23.00	156.31
M	ROD ASSY,ENG ROLL STOPPER	? x nn			1.00		155.00	23.00	119.35
M	INSULATOR,T/M MOUNTING	? BT			1.00		209.00	23.00	160.93
M	MOTOR,COOLING FAN	BT (Photo)			1.00	484	479.00	23.00	368.83
M	SHROUD,COOLING FAN	BR (Photo)			1.00	181	130.00	23.00	100.10
M	FAN,COOLING,LH	BR (Photo)			1.00		77.00	23.00	59.29
M	TANK ASSY,RADIATOR COND	CRU			1.00		42.00	23.00	32.34
M	RADIATOR ASSY	DD (Photo)			1.00	972	967.00	23.00	744.59
M	PANEL,AIR GUIDE	BR (Deflector) (Photo)			1.00		112.00	23.00	86.24
M	COVER,AIR CLEANER	? x nn			1.00		45.00	23.00	34.65
M	BODY ASSY,AIR CLEANER	? x nn			1.00		153.00	23.00	117.81
M	DUCT,A/CLNR INTAKE	BR			1.00		131.00	23.00	100.87
M	MANIFOLD,INLET	? x nn			1.00		562.00	23.00	432.74
M	MODULE,AIR BAG	(Steering) BR			1.00	600	597.00	23.00	459.69
M	SPRING,AIR BAG SENSOR	ARC			1.00	319	318.00	23.00	244.86
M	FACE,FR BUMPER	BR			1.00	706	703.00	23.00	541.31
M	COVER,FR BUMPER	MIS			1.00		13.00	23.00	10.01
M	COVER,HEADLAMP SUPT PANEL	BR			1.00		62.00	23.00	47.74
M	MARK,THREE-DIA	ARC			1.00	70	69.00	23.00	53.13
M	AIR DAM,SIDE,FR RH	X nn			1.00		18.00	23.00	13.86
M	AIR DAM,SIDE,FR LH	X nn			1.00		18.00	23.00	13.86
M	GARNISH,FR BUMPER,LH	X nn			1.00		127.00	23.00	97.79
M	GARNISH,FR BUMPER,RH	X nn			1.00		127.00	23.00	97.79
M	GRILLE,FR UNDER	BR			1.00		165.00	23.00	127.05
M	BRACKET,FR BUMPER,RH	BR			1.00		13.00	23.00	10.01

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ZAINAL BIN AMAT Reg No/Reg Date SMN8037P / 29/08/201 Date In/Mileage 10/12/2020/ 0 Chassis No MMBSTA13AKH002604 Engine No 3A92UHX7789 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/12/2020/ 14:30	QUK	282 / Kevin Leong	60593

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
P BRACKET,FR BUMPER,LH - BR	1.00	13.00	23.00	10.01
M GRILLE,RADIATOR - BR	1.00	557	554.00	426.58
M HOOD - BR	1.00	737	734.00	565.18
M INSULATOR,HOOD - CR4	1.00	177.00	23.00	136.29
M LATCH,HOOD - BT	1.00	69.00	23.00	53.13
M HINGE,HOOD,LH - BT	1.00	56.00	23.00	43.12
M HINGE,HOOD,RH - BT	1.00	56.00	23.00	43.12
M DAM,HOOD - X nn	1.00	20.00	23.00	15.40
M FENDER,FR LH - DD	1.00	500	497.00	382.69
M FENDER,FR RH - DD	1.00	500	497.00	382.69
M PANEL,HEADLAMP SUPPORT,UPR - DD	1.00	66	65.00	50.05
M PANEL ASSY,FR END - DD	1.00	1055.00	23.00	812.35
M GLASS,WINDSHIELD - BR	1.00	990	985.00	758.45
M COVER,FR DECK,RH - BR	1.00	16.00	23.00	12.32
M GARNISH,FR DECK - BR	1.00	178.00	23.00	137.06
M COVER,FR DECK,LH - X nn	1.00	16.00	23.00	12.32
M PANEL,INSTRUMENT (Dashboard) - BR	1.00	730.00	23.00	562.10
M MODULE,PASSENGER AIR BAG - BR	1.00	1672	1664.00	1281.28
M UNPAINTED BODYKITS - BR	1.00	1643.00	20.00	1314.40
M GARNISH,FR PILLAR,LH - MIS	1.00	30.00	23.00	23.10
M EMBLEM ECO - nec	2.00	17.00	00.00	34.00

Estimate

10/12/20, 3.00pm

OD - NH Auth  
EXCESS - ?

17 days

P/P

By Ref - sy

Steve (LKK)

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

## Confirm &amp; accepted by

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	25,201.28
7% GST on	25201.28	1764.09
Total Payable		26,965.37

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.