

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF718L

AAD2012-061

Not Authored
1/1/2020

Vehicle No.:
Chassis No.: **10 DEC 2020**
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHF718L
VF1ABL15AUC281220
RENAULT
LATITUDE
08/12/2020
III
31/12/2014

	PART	LIST	
		<i>Ry</i>	561.70 ✓
1	1 BUMPER COVER REAR	\$	
2	1 BUMPER LOWER REAR	\$	<i>Not 10/11</i> 411.90 ✓
3	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 16.60
4	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 16.60
5	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 98.10
6	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sm</i> 82.10
7	1 BUMPER RETAINER RH REAR	\$	<i>Sm</i> 59.80
8	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sm</i> 80.80
9	1 BUMPER RETAINER LH REAR	\$	<i>Sm</i> 54.20
10	1 ABSORBER REAR	\$	<i>Sm</i> 217.30
11	1 BUMPER BEAM REAR	\$	<i>R</i> 547.80
12	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50
13	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50
14	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80
15	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 404.56
16	1 TAILLAMP LH	\$	<i>Mycm</i> 401.40 ✓
17	1 TAILLAMP RH	\$	<i>Mycm</i> 401.40 ✓
18	1 EXHAUST CAP REAR	\$	<i>Sm</i> 125.40 X
19	1 BOOT REAR	\$	<i>Ry</i> 1,677.20 ✓
20	1 BOOT BADGE 'RENAULT'	\$	<i>Na</i> 82.40 ✓
21	1 BOOT BADGE	\$	<i>Nec</i> 95.80 ✓
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 277.70 X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 277.70 X
24	1 BOOT HINGE LH	\$	<i>R</i> 254.20 X
25	1 BOOT HINGE RH	\$	<i>R</i> 254.20 X
26	1 BOOT LOCK	\$	<i>R</i> 246.60 X
27	1 BOOT LOCK CATCH	\$	<i>R</i> 41.70 X
28	1 BUMPER COVER FRT	\$	<i>Bur</i> 747.20 ✓

Trans-cab Auto Services Pte Ltd

AAD2012-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF718L

29	1 BUMPER UNDERTRAY FRT	\$	<i>Sm</i>	292.50	}
30	1 BUMPER BRACKET KIT FRT LH	\$	<i>Sm</i>	101.40	
31	1 BUMPER RETAINER FRT LH	\$	<i>Sm</i>	101.40	
32	1 BUMPER BRACKET KIT FRT RH	\$	<i>Sm</i>	101.40	
33	1 BUMPER RETAINER FRT RH	\$	<i>Sm</i>	101.40	
34	1 BUMPER SUPPORT FRT	\$	<i>Sm</i>	10.70	
35	1 BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i>	207.21	
36	1 RADIATOR GRILLE	\$	<i>Sm</i>	969.90	
37	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>na</i>	225.36	
38	1 RADIATOR GRILLE FRAME	\$	<i>Sm</i>	686.00	
39	1 FRAME FULL SUPPORT PANEL	\$	<i>Sm</i>	592.70	
40	1 FRAME FULL SUPPORT BRACKET	\$	<i>n</i>	41.60	
		\$		11,840.73	
		10% \$		1,184.07	
		\$		10,656.65	

Special Nett

1	1SET PARKING AID	\$	<i>Sm</i>	700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
9	1 EXHAUST MOUNTING REAR	\$	<i>Sm</i>	17.82	X
10	1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i>	80.00	305N
11	1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i>	80.00	305N
12	1 BUMPER CLIP FRT	\$	<i>na</i>	85.00	X
13	1 BUMPER RETAINER CLIP FRT	\$	<i>na</i>	70.00	X
14	1 BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	70.00	X
15	1 BUMPER FOG LAMP GRILLE CLIP	\$	<i>na</i>	65.00	X
16	1 LICENSE PLATE WITH HOLDER FRT	\$	<i>Sm</i>	120.00	455N
	TOTAL	\$		1,512.82	
	TOTAL PARTS	\$		12,169.47	

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2012-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF718L

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	↳ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	↳ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↳ 170.00	X
To check steering geometry and computer wheel alignment	\$	↳ 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 7,580.00

Over All Total \$ 30,406.13

(LUMP SUM)

Repair Days

10 DAYS
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG FARRER ROAD TOWARDS HOLLAND ROAD . VEHICLE C WAS DRIVING IN FRONT OF MY VEHICLE AND SUDDENLY MAKE A JAM BRAKE . I STOPPED IN TIME BUT VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE AND MY VEHICLE HIT ONTO VEHICLE C . TOTAL 3 VEHICLES INVOLVED AND NO INJURIES .


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time: