

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF718L

AAD2012-061

Not Authored

1/1 Imp @ 4,650.00

Vehicle No:
 Chassis No: **10 DEC 2020**
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHF718L
 VF1ABL15AUC281220
 RENAULT
 LATITUDE
 08/12/2020
III
 31/12/2014

	PART	LIST	
1	1 BUMPER COVER REAR	\$ <i>Ry</i> 561.70	✓
2	1 BUMPER LOWER REAR	\$ <i>Ad 10/11</i> 411.90	✓
3	1 BUMPER REFLECTOR LH	\$ <i>SL</i> 16.60	} X
4	1 BUMPER REFLECTOR RH	\$ <i>SL</i> 16.60	
5	1 BUMPER BRACKET CTR REAR	\$ <i>SL</i> 98.10	
6	1 BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 82.10	
7	1 BUMPER RETAINER RH REAR	\$ <i>SL</i> 59.80	
8	1 BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 80.80	
9	1 BUMPER RETAINER LH REAR	\$ <i>SL</i> 54.20	
10	1 ABSORBER REAR	\$ <i>SL</i> 217.30	
11	1 BUMPER BEAM REAR	\$ <i>R</i> 547.80	
12	1 BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 114.50	
13	1 BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 114.50	
14	1 OUTER PANEL REAR (End Panel)	\$ <i>R</i> 745.80	
15	1 OUTER PANEL REAR (End Panel)TRIM	\$ <i>SL</i> 404.56	
16	1 TAILLAMP LH	\$ <i>MJC/M</i> 401.40	✓
17	1 TAILLAMP RH	\$ <i>MJC/M</i> 401.40	✓
18	1 EXHAUST CAP REAR	\$ <i>SL</i> 125.40	X
19	1 BOOT REAR	\$ <i>Ry</i> 1,677.20	✓
20	1 BOOT BADGE 'RENAULT'	\$ <i>NA</i> 82.40	✓
21	1 BOOT BADGE	\$ <i>MCC</i> 95.80	✓
22	1 BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 277.70	X
23	1 BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 277.70	X
24	1 BOOT HINGE LH	\$ <i>R</i> 254.20	X
25	1 BOOT HINGE RH	\$ <i>R</i> 254.20	X
26	1 BOOT LOCK	\$ <i>R</i> 246.60	X
27	1 BOOT LOCK CATCH	\$ <i>R</i> 41.70	X
28	1 BUMPER COVER FRT	\$ <i>Bur</i> 747.20	✓

Trans-cab Auto Services Pte Ltd

AAD2012-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF718L

29	1 BUMPER UNDERTRAY FRT	\$	Sm	292.50	}
30	1 BUMPER BRACKET KIT FRT LH	\$	Sm	101.40	
31	1 BUMPER RETAINER FRT LH	\$	Sm	101.40	
32	1 BUMPER BRACKET KIT FRT RH	\$	Sm	101.40	
33	1 BUMPER RETAINER FRT RH	\$	Sm	101.40	
34	1 BUMPER SUPPORT FRT	\$	Sm	10.70	
35	1 BUMPER FOG LAMP GRILLE LH	\$	Sm	207.21	
36	1 RADIATOR GRILLE	\$	Sm	969.90	
37	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	na	225.36	
38	1 RADIATOR GRILLE FRAME	\$	Sm	686.00	
39	1 FRAME FULL SUPPORT PANEL	\$	Sm	592.70	
40	1 FRAME FULL SUPPORT BRACKET	\$	n	41.60	
		\$		11,840.73	
		10% \$		1,184.07	
		\$		10,656.65	

Special Nett

1	1SET PARKING AID	\$	Sm	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
9	1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
10	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	305N
11	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	305N
12	1 BUMPER CLIP FRT	\$	na	85.00	X
13	1 BUMPER RETAINER CLIP FRT	\$	na	70.00	X
14	1 BUMPER GRILLE LOWER CLIP	\$	na	70.00	X
15	1 BUMPER FOG LAMP GRILLE CLIP	\$	na	65.00	X
16	1 LICENSE PLATE WITH HOLDER FRT	\$	Sm	120.00	455N
	TOTAL	\$		1,512.82	
	TOTAL PARTS	\$		12,169.47	

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2012-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF718L

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	↳ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	↳ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↳ 170.00	X
To check steering geometry and computer wheel alignment	\$	↳ 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 7,580.00

Over All Total \$ 30,406.13

(LUMP SUM)

Repair Days

10 DAYS
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: