



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 10/12/20
LKK - STEVE

VEHICLE NO : SMJ2183K

MODEL : MIT/ATTRAGE 1.2 CVT

WIP : 60601

Material	:	\$	<u>4,469.85</u>
Labour	:	\$	<u>4,790.00</u>
Sub-Total	:	\$	<u>9,259.85</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>8,959.85</u>
GST 7%	:	\$	<u>627.19</u>
Grand Total	:	\$	<u>9,587.04</u>
Finalise By/Date	:	<u>LARRY ON 21/12/20</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (wk. end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 10/12/2020	Cust No/Name	KCV10532/WONG WEE HON, KEVIN
	Reg No/Reg Date	SMJ2183K / 26/02/2019
	Date In/Mileage	10/12/2020/ 18715
	Chassis/Package	MMBSTA13AKH001219 /DC17P
	Engine No	3A92UHN9345
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/12/2020/ 11:38	BLC	884 / Lauro Songcuan	60601			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E	PNT88000	RENEW FRONT BUMPER, BONNET, FRONT FENDER RH & LH, REPAIR FRONT DOOR RH & LH						1800.00 ✓
E	PNT88000	REMOVE & INSTALL AIRCON CONDENSER AND RADIATOR						100.00 ?
E	PNT98000	SPRAY PAINT FOR FRONT BUMPER, BONNET, FRONT FENDER RH, FRONT FENDER LH, FRONT DOOR RH & FRONT DOOR LH						2100.00 ✓
A	54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						30.00 ✓
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						120.00 ✓
A	54900099	VACUUM & TOP UP AIRCON GAS						80.00 ?
M	SUNDRY	APPLY SEALANT FOR AFFECTED PORTIONS						40.00 ✓
M	SUNDRY	SUNDRIES						20.00 ✓
S	SPECIALISTJOB	SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)						50.00 ✓
E	PNT88000	RENEW FRONT SUPPORT PANEL → <i>supp</i>						450.00 X
X	EXC	EXCESS FOR OWN DAMAGE						-300.00
X	FACE,FR BUMPER ✓			1.00	703.00	23.00	541.31 ✓	
X	MARK,THREE-DIA ✓			1.00	69.00	23.00	53.13 ✓	
X	COVER,HEADLAMP SUPT PANEL ✓			1.00	62.00	23.00	47.74 ✓	
X	GRILLE,FR UNDER ✓			1.00	165.00	23.00	127.05 ✓	
X	BRACKET,FR BUMPER,RH ✓			1.00	13.00	23.00	10.01 ✓	
X	BRACKET,FR BUMPER,LH ✓			1.00	13.00	23.00	10.01 ✓	
X	GRILLE,RADIATOR ✓			1.00	554.00	23.00	426.58 ✓	
X	HOOD ✓			1.00	734.00	23.00	565.18 ✓	

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 10/12/2020	Cust No/Name	KCV10532/WONG WEE HON, KEVIN
	Reg No/Reg Date	SMJ2183K / 26/02/2019
	Date In/Mileage	10/12/2020/ 18715
	Chassis/Package	MMBSTA13AKH001219 /DC17P
	Engine No	3A92UHN9345
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/12/2020/ 11:38	BLC	884 / Lauro Songcuan	60601

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FENDER,FR LH ✓	1.00	497.00	23.00	382.69 ✓
X FENDER,FR RH ✓	1.00	497.00	23.00	382.69 ✓
X PANEL ASSY,FR END ?	1.00	1055.00	23.00	812.35 ?
X PANEL,AIR GUIDE,LH ?	1.00	11.00	23.00	8.47 ?
X HEADLAMP ASSY,RH ✓	1.00	660.00	23.00	508.20 ✓
X HEADLAMP ASSY,LH ✓	1.00	660.00	23.00	508.20 ✓
X PANEL,AIR GUIDE → <i>supp.</i>	1.00	112.00	23.00	86.24 ✓

Z TEXT
OD CLAIM - AIG
DOA: 10/12/2020
SURVEY: STEVE
07 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,469.85		Nett	8,959.85
Labour	4,680.00	7% GST on	8959.85	627.19
Standard Menu	0.00			
Specialist Job	50.00		Total Payable	9,587.04
Diagnostics Job	0.00			
Sundry/Others	-240.00			
Total(w/o GST)	8,959.85			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMJ 2183 K

	<u>Materials</u>		<u>Cost \$</u>
1	Panel, Air Guide	BR	112.00 ✓
		23% Discount	25.76
			<u>86.24</u>
	<u>Labour</u>		
1	Renew Front Support Panel		450.00 ✓
		7% GST	536.24
		Total	<u>37.54</u>
			573.78

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SWT 2183K

WIP: Colo 1 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Panel Assy FR EWD	? / SUPP	- 00		
2	AIR ASSY FR EWD LH	? / SUPP		Steve	
3	Panel AIR GUIDE LH	? / SUPP	- OK	11/12/99, 10:00am	
4	Panel AIR GUIDE	? / SUPP	- RR		
5		? / SUPP			
6	To renew fit support \$450	(?) SUPP			
7	To R/I condenser & Radiator \$100	(?) SUPP			
8	Top up Air con gas \$80	(?) SUPP		Steve 16/12/20	
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	14/12/99, 9:30am	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: atage
 SURVEYOR: Steve

All DTCs

Item	Setting	Information
M.U.T.-3 Version		SEW20011-00
V.C.I. Version		B177
Vehicle Information		A13A 2019MY

SMT 2183K
Before using MUT-3x NOT visit to check all the boards.

2020.12.18

All DTCS

2020.12.18

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCS	
AT/CVT/A-MTTC-SST	KOSOSS_99880010		No DTCS	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCS	
SRS-AIR BAG	KOSOSS_99880010	B1419	Front-LH G sensor open circuit	Active
Air Conditioner	KOSOSS_99880010		No DTCS	
ETACS	KOSOSS_99880010	B1707	Flasher open	Active
Meter	KOSOSS_99880010		No DTCS	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS	

All DTCs

Item	Setting	Information
M.U.T.-3 Version		SEW20011-00
V.C.I. Version		B177
Vehicle Information		A13A 2019MY

SMR2182K
@ use MUT-3x NOT unit to check and Erase all the Sand
JTS JB Done

2020.12.18

All DTCS

2020.12.18

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPi/GDI/DIESEL	KOSOSS_99880010		No DTCS	
AT/CVT/A-MT/TTC-SST	KOSOSS_99880010		No DTCS	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCS	
SRS-AIR BAG	KOSOSS_99880010		No DTCS	
Air Conditioner	KOSOSS_99880010		No DTCS	
ETACS	KOSOSS_99880010		No DTCS	
Meter	KOSOSS_99880010		No DTCS	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS	