



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for KCV10532/WONG WEE HON, KEVIN.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Includes account KAX00008 and operator 442 / CocoLu.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair services like bumper renewal, aircon gas, and electrical checks.

Estimate

Confirm & accepted by
Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

CYCLE & CARRIAGE

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10532/WONG WEE HON, KEVIN Reg No/Reg Date SMJ2183K / 26/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001219 Engine No 3A92UHN9345 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/12/2020/ 16:02		442 / CocoLu	60601

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M INSULATOR, HOOD	1.00	177.00	23.00	136.29
M HINGE, HOOD, LH	1.00	56.00	23.00	43.12
M HINGE, HOOD, RH	1.00	56.00	23.00	43.12
M LATCH, HOOD	1.00	69.00	23.00	53.13
M FENDER, FR LH	1.00	497.00	23.00	382.69
M FENDER, FR RH	1.00	497.00	23.00	382.69
M PANEL ASSY, FR END	1.00	1055.00	23.00	812.35
M PANEL, HEADLAMP SUPPORT, UPR	1.00	65.00	23.00	50.05
M PANEL, AIR GUIDE, LH	1.00	11.00	23.00	8.47
M PANEL, AIR GUIDE, RH	1.00	11.00	23.00	8.47
M COVER, ENG ROOM UNDER, FR	1.00	99.00	23.00	76.23
M GARNISH, FR PILLAR, RH	1.00	30.00	23.00	23.10
M GARNISH, FR PILLAR, LH	1.00	30.00	23.00	23.10
M HEADLAMP ASSY, RH	1.00	660.00	23.00	508.20
M HEADLAMP ASSY, LH	1.00	660.00	23.00	508.20
M TANK, WINDSHIELD WASHER	1.00	74.00	23.00	56.98
M MOTOR, WINDSHIELD WASHER	1.00	30.00	23.00	23.10
M CONDENSER ASSY, A/C REFRIGE	1.00	758.00	23.00	583.66
M PIPE, A/C CONDENSER OUTLET	1.00	305.00	23.00	234.85
M HOSE, A/C COMPR DISCHARGE	1.00	210.00	23.00	161.70
M HOSE, A/C COMPR SUCTION	1.00	231.00	23.00	177.87

Estimate

Steve (LKK)

10/12/20 - 4:30pm
 OD - Not Auth
 Excess - ?
 7 days
 P/P
 My Bel Spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

Confirmation accepted by allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Authorized signatory and company stamp

	Nett	11,791.68
7% GST on	11791.68	825.42
Total Payable		12,617.10

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or You must also agree to pay full amount for renewal of the windscreen.