

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

1984 CC

2018 Oct

WAUZZZF44JA229074

ESTIMATE OF REPAIR

Veh# : SDD525J

TP AIG.

Model:

AUDI A4

Accident Date : 10/12/20

Xiao Tony

29/10/2018

Location : AYE TOWARDS MCR BEFORE ALEXANDRA EXIT

3P:

MN8037P (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Rehnd</i>	2,106.72	✓	
2	10pcs	Rear bumper clips <i>re</i>		56.23	✓
3	2pcs	Rear bumper screw clips <i>new</i>		40	+
4	1pc	Rear bumper tow cover <i>Rehnd</i>	25.55	✓	
5	1pc	Rear bumper enforcement <i>Best</i>	845.85	✓	
6	2pcs	Rear bumper o/s & n/s reflector <i>could</i>	76.05	✓	
7	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	80.21	+	
8	2pcs	Rear bumper o/s & n/s inner retainer <i>new</i>	40.04	+	
9	1pc	Rear bumper middle retainer <i>new</i>	155.60	+	
10	4pcs	Rear reverse sensor <i>2 pieces changed</i>	1,086.02	543.01	
11	1pc	Rear end panel <i>Dischd</i>	774.28	✓	
12	1pc	Rear end panel inner trim <i>could</i>	161.14	✓	
13	4pcs	Rear end panel inner trim clips <i>re</i>		13.00	✓
14	2pcs	Rear o/s & n/s tail-lamp <i>ut</i>	1,813.76	✓	
15	2 pcs	Rear o/s & n/s tail-lamp garnish <i>stem</i>	50	+	
16	1pc	Rear boot cover <i>Rehnd</i>	2,495.55	✓	
17	1pc	Rear boot cover weatherstrip <i>ut</i>	187.79	✓	
18	1 pc	Rear boot cover inner trim <i>Rehnd</i>	331.70	✓	
19	1pc	Rear boot cover emblem <i>2</i>	121.80	✓	
20	1pc	Rear boot cover 'A4' emblem <i>per</i>	93.99	✓	
21	1pc	Rear boot cover 'TFSI' emblem	93.99	✓	
22	2 pcs	Rear boot cover o/s & n/s hinges <i>new</i>	443.95	+	
23	1pc	Rear boot cover lock (Upper) <i>Dmgd</i>	173.75	✓	
24	1 pc	Rear boot lock garnish (Upper) <i>ut</i>	161.10	✓	
25	2 pcs	Rear boot cover o/s & n/s lamp <i>ut</i>	1791.50	✓	
26	1pc	Rear boot floor panel <i>Rehnd</i>	2,146.63	✓	
27	1pc	Rear boot floor panel insulator <i>re</i>	699.14	200 (SN)	
28	1 pc	Rear spare wheel tank <i>new</i>	251	+	
29	1 pc	Rear spare wheel board cover <i>Rehnd</i>	699.14	✓	
30	1 pc	Rear exhaust muffler <i>RH Best</i>	2,598.31	831	
31	2 pcs	Rear exhaust muffler mounting <i>new</i>	114.27	+	
32	2 pcs	Rear o/s & n/s exhaust heat shield <i>comped</i>	298.40	✓	

33	1 pc	Rear keyless entry module <i>Repl</i>	315.60	✓		
34	1 pc	Hazard parking triangle <i>Repl</i>		✓ 150		
35	1 pc	Rear battery circuit breaker <i>Activated</i>	624.50	✓		
36	1 pc	Rear reg. no. plate <i>Best</i>		✓ 45		
37	1 pc	Rear reg. no. plate bracket <i>Repl</i>		✓ 29		
38	1 pc	Front bumper <i>Repl</i>	2,094.24	✓		
39	1 pc	Front bumper lower diffuser <i>new</i>	545	x		
40	4 pcs	Front bumper clips <i>m</i>		220.81	50	
41	2 pcs	Front bumper o/s & n/s retainer <i>new</i>	69.03	x		
42	1 pc	Front bumper enforcement <i>Best</i>	755.63	✓		
43	1 pc	Front bumper enforcement bracket <i>culd</i>	110	✓		
44	1 pc	Front bumper insulator <i>culd</i>	320.97	✓		
45	1 pc	Front bumper parking sensor <i>Repl</i>	271.51	✓		
46	1 pc	Front bonnet <i>Repl</i>	2,219.69	✓		
47	1 pc	Front bonnet weatherstrip (middle) <i>cut</i>	80	✓		
48	2 pcs	Front bonnet o/s & n/s lock <i>new</i>	256	x		
49	1 pc	Front o/s & n/s head lamp <i>culd</i>	15386	18,685.29	✓	
50	2 pcs	Front o/s & n/s head lamp washer <i>new</i>	229	x		
51	1 pc	Front o/s fender <i>Repl</i>	898	x		
52	1 pc	Front support panel <i>new</i>	1,040.98	x		
53	1 pc	Front support panel top trim <i>Repl</i>	150	x		
54	1 pc	Front support panel top garnish <i>culd</i>	290	✓		
55	1 pc	Front grille <i>culd</i>	1,341.80	✓		
56	1 pc	Front grille chrome <i>new</i>	2301	x		
57	1 pc	Front grille emblem <i>m</i>	121.75	✓		
58	1 pc	Condenser <i>Repl</i>	869.50	✓		
59	1 pc	Radiator <i>new</i>	1430	x		
60	2 pcs	Radiator o/s & n/s cover <i>culd</i>	80	✓		
61	1 pc	Front tow cover <i>new</i>	48.82	x		
62	2 pcs	Front o/s & n/s fog lamp garnish <i>new</i>	128.25	x		
63	2 pcs	Front o/s & n/s seat belt <i>Activated</i>	2080	2340	✓	
64	1 pc	Front reg. no. plate <i>Best</i>		✓ 45		
65	1 pc	Front reg. no. plate bracket <i>new</i>		x 55		
		Sub-Total:	43,854.01	290.03	0.00	
			5%	0%	10%	
		After Less %:	41,661.30	290.03	0.00	

41903.12 S.N: 364.23
10% : 37712.80

	Labour		
1	To remove & replace front & rear damaged parts.	2,200.00	1820
2	To spray painting.	1,800.00	1500
3	To remove & replace rear exhaust.	200.00	120
4	To remove & replace air condenser	100.00	60
5	To top up condenser gas.	80.00	20
6	To check wiring.	200.00	60
7	To re-seal anti-rust.	100.00	✓
8	To remove & refit reverse sensor.	100.00	50
9	To remove upholstery to facilitate repairs.	200.00	120
10	To remove & reset seatbelt.	200.00	✓
11	To perform diagnostics.	300.00	150
12	To remove & refit front sensor.	80.00	50
	Sub-Total:	5,560.00	
	Total:	53,596.21	
	After less 20%	42,876.97	

4230

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



bizSAFE 8778 1999
24 hr accident call

Mobil 1



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
L/S 14 Days.

Supplementary 1504.75

total: 43811.78

L/S: 35K.

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SDD525J

Accident Date : 10/12/20

Location : AYE TOWARDS MCR BEFORE ALEXANDRA EXIT

Model:

AUDI A4
29/10/2018

3P:

SMN8037P (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear exhaust joint <i>new</i>	80.00	✓	-
2	1pc	Rear end panel lower <i>distilled</i>	365.80	✓	-
3	2pcs	Rear o/s & n/s tail lamp support bracket <i>cut d</i>	80.00	✓	-
4	1pc	Rear bumper lower diffuser <i>distilled</i>	220.00	✓	-
5	4litre	coolant <i>new</i>	80.00	40	-
6	1pc	Rear spare wheel tank color code sticker <i>new</i>	15.00	✓	-
7	1pc	Rear bumper retainer pin <i>new</i>	460.80	✓	-
8	1pc	Rear boot kick sensor module <i>new</i>	196.90	✓	-
9	1pc	Rear radia antenna module <i>cut d</i>	169.00	✓	-
10	1pc	Front support panel middle bracket <i>cut d</i>			
Sub-Total:			840.80	120.00	0.00
			5%	0%	10%
After Less %:			798.76	120.00	0.00
Total:				918.76	
After less 20%				735.01	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



bitSAFE
STAR

8778 1999
24 hr accident call

Mobil 1



PAYNOW