

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 1862G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RIGHT SLIDING DOOR (CONSISTENT)	BENT	1,591.70	1,591.70
1	RIGHT SLIDING DOOR OUTER HANDLE (CONSISTENT)	DENTED	180.70	180.70
1	RIGHT SLIDING DOOR RUBBER (CONSISTENT)	SERVICEABLE	231.70	-
1	EMBLEM 'D4D'(CONSISTENT)	NECESSARY	46.60	46.60
	LESS 20% DISCOUNT		-410.14	-
	LESS 25% DISCOUNT		-	-454.75
			1,640.56	1,364.25
	SPECIAL NETT ITEMS			
1	SIDE PANEL STICKER (SN)(CONSISTENT)	NECESSARY	12.00	12.00
35	RIVERT @\$5.00 (SN)(CONSISTENT)	NOT NECESSARY	175.00	-
			187.00	12.00
	<u>LABOUR</u>			
	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS.		150.00	30.00
	TO CHECK WATER SEEPAGE.		60.00	20.00
	TO CHECK ALIGNMENT.	NOT NECESSARY	120.00	-
	TO TRANSFER SLIDDING DOOR RELATED PART EG STAINLESS STEEL METAL & RELATED FIXING TO NEW SLIDDING DOOR .		180.00	60.00
	TO REPAIR PANEL BEAT ON RIGHT FRT DOOR PILLAR ,LOCKER PANEL ,ALIGN ON RIGHT FRT AFFECTED DOOR & LABOUR TO RE-PLACED ABOVE PARTS.		1,000.00	500.00
	TO PUTTY ,PRIMER & SPRAY PAINT ON RIGHT SLIDDING DOOR ,RIGHT LOCKER PANEL ,FRT DOOR REAR PILLAR & RIGHT FRT DOOR USING 2K PAINT.		1,100.00	450.00
			2,610.00	1,060.00
	GRAND TOTAL		4,437.56	2,436.25



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20013699/Kea3q2

**KONG SENG CHEONG** 

**Licensed Appraiser**