

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

9-Dec-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6985 H

S/NETT

1 pc	n/s door sticker	\$	100.00 ^{neu ✓}
	Sundry	\$	50.00 ✗
	To dismantle and refit the inner component of front n/s door into new shell door	\$	150.00 ✗
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc	\$	200.00 ✓
	To putty and spray painting on front o/s door, o/s rocker panel garnish, o/s mirror cover	\$	600.00 ²⁰⁰
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 ²⁰
		\$	<u>1,300.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tanpin 97495149

WP 16/12/20 330pm

1/2 Resurvey after repair

Tanpin e/Insurance

2 days

Achilles
205/55R16