

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20013708/ABA3Q2
Date: 29/07/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SLS591T

Date of Loss: 03/12/2020

Policy No:

Insured Vehicle No :

SFJ3344P

Nature of Claim:

TP

Claim No:

5914487200SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLS591T**

Make & Model: MAZDA 3, 1.5 (A)

Reg. Date: 05/09/2017 (Man. Year: 2017)

Colour: Red

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: P520462381

Chassis No: JM6BN22A8H0171893

Odometer: 43722 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Front Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Tyre Size:

205/60 R16

Rear Left Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,939.00	1,259.00	1,680.00	57.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	910.00	1,470.00	61.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,319.00	2,169.00	3,150.00	59.22
+ GST 7.00/7.00% (S\$)	372.33	151.83	220.50	59.22

Nett Amount (S\$)	5,691.33	2,320.83	3,370.50	59.22
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
Nett Liability (S\$)		2,706.03		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020

Estimated Period of Repair: 3.0 days

Inspected At:

1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	670.00 FL	*670.00 FL
2	1		*REAR BUMPER TOW COVER	Not Necessary	40.00 FL	*- FL
3	1		*REAR BUMPER GUIDE LH	Not Necessary	40.00 FL	*- FL
4	1		*REAR BUMPER GUIDE RH	Not Necessary	40.00 FL	*- FL
5	1		*REAR BUMPER GUIDE CENTER	Not Necessary	50.00 FL	*- FL
6	1		*REAR REINFORCEMENT	Not Necessary	550.00 FL	*- FL
7	1		*REAR END PANEL	Repair	450.00 FL	*- FL
8	1		*TAILLAMP RH	Not Necessary	390.00 FL	*- FL
9	1		*BOOTLID	Dented	730.00 FL	*730.00 FL
10	1		*BOOTLID LAMP RH	Not Necessary	380.00 FL	*- FL
11	1		*BOOT AIR VENT RH	Not Necessary	110.00 FL	*- FL
12	1		*BOOT EMBLEM	Necessary	50.00 FL	*50.00 FL
13	1		*MAZDA LETTERING	Necessary	40.00 FL	*40.00 FL
14	1		*LETTERING	Necessary	40.00 FL	*40.00 FL
15	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
16	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,655.00	1,565.00
- List Item Discount on L Items 20.00/20.00% (\$)	716.00	306.00
Total Parts (\$)	2,939.00	1,259.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	400.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (REAR BUMPER,RHR FENDER & DOOR)	New	1,000.00	400.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	40.00	30.00
4	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID	New	140.00	80.00
Gross Labour Cost (S\$)			2,380.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >