



# 1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

## ESTIMATION QUOTE

TP Smpo  
Denise

VEHICLE NO : SKX834T  
MAKE MODEL : HONDA CIVIC  
REFERENCE : 1AP-202012-13  
DOA :  
CLAIM TYPE : TP CLAIM

ATTN: MOTOR CLAIMS DEPARTMENT

PAGE 1 OF 3

| LIST ITEMS                                         | QTY | LIST PRICE (\$) | REMARKS |
|----------------------------------------------------|-----|-----------------|---------|
| *FRONT BONNET <i>Buckled</i>                       | 1   | \$ 590.50       | ✓       |
| *FRONT BONNET INNER RUBBER <i>new</i>              | 1   | \$ 181.00       | x       |
| *FRONT BONNET INNER SIDE RUBBER LH / RH <i>new</i> | 2   | \$ 164.00       | x       |
| *FRONT BONNET HINGE LH / RH <i>new</i>             | 2   | \$ 352.00       | x       |
| *FRONT BONNET LOCK <i>new</i>                      | 1   | \$ 185.00       | ✓       |
| *FRONT BONNET LOCK STRIKER <i>new</i>              | 1   | \$ 112.24       | x       |
| *FRONT GRILLE <i>Cracked</i>                       | 1   | \$ 345.90       | ✓       |
| *FRONT GRILLE EMBLEM LOGO <i>new</i>               | 1   | \$ 180.00       | 58      |
| *FRONT BUMPER <i>Distorted</i>                     | 1   | \$ 738.00       | 640.    |
| *FRONT BUMPER SIDE BRACKET LH / RH <i>new</i>      | 2   | \$ 135.00       | 62      |
| *FRONT BUMPER FOG LAMP LH / RH <i>new</i>          | 2   | \$ 601.80       | x       |
| *FRONT BUMPER FOG LAMP COVER LH / RH <i>new</i>    | 2   | \$ 196.00       | x       |
| *FRONT BUMPER REINFORCEMENT <i>Distorted</i>       | 1   | \$ 380.60       | 295     |
| *FRONT HEAD LAMP LH / RH <i>Cracked</i>            | 2   | \$ 1,942.80     | ✓       |
| *FRONT HEAD LAMP LOWER BRACKET LH / RH <i>new</i>  | 2   | \$ 135.80       | x       |
| *FRONT SUPPORT PANEL <i>Repair</i>                 | 1   | \$ 539.40       | x       |
| *FRONT SUPPORT PANEL TOP COVER <i>Del-d</i>        | 1   | \$ 160.80       | ✓       |
| *FRONT SUPPORT PANEL SIDE COVER LH / RH <i>new</i> | 2   | \$ 126.70       | x       |
| *AIRCON CONDENSER <i>Best</i>                      | 1   | \$ 829.00       | ✓       |
| *RADIATOR <i>2 new</i>                             | 1   | \$ 1,392.00     | +       |
| *RADIATOR FAN BLADE <i>new</i>                     | 1   | \$ 158.00       | +       |
| *RADIATOR FAN COWLING <i>new</i>                   | 1   | \$ 119.00       | +       |
| *RADIATOR FAN MOTOR <i>new</i>                     | 1   | \$ 396.00       | +       |
| *FRONT FENDER LH / RH <i>Repair</i>                | 2   | \$ 980.00       | +       |
| *REAR BOOT LID <i>Distorted</i>                    | 1   | \$ 721.40       | 689.    |
| *REAR BOOT LID HINGES LH / RH <i>Best</i>          | 2   | \$ 196.00       | ✓       |
| *REAR BOOT LID EMBLEM LOGO <i>new</i>              | 1   | \$ 135.10       | ✓       |
| *REAR BOOT LID INNER RUBBER <i>new</i>             | 1   | \$ 237.60       | ✓       |
| *REAR BOOT LID INNER LOCK <i>new</i>               | 1   | \$ 294.50       | ✓       |
| *REAR BOOT LID INNER TRIM BOARD <i>Del-d</i>       | 1   | \$ 412.20       | 235     |
| *REAR BOOT LID INNER SIDE RUBBER <i>new</i>        | 1   | \$ 236.40       | x       |

## ESTIMATION QUOTE

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SKX834T  
MAKE MODEL : HONDA CIVIC  
REFERENCE : 1AP-202012-13  
DOA :  
CLAIM TYPE : TP CLAIM

PAGE 2 OF 3

| LIST ITEMS                                             | QTY | LIST PRICE (\$) | REMARKS |
|--------------------------------------------------------|-----|-----------------|---------|
| *REAR BOOT LID LAMP LH / RH <i>crushed</i>             | 2   | \$ 660.00       | ✓       |
| *REAR BOOT LID TOP SPOILER <i>del</i>                  | 1   | \$ 589.00       | ✓       |
| *REAR TAIL LAMP LH / RH <i>crushed</i>                 | 2   | \$ 740.40       | ✓       |
| *REAR TAIL LAMP PANEL LH / RH <i>LH Distorted</i>      | 2   | \$ 297.20       | 148.60. |
| *REAR TAIL LAMP LOWER BRACKET LH / RH <i>Distorted</i> | 2   | \$ 144.00       | ✓       |
| *REAR END PANEL <i>Distorted</i>                       | 1   | \$ 418.30       | ✓       |
| *REAR END PANEL TOP GARNISH <i>del</i>                 | 1   | \$ 191.20       | ✓       |
| *REAR FENDER LH / RH <i>LH Bunched</i>                 | 12  | \$ 841.50       | ✓       |
| *REAR FENDER INNER TRIM BOARD LH / RH <i>del</i>       | 2   | \$ 312.80       | ✓       |
| *REAR BUMPER <i>Distorted</i>                          | 1   | \$ 745.30       | 638     |
| *REAR BUMPER SIDE BRACKET LH / RH <i>new</i>           | 2   | \$ 160.20       | ✓       |
| *REAR BUMPER MUD SHIELD <i>new</i>                     | 1   | \$ 190.00       | X       |
| *REAR EXHAUST <i>Best</i>                              | 1   | \$ 808.50       | ✓       |
| *REAR EXHAUST ALUMINIUM COVER <i>crushed</i>           | 1   | \$ 164.00       | ✓       |
| *REAR EXHAUST CHROME PIPE <i>new</i>                   | 1   | \$ 420.00       | X.      |
| *REAR SPARE TYRE PANEL <i>Bunched</i>                  | 1   | \$ 1,045.30     | ✓       |
| *REAR SPARE TYRE PANEL TOP COVER <i>del</i>            | 1   | \$ 425.90       | 245     |
| *REAR SPARE TYRE PANEL SEALANT <i>new</i>              | 1   | \$ 450.00       | 200.    |
| *REAR SPARE TYRE TOP SPONGE <i>crushed</i>             | 1   | \$ 248.20       | 185     |

*Res Windscreen. 980 ✓*  
*Shattered*  
LESS 20% \$ 4,406.31  
SUBTOTAL \$ 17,625.23  
BALANCE C/F \$ 17,625.23  
*15368.*  
*12294.40*

| SPECIAL NETT ITEMS                                   | QTY   | LIST PRICE (\$) | REMARKS    |
|------------------------------------------------------|-------|-----------------|------------|
| BALANCE B/F                                          |       | \$ 17,625.23    |            |
| *FRONT GRILLE CLIPS <i>new</i>                       | 1     | \$ 50.00        | 20         |
| *FRONT BUMPER CLIPS <i>new</i>                       | 1     | \$ 50.00        | 30         |
| *FRONT BUMPER NUMBER PLATE WITH GARNISH <i>Best</i>  | 1     | \$ 100.00       | 60.        |
| *FRONT SUPPORT PANEL TOP COVER CLIPS <i>new</i>      | 1     | \$ 50.00        | 20.        |
| *REAR BOOT LID NUMBER PLATE WITH GARNISH <i>Best</i> | 1     | \$ 100.00       | 60.        |
| *REAR BOOT LID INNER TRIM BOARD CLIPS <i>new</i>     | 1     | \$ 50.00        | 30         |
| *REAR TAIL LAMP CLIPS <i>new</i>                     | 1     | \$ 50.00        | 20.        |
| *REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>       | 1     | \$ 50.00        | ✓          |
| *REAR BUMPER REVERSE SENSOR <i>new</i>               | 1 SET | \$ 200.00       | ✓          |
| *REAR BUMPER CLIPS <i>new</i>                        | 1     | \$ 50.00        | 30         |
| SUBTOTAL                                             |       | \$ 750.00       |            |
| BALANCE C/F                                          |       | \$ 18,375.23    | <i>520</i> |

## ESTIMATION QUOTE

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SKX834T  
MAKE MODEL : HONDA CIVIC  
REFERENCE : 1AP-202012-13  
DOA :  
CLAIM TYPE : TP CLAIM

PAGE 3 OF 3

| LABOUR                                                                                                        | S/NO | LIST PRICE (\$) | REMARKS          |
|---------------------------------------------------------------------------------------------------------------|------|-----------------|------------------|
| BALANCE B/F \$ 18,375.23                                                                                      |      |                 |                  |
| TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - FRONT AND REAR | 1    | \$ 250.00       | 60.              |
| TO REMOVE AND REFIT AIRCON CONDENSER / RADIATOR TO FACILITATE THE REPAIR                                      | 2    | \$ 300.00       | <del>80</del> 80 |
| TO REMOVE AND REFIT SPARE TYRE PANEL TO FACILITATE THE REPAIR                                                 | 3    | \$ 150.00       | X.               |
| TOP UP AIRCON GAS                                                                                             | 4    | \$ 100.00       | 40.              |
| TOP UP COOLANT                                                                                                | 5    | \$ 100.00       | 40.              |
| TO REMOVE, REFIT AND TEST REVERSE SENSOR                                                                      | 6    | \$ 200.00       | 50               |
| TO REMOVE, STRAIGHTEN AND REFIT EXHAUST LH / RH                                                               | 7    | \$ 300.00       | 80.              |
| PANEL BEATING ON AFFECTED AREA                                                                                | 8    | \$ 3,000.00     | 2200             |
| SPRAY PAINTING                                                                                                | 9    | \$ 3,000.00     | 2000             |
| APPLY ANTI RUST ON AFFECTED AREA                                                                              | 10   | \$ 150.00       | 120.             |

SUBTOTAL \$ 7,550.00

GRAND TOTAL \$ 25,925.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

lkl: 17484.4

4/s: 14K.

17 Days