

NG SIG KIAT
BLK 633 CHOA CHU KANG NORTH 6
#14-301
SINGAPORE 680633

File No :
Date : 10-December-2020

Estimated cost of repair for vehicle no : SLX5963U TOYOTA COROLLA
Accident involving vehicle no: SLX5963U & SFW6263B on 08.12.2020

Description	Quantity	Cost Price
Rear tailgate	1	\$ 725.00
Rear tailgate emblem	1	\$ 61.90
Rear tailgate badge 'Corolla'	1	\$ 61.90
Rear tailgate badge 'Altis'	1	\$ 61.70
LH tailgate inner tail lamp	1	\$ 270.10
LH tailgate inner tail lamp	1	\$ 270.10
Rear tailgate inner lock	1	\$ 352.00
RH tailgate hinge	1	\$ 70.70
RH outer taillamp	1	\$ 379.65
LH outer taillamp	1	\$ 379.65
Rear bumper	1	\$ 480.50
Rear bumper clips	1	\$ 32.00
Rear bumper reinforcement	1	\$ 386.00
RH bumper retainer	1	\$ 91.70
RH bumper bracket	1	\$ 91.70
Rear end panel	1	\$ 645.30
Rear end panel top trim	1	\$ 197.10
		\$ 4,557.00
	less 20%	\$ 911.40
		\$ 3,645.60
Rear tailgate camera	1 S. Nett	\$ 380.00
Rear bumper parking sensor	1 S. Nett	\$ 260.00
Rear bumper sticker	1	\$ 80.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus taillamp.		\$ 35.00
To remove rear damaged parts, to jack out rear end panel , rear floor panel and cut out damaged parts, to reweld, reshape and repair rear end panel, RH rear fender, LH rear fender, tailgate , rear bumper to straighten chassis member and adjust body panel alignment		\$ 750.00



To spray paint affected rear and inner damaged portion inclusive of preparatory works and material	\$	1,100.00
To apply anti-corrosion tuff kote .	\$	100.00
	\$	<u>6,350.60</u>

T/Party: AIG Asia Pacific Insurance Pte Ltd