

# AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721  
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : LAWERENCE LOO TECK HO  
BLK 455B AMK ST 44  
#32-15  
562455

Estimate No: MCS1900368  
Date: 08 Dec 2020  
Policy No: MT/00733975  
Veh Reg No: SLE2803T  
Make/Model: HYUNDAI ELANTRA

ATTN:

Your Ref No: SLE2803T  
Claim Type: Third Party  
Accident Date: 07/12/2020  
TP Veh Reg No: SMP9690K

*Not Notified*  
*Running 84 pain*  
*3 days*

## Estimate Repair Cost to Vehicle No :SLE2803T

Description	Quantity	List Price	Amount
		SS	SS
<b>SPARE PARTS</b>			
1 REAR BUMPER	1 PC	459.40	✓
2 REAR BUMPER REINFORCEMENT	1 PC	480.20	✓
3 REAR BUMPER CLIP	10 PC	60.00	✓
4 REAR BUMPER LOWER GARNISH	1 PC	250.30	✓
5 REAR REFLECTOR LH	1 PC	45.80	✓
6 REAR CENTRE BADGE	1 PC	29.10	✓
		1,324.80	
	Less 20%	264.96	1,059.84
<b>LABOUR</b>			
7 TO CHECK WIRING AND REINSTALL REVERSE SENSOR	1 PC	20.00	✓
8 TO DISMANTLE AND INSTALL DAMAGE PARTS, TO KNOCK AND REPAIR REAR BOOT LID AND REFIT LISTED PARTS BACK SAME.	1 PC	500.00	200
9 TO SPRAY REAR BOOT LID, REAR BUMPER, REAR BUMPER REINFORCEMENT..	1 PC	650.00	400
		1,170.00	1,170.00
Total			S\$ 2,229.84
Add GST @ 7%			156.09
Total Amount Payable			S\$ 2,385.93

TOTAL: SINGAPORE DOLLAR TWO THOUSAND THREE HUNDRED EIGHTY FIVE AND CENTS NINETY THREE ONLY

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

  
AUTHORISED SIGNATURE