



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15194/EISMAWATI BTE BISRI Reg No/Reg Date SMR5019R / 10/01/202 Date In/Mileage / 0 Chassis No GF7W0601665 Engine No 4J118D5519 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	11/12/2020/ 13:28	QUO	247 / DonBong	60631				
Description of Goods / Services									
E PNT88000 RENEW ACCIDENT DAMAGED ON FRONT BUMPER, REPAIR LH FRONT FENDER									450 900.00
E PNT98000 PAINT WORK SPRAY FRONT BUMPER FACE, LH FRONT FENDER AND AFFECTED PORTION									700 1050.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST									120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment									20 50.00
M SUNDRY SUNDRIES						1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,LH						1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,RH						1.00	859.00	23.00	661.43
M FACE,FR BUMPER						1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER,LH						1.00	48.00	23.00	36.96
M LH GARNISH,FR BUMPER SIDE						1.00	220.00	23.00	169.40
M LH GARNISH,FR BUMPER SIDE						1.00	112.00	23.00	86.24
M LH GARNISH,FR BUMPER SIDE						1.00	116.00	23.00	89.32
M MOULDING,FR BUMPER,LH						1.00	160.00	23.00	123.20
M MOULDING,FR WHEEL ARCH,LH						1.00	1938.00	23.00	1492.26
M HEADLAMP ASSY,LH									

Estimate

SURVEYOR NAME: Steve CLKK
SURVEYOR SIGNATURE: OD - Nkt AL 11/12/20, 2.99pm
DATE: Excels - ?
REMARKS: 4 dgs

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on **Nett 4,993.49**
Total Payable 5,343.03

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.