

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0964/2020/NS
DATE	:	8-Dec-20
WIP	:	61576

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR LUO WUQIONG
ADDRESS	:	BLK 44 MARINE CRESCENT #25-12 SINGAPORE 440044
TELEPHONE	:	HP +65 93508863
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070125657
VEHICLE NO	:	SMU 6923 H
MODEL CODE	:	AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR	:	25/8/2020
ENGINE NO	:	CHZ C33089
CHASSIS NO	:	WAUZZZGA7KA084229
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	7-Dec-20
PLACE OF ACCIDENT	:	STILL ROAD SOUTH TURNING TO MARINE PARADE ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 6923 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	X X
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00	/ photo ✓
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	/ ✓
4	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	/ ✓
5	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00	/ ✓
6	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$ 400.00	/ ✓ sale agreement?
SUB TOTAL LABOUR CHARGES		: \$ 3,720.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 6923 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT WATER SEEPAGE TEST ON FRONT WINDSCREEN.	S/N \$ 200.00	150
8	TO REMOVE AND RENEW FRONT WINDSCREEN RAIN SENSOR FOIL AND RESET SYSTEM.	S/N \$ 300.00	
9	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$ 3,600.00	
10	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS.	S/N \$ 2,800.00	? photo
11	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$ 2,400.00	? photo
12	TO PLACE VEHICLE ON CAR O-LINER.	S/N \$ 2,400.00	? photo
SUB TOTAL LABOUR CHARGES		: \$ 11,700.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 6923 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RENEW GEARBOX MECHATRONIC AND CARRY OUT ADAPTATION.	S/N \$ 980.00	? <i>pleh</i> ✓
14	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT. TO REPAIR RHS UPPER A-PILLAR. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 12,800.00	<i>3750</i> 5000
15	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, RHS UPPER A-PILLAR AND BOTH FRONT FENDER TOP SUPPORTS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	\$ 6,900.00	<i>2910</i> 3460
16	TO CARRY OUT PRE AND POST REPAIR WHEEL ALIGNMENT CHECK.	S/N \$ 480.00	? ✓
17	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 36,964.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H


S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>form</i> ✓	\$	1,854.00	1482
2 FRONT BUMPER FIXING PARTS <i>re</i> ✓	\$	343.00	154.35
3 FRONT BUMPER GRILLE - CENTRE <i>cm</i> ✓	\$	195.00	155.60
4 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>mis</i> ✓	2	\$	334.00 267.20
5 FRONT BUMPER END CAP - LH/RH <i>mis</i> ✓	2	\$	68.00 55.44
6 FRONT BUMPER SPOILER form <i>mis</i> ✓	\$	296.00	236.40
7 FRONT BUMPER CLOSING ELEMENT <i>de</i> ✓	\$	154.00	122.80
8 WHEEL SPOILER - LH/RH <i>cm</i> ✓	2	\$	68.00 53.44
9 FRONT BUMPER ADAPTER - LH <i>? bo</i> ✓	\$	35.00	28.00
10 FRONT BUMPER ADAPTER - RH <i>? mis</i> ✓	\$	42.00	33.20
11 RADIATOR GRILLE <i>cm</i> ✓	\$	1,395.00	1116.00
12 RADIATOR GRILLE STRIKER PLATE <i>cm</i> ✓	\$	123.00	98
13 FRONT BUMPER CARRIER <i>bt</i> ✓	\$	679.00	543.20
14 FRONT BUMPER FOAM FILLER PIECE <i>cm</i> ✓	\$	77.00	61.20
15 FRONT BUMPER GUIDE SECTION - LH/RH <i>cm</i> ✓	\$	70.00	56.00
16 FRONT BUMPER TOP COVER <i>de</i> ✓	\$	99.00	79.04
17 CAUTION SIGN STICKER <i>re</i> ✓	NEC	\$	14.00 10.80
18 AIRCON STICKER <i>re</i> ✓	NEC	\$	8.00 5.68
19 HORN - LH LOW TONE <i>3 set</i> <i>bo</i> ✓	\$	283.00	226
20 SIGNAL HORN - RH HIGH TONE <i>X src</i>	\$	180.00	
SUB TOTAL SPARE PARTS	:	\$	6,317.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 SPRING SHACKLE - LH/RH X LH-bt / RH-Xsu	2	\$ 62.00	24.48
22 FRONT FENDER - LH/RH bt	2	\$ 2,268.00	1814.40
23 FRONT FENDER ATTACHMENT PARTS ? Xnn		\$ 40.00	
24 FRONT FENDER BRACKET - LH/RH INNER dec	2	\$ 32.00	24.32
25 FRONT FENDER BRACKET - LH/RH OUTER dec	2	\$ 94.00	74.56
26 FRONT FENDER MIDDLE BRACKET - LH/RH dec	2	\$ 32.00	24.32
27 FRONT FENDER BRACE - LH/RH LH-bt / RH-?bt	2	\$ 74.00	57.76
28 FRONT FENDER BRACKET - LH/RH ? Xsu	2	\$ 46.00	17.92
29 WHEEL HOUSING LINER - LH/RH ? bt	2	\$ 388.00	309.60
30 WHEEL HOUSING LINER ATTACHMENT PARTS ? Xsu		\$ 57.00	
31 BONNET bt		\$ 2,757.00	2205.60
32 BONNET ATTACHMENT PARTS ? Xnn		\$ 163.00	8
33 BONNET LID HINGE - LH/RH bt	2	\$ 122.00	96.48
34 BONNET GAS FILLED STRUT X su		\$ 101.00	
35 BONNET STRIKER - LH/RH bt / RH-?bt	2	\$ 218.00	173.60
36 BONNET SOUND ABSORBER dec		\$ 217.00	173.20
37 BONNET IMPACT PROTECTION - CENTRE dec		\$ 30.00	23.76 23.36
38 BONNET IMPACT PROTECTION - LH dec		\$ 30.00	23.76
39 BONNET IMPACT PROTECTION - RH dec		\$ 30.00	23.36
40 FRONT FENDER TOP SUPPORT OUTER COVER - LH/RH LH-bt / RH-su	2	\$ 82.00	64.32
SUB TOTAL SPARE PARTS	:	\$ 6,843.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H


S/N PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
* 41 FRONT FENDER TOP SUPPORT INNER COVER - LH/RH ?	2	\$	nn 32.00	24.32 ? *
42 PLENUM CHAMBER COVER cut ✓		\$	156.00	124.40
43 BONNET LID LOCK cr ✓	2	\$	423.00	338.40
44 BONNET BOWDEN CABLE - CENTRE cut ✓		\$	57.00	45.52
45 BONNET LID LOCK CABLE cut ✓		\$	73.00	57.92
46 BONNET RELEASE ELEMENT mis ✓		\$	57.00	45.52
47 BONNET BOWDEN CABLE - LH/RH cut ✓	2	\$	114.00	91.04
48 BONNET RELEASE LEVER cut mis ✓		\$	13.00	10.08
49 HEADLIGHT MOUNTING - LH/RH cr ✓	2	\$	234.00	187.20
50 LED HEADLIGHT - LH/RH cr ✓	2	\$	9,718.00	7774.40
51 MAIN LIGHT ELECTRONICS POWER MODULE - LH/RH ? (diagnostic report) SHORT	2	\$	1,498.00	606.40
52 LIGHT CONTROL SYSTEM CONTROL UNIT ? (report) ? xmn	2	\$	1,102.00	
53 LED WITH HEAT SINK - LH/RH ? xsu LH-cut RH-x	2	\$	1,450.00	
54 HEADLIGHT HOSE - LH/RH ? (2)		\$	58.00	23.04
55 LIFT CYLINDER - LH/RH ? cr ✓	2	\$	282.00	112.40
56 LIFT CYLINDER HOSE ? cut / ton ✓		\$	175.00	140
57 HEADLIGHT WASHER PUMP ? xsu		\$	151.00	
58 WINDSCREEN WASHER SYSTEM PUMP ? xsu		\$	121.00	
59 WASH WATER RESERVOIR de ✓		\$	173.00	138.40
60 LOCK CARRIER cr ✓		\$	983.00	786.40
SUB TOTAL SPARE PARTS	:	\$	16,870.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H


S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
61 AIRCON CONDENSER <i>bt ✓</i>	\$	545.00	<i>436.00</i>
62 REFRIGERANT LINE <i>? bt ✓</i>	\$	619.00	<i>495.20</i>
63 REFRIGERANT LINE <i>? bt ✓</i>	\$	476.00	<i>380.40</i>
64 REFRIGERANT LINE <i>? bt ✓</i>	\$	476.00	<i>380.40</i>
65 AIRCON REFRIGERANT LINE BRACKET <i>brn ✓</i>	\$	26.00	<i>20.24</i>
66 AIRCON REFRIGERANT LINE CLAMP <i>?</i>	\$	29.00	
67 EXTERNAL TEMPERATURE SENSOR <i>? ms ✓</i>	\$	56.00	<i>44.32</i>
68 CHARGE AIR COOLER <i>? bt ✓</i>	\$	695.00	<i>555.60</i>
69 ACTIVATED CHARCOAL CONTAINER <i>? NN</i>	\$	305.00	
70 RADIATOR <i>bt ✓</i>	\$	941.00	<i>752.80</i>
71 ADDITIONAL RADIATOR <i>bt ✓</i>	\$	859.00	<i>687.20</i>
72 RADIATOR SEALING STRIP - LH/RH <i>cat ✓</i>	2 \$	36.00	<i>27.68</i>
73 RADIATOR BRACKET - UPPER <i>ms ✓</i>	\$	40.00	<i>32.00</i>
74 READY MIX COOLANT <i>ms ✓</i>	\$	177.00	<i>141.44</i>
75 RADIATOR FAN <i>? brn ✓</i>	\$	1,170.00	<i>936.00</i>
76 RADIATOR FAN <i>? NN</i>	\$	1,191.00	
77 RADIATOR AIR GUIDE - LH/RH <i>cm ✓</i>	2 \$	60.00	<i>47.84</i>
78 RADIATOR AIR GUIDE - UPPER CENTRE <i>cm ✓</i>	\$	22.00	<i>17.04</i>
79 RADIATOR HOSE <i>cm ✓</i>	\$	241.00	<i>192.80</i>
80 AIR INTAKE AIR GUIDE - OUTER LOWER <i>cm ✓</i>	\$	54.00	<i>43.20</i>
SUB TOTAL SPARE PARTS	:	\$	8,018.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H


S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
81	AIR INTAKE COVER <i>cm</i> ✓		40.50 TBC	32.40
82	AIR INTAKE AIR GUIDE HOSE <i>at</i> ✓	\$	64.00	50.80
83	AIR INTAKE AIR GUIDE - UPPER <i>cm</i> ✓	\$	19.00	14.96
84	AIR INTAKE WATER DRAINAGE HOSE <i>at</i> ✓	\$	32.00	25.12
85	AIR INTAKE MANIFOLD - OUTER <i>? x su</i>	\$	134.00	
86	AIR INTAKE AIR FILTER <i>x su</i>	\$	267.00	
87	AIR INTAKE MANIFOLD - INNER <i>? de</i> ✓	\$	606.00	484.80
88	THROTTLE VALVE CONTROL ELEMENT <i>x su</i>	\$	1,006.00	
89	FRONT WHEEL COVER - LH/RH <i>na</i> ✓	2	\$ 636.00	508.80
90	STEERING WHEEL AIRBAG <i>act</i> ✓	\$	3,490.00	2792
91	AIRBAG UNIT <i>act</i> ✓	\$	4,324.00	3459.20
92	HEAD AIRBAG UNIT - LH/RH <i>act</i> ✓	2	\$ 2,854.00	2283.20
93	AIRBAG CONTROL UNIT <i>act</i> ✓	\$	1,643.00	1314.40
94	STEERING WHEEL <i>de</i> ✓	\$	2,000.00	1600
95	DASHBOARD <i>Turn</i> ✓	\$	4,211.00	3368.80
96	SEAT BELT - LH/RH <i>act</i> ✓	2	\$ 2,068.00	1654.40
97	SEATBELT HEIGHT ADJUSTER <i>? x su</i>	2	\$ 322.00	
98	MOULDED HEADLINER <i>de</i> ✓	\$	1,961.00	1568.80
99	A-PILLAR TRIM - LH/RH <i>? cut</i> ✓	2	\$ 318.00	253.60
100	B-PILLAR TRIM - LH/RH UPPER <i>? x su</i>	2	\$ 370.00	
SUB TOTAL SPARE PARTS		:	\$	26,325.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
101	C-PILLAR TRIM - LH/RH ? <i>con</i> ✓	2	\$	180.00	143.52
102	FRONT GRAB HANDLE ? <i>buo</i> ✓	2	\$	279.00	223.20
103	AIRBAG CRASH SENSOR <i>ACT</i> ✓	2	\$	778.00	622.40
104	CHASSIS FRAME COVER PLATE (LH/RH) ? <i>lt</i> ✓	2	\$	182.00	75.60
105	FRONT FENDER TOP SUPPORT - LH/RH ? <i>xsu</i> ✓	2	\$	68.00	
106	ENGINE MOUNTING ? <i>dis</i> ✓		\$	246.00	196.80
107	GEARBOX MOUNTING ? <i>xsu</i> ✓		\$	249.00	
108	MECHATRONIC WITH SOFTWARE ? <i>dented</i> ✓		\$	4,008.00	3206.40
109	FRONT WINDSCREEN <i>con</i> ✓		\$	990.00	791.60
110	RAIN SENSOR GEL FOIL <i>rec</i> ✓		\$	132.00	105.20
111	RAIN SENSOR RETAINING SPRING <i>rec</i> ✓		\$	20.00	16
112	PRIMER <i>rec</i> ✓		\$	19.00	14.96
113	AIRCON COMPRESSOR ? <i>xsu</i> ✓		\$	2,136.00	
114	SOOLANT COMPRESSON OIL <i>Xnn</i> ✓		\$	310.00	
115	POLY-V-BELT ? <i>xsu</i> ✓		\$	47.00	
116	NOISE INSULATION ? <i>buo</i> ✓		\$	264.00	210.80
117	FRONT WINDSCREEN SEALANT <i>rec</i> ✓	S/N	\$	200.00	✓
118	STONE CHIP ? <i>xng</i> ✓	S/N	\$	180.00	
119	CAVITY WAX ? <i>xnn</i> ✓	S/N	\$	140.00	
120	ACRYLIC SEALANT ? <i>rec</i> ✓	S/N	\$	180.00	✓
121	FRONT NO PLATE <i>lt</i> ✓	S/N	\$	60.00	✓
122	SUNDRIES ? <i>rec</i> ✓		\$	500.00	128.29
TOTAL SPARE PARTS			:	\$	75,541.00
TOTAL LABOUR CHARGES			:	\$	36,964.00
GRAND TOTAL			:	\$	112,505.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate - 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0964/2020/NS 15-Jan-21 CHANG 1 of 1 SMU 6923 H AUDI Q2 1.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>PARTS</u>			
1	OIL SEPARATOR <i>cut ✓</i>	\$ 107.00	85.60
2	OIL FILTER <i>bf ✓</i>	\$ 25.00	19.68
GRAND TOTAL		\$ 132.00	

For Premium Automobiles Pte Ltd

Adrian Ling
15/01/2021



Authorised Signature

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Steve
8/1/21

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0964/2020/NS

8-Jan-21

GLORY

1 of 1

SMU 6923 H

AUDI Q2 1.0 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
PARTS			
1	OIL SUMP COVER <i>? cut - BR</i>	\$ 14.00	10.64
2	OIL SUMP VENT HOSE <i>? cut - BR</i>	\$ 34.00	10.64 26.88
3	COOLANT PUMP <i>? BR</i>	\$ 368.00	26.88 294.4
4	COOLANT HOSE WITH QUICK RELEASE COUPLING LOWER <i>? cut</i>	\$ 130.00	294.4 103.6
5	COOLANT HOSE WITH QUICK RELEASE COUPLING FRONT <i>? cut</i>	\$ 241.00	103.6 192.8
6	RADIATOR BRACKET UPPER <i>? nec</i>	\$ 79.00	192.8 62.88
7	RADIATOR LOWER BUSH <i>? nec</i>	\$ 19.00	62.88 14.72
8	CHARGED AIR COOLER SEALS <i>? nec</i>	\$ 26.00	14.72 20.64
9	COOLANT PIPE <i>? SC</i>	\$ 29.00	20.64 22.80
10	FLAT CONTACT HOUSING 2 PIN <i>? BR (Socket)</i>	\$ 17.00	13.28 13.28
11	VACUUM HOSE WITH NON RETURN VALVE <i>? CR</i>	\$ 368.00	294.4 294.4
	AND PRESSURE SENSOR <i>? X</i>		
12	1 SET AERODYNAMIC WIPER BLADES <i>? X</i>	\$ 87.00	69.12
13	WIRING SET FOR THREE PHASE ALTERNATOR <i>? TN</i>	\$ 215.00	172
14	FLAT CONTACT HOUSING 25 PIN <i>? nec</i>	\$ 125.00	99.6
15	TRANSMISSION FLUID 1.0 L <i>? nec</i>	\$ 120.00	96
16	WIRING SET FOR ELECTRO MECHANICAL POWER STEERING <i>? CR</i>	\$ 178.00	142.60 (Red cable)
17	HEADLIGHT COMPENSATING PIECE <i>? nec</i>	\$ 90.00	74
GRAND TOTAL		\$ 2,140.00	

For Premium Automobiles Pte Ltd

Authorised Signature

AIG-Rasul

- Resunay

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 6923 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT WATER SEEPAGE TEST ON FRONT WINDSCREEN.	S/N \$ 200.00 ✓	
8	TO REMOVE AND RENEW FRONT WINDSCREEN RAIN SENSOR FOIL AND RESET SYSTEM.	S/N \$ 300.00 ✓	
9	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS.	S/N \$ 3,600.00 ✓	
10	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS.	S/N \$ 2,800.00 ? photo	
11	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$ 2,400.00 ? photo	
12	TO PLACE VEHICLE ON CAR O-LINER.	S/N \$ 2,400.00 ? photo ✓	
SUB TOTAL LABOUR CHARGES		: \$ 11,700.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 6923 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RENEW GEARBOX MECHATRONIC AND CARRY OUT ADAPTATION.	S/N \$ 980.00	? photo ✓
14	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT. TO REPAIR RHS UPPER A-PILLAR. <u>ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN.</u> RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 12,800.00 3750	2.5 # add labour days
15	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, RHS UPPER A-PILLAR AND BOTH FRONT FENDER TOP SUPPORTS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	\$ 6,900.00 2910	
16	TO CARRY OUT PRE AND POST REPAIR WHEEL ALIGNMENT CHECK.	S/N \$ 480.00	?
17	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 36,964.00	

Car-in

wip: 61576

kiam / chai

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>tw</i> ✓	5	1,854.00	
2 FRONT BUMPER FIXING PARTS <i>re</i> ✓	5	343.00	
3 FRONT BUMPER GRILLE - CENTRE <i>on</i> ✓	5	195.00	
4 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>MIS</i> ✓ 2	5	334.00	
5 FRONT BUMPER END CAP - LH/RH <i>MIS</i> ✓ 2	5	68.00	
6 FRONT BUMPER SPOILER <i>tw</i> <i>MIS</i> ✓	5	296.00	
7 FRONT BUMPER CLOSING ELEMENT <i>de</i> ✓	5	154.00	
8 WHEEL SPOILER - LH/RH <i>on</i> ✓ 2	5	68.00	
9 FRONT BUMPER ADAPTER - LH ? ✓ <i>BR</i>	5	35.00	
10 FRONT BUMPER ADAPTER - RH ? ✓ <i>MIS</i>	5	42.00	
11 RADIATOR GRILLE <i>on</i> ✓	5	1,395.00	
12 RADIATOR GRILLE STRIKER PLATE <i>on</i> ✓	5	123.00	
13 FRONT BUMPER CARRIER <i>bt</i> ✓	5	679.00	
14 FRONT BUMPER FOAM FILLER PIECE <i>on</i> ✓	5	77.00	
15 FRONT BUMPER GUIDE SECTION - LH RH <i>LH RH</i> <i>MIS</i> ✓ 2	5	RH / MIS 70.00	
16 FRONT BUMPER TOP COVER <i>de</i> ✓	5	99.00	
17 CAUTION SIGN STICKER <i>re</i> ✓	NEC 5	14.00	
18 AIRCON STICKER <i>re</i> ✓	NEC 5	8.00	
19 HORN - LH LOW TONE X ✓ <i>BR</i>	5	283.00	
20 SIGNAL HORN - RH HIGH TONE X X	5	180.00	
SUB TOTAL SPARE PARTS	:	\$ 6,317.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : MORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	SPRING SHACKLE - LH/RH LH / BT	2	\$	62.00
22	FRONT FENDER - LH/RH LH	2	\$	2,268.00
23	FRONT FENDER ATTACHMENT PARTS ?	5	\$	40.00
24	FRONT FENDER BRACKET - LH/RH INNER dec	2	\$	32.00
25	FRONT FENDER BRACKET - LH/RH OUTER dec	2	\$	94.00
26	FRONT FENDER MIDDLE BRACKET - LH/RH dec	2	\$	32.00
27	FRONT FENDER BRACE - LH/RH LH / RH-?	2	\$ (RM) / BT	74.00
28	FRONT FENDER BRACKET - LH/RH ?	2	\$ (LH) / BT	46.00
29	WHEEL HOUSING LINER - LH/RH ? / BR	2	\$	388.00
30	WHEEL HOUSING LINER ATTACHMENT PARTS	5	\$	57.00
31	BONNET bt	5	\$	2,757.00
32	BONNET ATTACHMENT PARTS ?	5	\$	163.00
33	BONNET LID HINGE - LH/RH bt	2	\$	122.00
34	BONNET GAS FILLED STRUT X	5	\$	101.00
35	BONNET STRIKER - LH/RH bt / RH-?	2	\$ (RM) / BT	218.00
36	BONNET SOUND ABSORBER dec	5	\$	217.00
37	BONNET IMPACT PROTECTION - CENTRE dec	5	\$	30.00
38	BONNET IMPACT PROTECTION - LH dec	5	\$	30.00
39	BONNET IMPACT PROTECTION - RH dec	5	\$	30.00
40	FRONT FENDER TOP SUPPORT OUTER COVER - LH/RH LH / RH- dec	2	\$	82.00
SUB TOTAL SPARE PARTS			\$	6,843.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
41	FRONT FENDER TOP SUPPORT INNER COVER - LH/RH	2	\$ 32.00	X
42	PLENUM CHAMBER COVER	1	\$ 156.00	cut
43	BONNET LID LOCK	2	\$ 423.00	cut
44	BONNET BOWDEN CABLE - CENTRE	1	\$ 57.00	cut
45	BONNET LID LOCK CABLE	1	\$ 73.00	cut
46	BONNET RELEASE ELEMENT	1	\$ 57.00	Mis
47	BONNET BOWDEN CABLE - LH/RH	2	\$ 114.00	cut
48	BONNET RELEASE LEVER	1	\$ 13.00	cut/Mis
49	HEADLIGHT MOUNTING - LH/RH	2	\$ 234.00	cut
50	LED HEADLIGHT - LH/RH	2	\$ 9,718.00	cut
51	MAIN LIGHT ELECTRONICS POWER MODULE - LH/RH	2	\$ 1,498.00	CLH
52	LIGHT CONTROL SYSTEM CONTROL UNIT	2	\$ 1,102.00	CLH
53	LED WITH HEAT SINK - LH/RH	2	\$ 1,450.00	CLH
54	HEADLIGHT HOSE - LH/RH	2	\$ 58.00	CLH
55	LIFT CYLINDER - LH/RH	2	\$ 282.00	CLH
56	LIFT CYLINDER HOSE	1	\$ 175.00	TN
57	HEADLIGHT WASHER PUMP	1	\$ 151.00	
58	WINDSCREEN WASHER SYSTEM PUMP	1	\$ 121.00	
59	WASH WATER RESERVOIR	1	\$ 173.00	
60	LOCK CARRIER	1	\$ 983.00	
SUB TOTAL SPARE PARTS		:	\$ 16,870.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	AIRCON CONDENSER <i>bt</i> ✓		\$	545.00	
62	REFRIGERANT LINE ? <i>BT</i> ✓		\$	619.00	
63	REFRIGERANT LINE ? <i>BT</i> ✓		\$	476.00	
64	REFRIGERANT LINE ? <i>BT</i> ✓		\$	476.00	
65	AIRCON REFRIGERANT LINE BRACKET <i>BT</i> ✓		\$	26.00	
66	AIRCON REFRIGERANT LINE CLAMP ?		\$	29.00	
67	EXTERNAL TEMPERATURE SENSOR ? <i>MIS</i> ✓		\$	56.00	
68	CHARGE AIR COOLER ? <i>bt</i> ✓		\$	695.00	
69	ACTIVATED CHARCOAL CONTAINER ?		\$	305.00	
70	RADIATOR <i>bt</i> ✓		\$	941.00	
71	ADDITIONAL RADIATOR <i>bt</i> ✓		\$	859.00	
72	RADIATOR SEALING STRIP - LH/RH <i>cat</i> ✓	2	\$	36.00	
73	RADIATOR BRACKET - UPPER <i>Mps</i> ✓		\$	40.00	
74	READY MIX COOLANT <i>rm</i> ✓		\$	177.00	
75	RADIATOR FAN ? <i>BR</i> ✓		\$	1,170.00	
76	RADIATOR FAN ?		\$	1,191.00	
77	RADIATOR AIR GUIDE - LH/RH <i>cm</i> ✓	2	\$	60.00	
78	RADIATOR AIR GUIDE - UPPER CENTRE <i>cm</i> ✓		\$	22.00	
79	RADIATOR HOSE <i>cm</i> ✓		\$	241.00	
80	AIR INTAKE AIR GUIDE - OUTER LOWER <i>cm</i> ✓		\$	54.00	
SUB TOTAL SPARE PARTS			:	\$	8,018.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	AIR INTAKE COVER <i>con /</i>				TBC
82	AIR INTAKE AIR GUIDE HOSE <i>int /</i>	5		64.00	
83	AIR INTAKE AIR GUIDE - UPPER <i>con /</i>	5		19.00	
84	AIR INTAKE WATER DRAINAGE HOSE <i>int /</i>	5		32.00	
85	AIR INTAKE MANIFOLD - OUTER ?	5		134.00	
86	AIR INTAKE AIR FILTER <i>X</i>	5		267.00	
87	AIR INTAKE MANIFOLD - INNER ? <i>De /</i>	5		606.00	
88	THROTTLE VALVE CONTROL ELEMENT <i>X</i>	5		1,006.00	
89	FRONT WHEEL COVER - LH/RH <i>rec /</i>	2	5	636.00	
90	STEERING WHEEL AIRBAG <i>act /</i>	5		3,490.00	
91	AIRBAG UNIT <i>act /</i>	5		4,324.00	
92	HEAD AIRBAG UNIT - LH/RH <i>act /</i>	2	5	2,854.00	
93	AIRBAG CONTROL UNIT <i>act /</i>	5		1,643.00	
94	STEERING WHEEL <i>De /</i>	5		2,000.00	
95	DASHBOARD <i>Torn /</i>	5		4,211.00	
96	SEAT BELT - LH/RH <i>act /</i>	2	5	2,068.00	
97	SEATBELT HEIGHT ADJUSTER ?	2	5	322.00	
98	MOULDED HEADLINER <i>De /</i>	5		1,961.00	
99	A-PILLAR TRIM - LH/RH ? <i>cut</i>	2	5	318.00	
100	B-PILLAR TRIM - LH/RH UPPER ?	2	5	370.00	
SUB TOTAL SPARE PARTS		:	\$	26,325.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 6923 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
101	PILLAR TRIM LH/RH ? / CRU	2	\$	180.00	
102	FRONT GRAB HANDLE ? / BR	2	\$	279.00	
103	AIRBAG CRASH SENSOR AC	2	\$	778.00	
104	CHASSIS FRAME COVER PLATE LH/RH ? / BTx1	1	\$	182.00	
105	FRONT FENDER TOP SUPPORT - LH/RH ?	2	\$	68.00	
106	ENGINE MOUNTING ? di's		\$	246.00	
107	GEARBOX MOUNTING ?		\$	249.00	
108	MECHATRONIC WITH SOFTWARE ? / 00		\$	4,008.00	
109	FRONT WINDSCREEN CR		\$	990.00	
110	RAIN SENSOR GEL FOIL AC		\$	132.00	
111	RAIN SENSOR RETAINING SPRING		\$	20.00	
112	PRIMER		\$	19.00	
113	AIRCON COMPRESSOR ?		\$	2,136.00	
114	COOLANT COMPRESSOR OIL X		\$	310.00	
115	POLY-V-BELT ?		\$	47.00	
116	NOISE INSULATION ? / BR		\$	264.00	
117	FRONT WINDSCREEN SEALANT	S/N	\$	200.00	
118	STONE CHIP ?	S/N	\$	180.00	
119	CAVITY WAX ?	S/N	\$	140.00	
120	ACRYLIC SEALANT ?	S/N	\$	180.00	
121	FRONT NO PLATE 3f	S/N	\$	60.00	
122	SUNDRIES ?		\$	500.00	
TOTAL SPARE PARTS			:	\$	75,541.00
TOTAL LABOUR CHARGES			:	\$	36,964.00
GRAND TOTAL			:	\$	112,505.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Add
N 016 185 7 X14