

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 11 Dec 2020

Preliminary Advice

Vehicle No	: SMU6923H	Accident Date	: 07/12/2020
Make	: AUDI Q2	Policy No.	: 2070125657
Assignment Date	: 11/12/2020	Excess	: S\$0.00
Date of Inspection	: 09/12/2020	Est. Duration of Repair	: 22
Inspection At	: 24 BENOI SECTOR		
	REPAIRER : PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	112,505.00
Revised Amount	:S\$	65,744.00
Check Items (Estimated)	:S\$	30,921.00
Total	:S\$	96,665.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	140,776.00
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	53,515.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	87,261.00
Margin for Repair (Pre-Accident Value)	:S\$	56,485.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.