



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200650

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 07/02/2022
Reference CC4/FCI20013725/Kes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 7224E
Insured Veh. SHC 8939D
Claim No. D20005032MFSH
Policy No. D-20094922MFSH
Accident Date 28/11/2020
Inspection Date 13/04/2021

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI20013725/Kes3q2

Date: 07/02/2022

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8939D	Veh. Inspected	SMC 7224E
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20005032MFSH	Excess (\$)	0.00
Assign From	CHRIS	Assign Date	11/12/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP53415190	Colour	METALLIC BLUE
Odometer	58642 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	TOYO	7 mm
L/H Front Tyre	185/60 R15	TOYO	7 mm
R/H Rear Tyre	185/60 R15	TOYO	7 mm
L/H Rear Tyre	185/60 R15	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/11/2020	Inspection Date	13/04/2021
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 7224E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT LH FENDER EMBLEM 'HYBRID'	NECESSARY	58.90	58.90
	LESS 20% DISCOUNT		-11.78	-11.78
			47.12	47.12
	LABOUR			
	REMOVE AND REFIT FRT BUMPER ,FRT LH SIDE MIRROR .KNOCK AND REPAIR FRT LH FENDER ,FRT LH DOOR AND REALIGN THE SAME .		380.00	300.00
	PUTTY AND RESPRAY FRT BUMPER ,FRT LH SIDE ,MIRROR ,FRT LH FENDER & FRT LH DOOR .		700.00	500.00
			1,080.00	800.00
	GRAND TOTAL		1,127.12	847.12
	RECOMMENDED COST OF REPAIRS			847.12

Report Ref No. CC4/FCI20013725/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 7224E

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 7224E

RE-INSPECTION

