

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SMC 7224E  
 TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877

TEL: 65073848 FAX: 65073849  
 ATTN: Motor Claim Department

WS Ref: TP/FC  
 Claim Type: Third Party  
 Accident Date: 28/11/2020  
 TP Veh Reg No: SHC8939D

*Not Withheld*  
*Running After Paint*  
*4 days*

Estimate No: ES2190341/WS  
 Date: 12 Apr 2021  
 Policy No: 5110893327-01  
 Veh Reg No: SMC7224E  
 Make/Model: HONDA HONDA FIT HYBRID 1.5 AUTO  
 Chassis No: GP53415190  
 Engine No: LEB6069782  
 Reg. Date: 18/07/2018

### Estimate Repair Cost to Vehicle No :SMC7224E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
<b>List Price</b>				
1 FRONT LH FENDER EMBLEM "HYBRID"	58.90	1 PC	<i>22</i> 58.90	—
		Less 20%	11.78	47.12
<b>Labour</b>				
2 REMOVE AND REFIT FRT BUMPER, FRT LH SIDE MIRROR. KNOCK AND REPAIR FRT LH FENDER, FRT LH DOOR AND REALIGN THE SAME.	380	1 LA	380.00	<i>300</i>
3 PUTTY AND RESPRAY FRT BUMPER, FRT LH SIDE MIRROR, FRT LH FENDER & FRT LH DOOR.	700	1 LA	700.00	<i>500</i>
			<u>1,080.00</u>	<u>1,080.00</u>

Total S\$ 1,127.12  
 Add GST @ 7% 78.90  
**Total Amount Payable S\$ 1,206.02**

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

*32*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: