

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305438278

Date : 14/12/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHD3380S

Date of Accident : 09-Dec-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC — GBH7095P
- The finalized amount shall be:
 - Spare Parts after List discount
 - Labour Charges
 - Total for Part-By-Part Repair Cost
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$2,700.00
Final Lumpsum Repair cost \$2,700.00
- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : NAZ
Date : 28/12/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.12.2020

Time: 08:31:59

Page: 1/3

TS

NFOUC-4S
LKR-Taufik

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305438278
 REGN NO : SHD3380S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 18.08.2016
 DATE/TIME IN : 10.12.2020 13:15
 ACCIDENT DATE : 09.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	/CRK
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	/CRK
0003	04-01-0103-0739-G	REAR BUMPER SPONGE	1	119.50	20.00	95.60	? XSVL
0004	04-01-0103-0740-G	REAR BUMPER BEAM	1	428.40	20.00	342.72	? XSVL
0005	04-01-0103-0742-G	REAR BUMPER STAY LH	1	160.60	20.00	128.48	? / BT
0006	04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	35.60	20.00	28.48	? / CRK
0007	04-01-0103-0851-G	REAR BUMPER REFLECTOR LH	1	32.00	20.00	25.60	? XSVL
0008	04-01-0103-0581-A	TAILLAMP LH	1	697.80	20.00	558.24	/SCR
0009	04-01-0103-0584-G	BOOTLID LAMP LH	1	1,131.20	20.00	904.96	XSVL
0010	04-01-0103-0785-G	BOOTLID MOULDING	1	85.00	20.00	68.00	/SCR
0011	04-01-0103-0784-G	BOOTLID GARNISH	1	227.90	20.00	182.32	? XSVL
0012	04-01-0103-0786-G	BOOTLID EMBLEM-CRDI	1	52.40	20.00	41.92	/NEC
0013	04-01-0103-0787-G	BOOTLID EMBLEM-I40	1	67.90	20.00	54.32	/NEC

Bumper clips (10) 22.00/20.00/ \$ 17.60 / NEC

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438278
REGN NO : SHD3380S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 18.08.2016
DATE/TIME IN : 10.12.2020 13:15
ACCIDENT DATE : 09.12.2020

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT			
0014 04-01-0103-0800-G	BOOTLID EMBLEM-H	1	63.10	20.00	50.48
0015 28-01-0103-0005-A	BOOTLID COMFORDELGRO	1	30.00	10.00	27.00
0016 28-01-0103-0006-A	BOOTLID 65521111	1	30.00	10.00	27.00
0017 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00	100	50.00
0018 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	10.00	122.13

SUB-TOTAL : 3,774.45

JOB NATURE

0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00
0001 20-05	Rear Bumper Adv.Sticker	20.00
0002 PB	PANEL BEATING	600.00 560
0003 SP	SPRAYPAINT CHARGE	500.00 400

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

NTUC - LJS
 LKK-Taufik

JOB NO : 305438278
 REGN NO : SHD3380S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 18.08.2016
 DATE/TIME IN : 10.12.2020 13:15
 ACCIDENT DATE : 09.12.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0004 17-01 CHECK ALL LIGHTING	40.00		20		
0005 20-00 TUFF COAT ON AFFECTED PARTS.	40.00		30		
0006 L R/I REVERSE SENSOR	120.00		30		

SUB-TOTAL : 1,520.00

TOTAL : 5,294.45

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

NAZ LKK
 11/12/2020 1215
 LIS
 3 DAYS
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS

PARTS \$2,518.40
 LESS 20% \$2,014.72
 SINERT 226.13
 LABOUR \$1,180.00
 TOTAL \$3,420.85
 LESS LIS 20% \$2,736.68
 LIS TOTAL \$2,700.00

FINALIZED LUMP SUM TOTAL \$2,700.00 13 REPAIR DAYS.