

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

*Wash
clean
Asher.*

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000274
Date: 30 Nov 2020
Veh Reg No: SMP3467D
Make/Model: TOYOTA ESTIMA
AERAS 2.4 CVT
Chasis No: ACR507166068
Reg. Date: 23/09/2019
Your Ref No: SKZ7662B

Claim Type: Third Party
Accident Date: 27/11/2020
TP Veh Reg No: SKZ7662B

*Andrian
Sunny
10/12/20
2.20pm.*

Estimate Repair Cost to Vehicle No :SMP3467D

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC BOOT LID <i>Dented</i>	1,490.10 ✓	
2	1 PC BOOT LID LOGO <i>New</i>	66.80 ✓	
3	1 PC BOOT LID ESTIMA EMBLEM <i>New</i>	44.20 ✓	
4	1 PC REAR WINDSCREEN RUBBER <i>New</i>	91.20 ✓	
5	1 PC BOOT LID LOCK <i>New</i>	389.80 x	
6	1 PC BOOT LID RUBBER <i>New</i>	325.70 x	
7	1 PC BOOT LID TRIM <i>New</i>	476.10 x	
8	1 PC REAR BUMPER <i>Del-d</i>	765. ✓	
9	2 PCS REAR BUMPER SIDE RETAINERS <i>New</i>	104.20 ✓	
10	1 PC REAR PANEL <i>Dented.</i>	625.50 ✓	
11	1 PC REAR PANEL TRIM <i>Del-d</i>	253.10 ✓	
	<i>1pc u bumper sponge 126.70</i>	4,508.40	
	<i>1pc u antenna sensor 187.50</i>	Less 25%	
		1,127.10	3,381.33
Special Net			
12	1 PC BOOT LID RUBBER LINING <i>New</i>	150.00 100.	
13	1 TUBE REAR WINDSCREEN SEALANT <i>New</i>	60.00 40	
14	1 PC REAR WINDSCREEN SEAL <i>New</i>	60.00 40	
15	1 SET BOOT LID TRIM CLIPS <i>New</i>	50.00 x	
16	1 SET REAR BUMPER CLIPS <i>New</i>	40.00 30	
17	1 SET REAR PANEL TRIM CLIPS <i>New</i>	40.00 20	
18	1 SET REVERSE SENSORS <i>Dented</i>	350.00 300	
		750.00	750.00
Labour			
19	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 800	
20	1 TO SPRAY PAINTING	1,000.00 800	
21	1 TO SPRAY UNDERSEAL	80.00 40	
22	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2000274
Date: 30 Nov 2020
Veh Reg No: SMP3467D
Make/Model: TOYOTA ESTIMA
AERAS 2.4 CVT
Chasis No: ACR507166068
Reg. Date: 23/09/2019
Your Ref No: SKZ7662B

Claim Type: Third Party
Accident Date: 27/11/2020
TP Veh Reg No: SKZ7662B

Estimate Repair Cost to Vehicle No :SMP3467D

Quantity	Description	List Price S\$	Amount S\$
23	1 TO CHECK WIRING	50.00	30
24	1 TO REPLACE REAR INNER TRIM	100.00	60
25	1 TO REFIT THIRD BRAKE LIGHT	80.00	x
26	1 TO REMOVE AND REPLACE REVERSE SENSOR	80.00	50
27	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	50
		2,590.00	2,590.00
Total			S\$ 6,721.33
Add GST @ 7%			470.49
Total Amount Payable			S\$ 7,191.82

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND ONE HUNDRED NINETY ONE AND CENTS EIGHTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian Lj
L/S 12/06/21
08 Days.
total \$255.72
L/S A.2K