



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO20013740/Kvd3q2 Date: 10/02/2021 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	YN 9526X	<b>Veh. Inspected</b>	GBK 4240R
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2003633/AGC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	11/12/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	TOYOTA DYNA (M)	<b>c.c</b>	2982
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	JTFAT35Y40K215078	<b>Colour</b>	ORANGE
<b>Odometer</b>	13744 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/75 R15	BRIDGESTONE	8 mm
<b>L/H Front Tyre</b>	195/75 R15	BRIDGESTONE	8 mm
<b>R/H Rear Tyre</b>	155 R12X8 (D)	BRIDGESTONE	8/8 mm
<b>L/H Rear Tyre</b>	155 R12X8 (D)	BRIDGESTONE	8/8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	09/12/2020	<b>Inspection Date</b>	14/12/2020
<b>Survey held at</b>	AH CHANG MOTOR SERVICE CENTRE BLK 10 ANG MO KIO IND PARK 2A AMK AUTOPOINT #03-16 SINGAPORE 568047		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	