

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20013748/APS3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	SBR6836Y	Insured Vehicle No :	SHD2356U
Date of Loss:	06/12/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002676

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBR6836Y	Engine No:	F1527691
Make & Model:	VOLKSWAGEN BEETLE 1300, 1.3 (M)	Chassis No:	119251769
Reg. Date:	27/03/1969 (Man. Year: 1969)	Odometer:	70801 km
Colour:	Black		
Engine Capacity:	1285 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,550.00	1,395.00	155.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	860.00	350.00	28.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,760.00	2,255.00	505.00	18.30
+ GST 7.00/7.00% (S\$)	193.20	157.85	35.35	18.30
Nett Amount (S\$)	2,953.20	2,412.85	540.35	18.30
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,600.30		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment: 08/12/2020

Date Inspected: 08/12/2020 Inspected At:

People's Vehicle Recovery Service
(HQ)

Blk 3023A Ubi Rd 1, #01-60

Singapore 408717

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	144	VOLKSWAGEN BEETLE 1300 1.3 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBR6836Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT	Bent	950.00 F	*950.00 FN
2	2		*BUMPER BRACKET FRT	Bent	570.00 F	*570.00 FN
3	1		*NUMBER PLATE FRT	Necessary	30.00 F	*30.00 FN
					Sub Total (\$\$)	1,550.00
					- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	1,550.00
						1,395.00

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	350.00	200.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS	New	500.00	400.00
3	TOWING CHARGES	New	240.00	180.00
4	LTA DOCUMENTS NUMBER PLATE PIN	New	120.00	80.00
Gross Labour Cost (\$\$)			1,210.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >