

ASS.

LKe

AIG

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 11.12.2020
Time: 17:24:28
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438407
REGN NO : SH 7163A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 10.12.2020 21:00
ACCIDENT DATE : 10.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	cut	—
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	na	—
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1 L	451.25	20.00	361.00	cut	—
0004 04-01-0104-2532-G	IONIQVC BRACKET ASSY-RR B	1 L	55.80	20.00	44.64	Xun	
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	2.00-	180.00	Xun	
0006 04-01-0104-0852-G	IONIQVC REFLECTOR/REFLEX	1 L	41.45	20.00	33.16	cut	—
						20% - 974.10	779.28
SUB-TOTAL						: 1,003.92	

JOB NATURE

0000 23-01	TOWING FEE	60.00	—
0001 L	PANEL BEATING (repair RR fender Rh)	500.00	480
0002 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	200
0003 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30
SUB-TOTAL		: 1,130.00	

\$1749.28
3 days

w/strake.
Tampin 17495749
-UP 14/12/20 @ 12pm
p/p resurvey before paint
3 days
Tampin @ Pulautau.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: