

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CS/AG/20013754/49d3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / *CP* / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMQ 3035L

at Workshop m/s

ZENO grocery

of

Insured:

SJB 870B

Policy No.

Claims No.

C10008316/LH

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

#4/K.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 31745

Vehicle: IN / OUT

Date:

Person Contacted:

Rep 8800

Veh No:

SMQ 3035L

Yr Regn:

16/4/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

*Honda**Jazz*

c.c

1498

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

86929

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHM6K5850FX 202571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55-R15

R:

BS / *DUN* / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/12/20

D.O.I.

14/12/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/12/20 2/5 #2700 Confirmed with survey (Red #3675.16, 571.7)

Date/Time, File Pass to?

☐

Preli. Report

1) *24/12/20*☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

2700



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

Not Authored
 Alan
 1/5 \$2700
 4 days
 when Mr. Apple up.

QUOTATION

No : QT-000231

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

BLK 190 CLEMENCEAU AVENUE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

ATTN: MOTOR CLAIM DEPARTMENT

TEL : 62212199/65402199 FAX : 67250853

Your Ref. : SJB870B
 Vehicle No. : SMQ3035L
 Make & Model : HONDA JAZZ
 Chasis No. : JHMGK5850FX202571
 Engine No. : L15B31000365
 Accident Date : 10/12/2020
 Policy No. : 5114268197-01
 Date : 14/12/2020
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	REAR BUMPER <i>20/102 492.70</i>	1.0	PCS 541.70	541.70
2	BUMPER GRILLE	2.0	PCS 66.00	132.00 X
3	BUMPER SIDE RETAINER (L/H/R) <i>11 Absent</i>	1.0	PCS 18.90	18.90
4	BUMPER SIDE RETAINER (R/H/R) <i>11</i>	1.0	PCS 18.90	18.90 X
5	BUMPER CLIP <i>nee</i>	8.0	PCS 3.80	30.40
6	REAR BOOT <i>Body 20 749.60</i>	1.0	PCS 913.30	913.30
7	REAR BOOT GARNISH <i>11</i>	1.0	PCS 192.90	192.90 X
8	REAR BOOT INNER TRIM BOARD <i>20</i>	1.0	PCS 106.20	106.20
9	REAR BOOT INNER TRIM BOARD CLIPS <i>nee</i>	10.0	PCS 3.50	35.00
10	REAR BOOT INNER LOCK <i>1w1 86.20</i>	1.0	PCS 86.90	86.90
11	REAR BOOT LOCK STRIKER <i>11</i>	1.0	PCS 27.70	27.70 X
12	REAR BOOT WEATHERSTRIP <i>1w1</i>	1.0	PCS 101.30	101.30
13	WINDSCREEN INNER SEAL (REAR) <i>nee</i>	1.0	PCS 29.10	29.10
14	WINDSCREEN MOULDING (REAR) <i>nee</i>	1.0	PCS 105.60	105.60
15	EMBLEM "JAZZ" <i>nee</i>	1.0	PCS 26.20	26.20
16	WIPER MOTOR <i>11</i>	1.0	PCS 199.00	199.00 X
17	LAMP (R/H/R) <i>11</i>	1.0	PCS 246.90	246.90 X
18	LAMP (L/H/R) <i>one 244.60</i>	1.0	PCS 246.90	246.90
19	REAR END PANEL <i>11</i>	1.0	PCS 418.00	418.00 X
20	SENSOR (KEY) <i>11</i>	1.0	PCS 65.30	65.30 X
21	BUZZER (REVERSE) <i>11</i>	1.0	PCS 95.50	95.50 X
22	Discount 20 %			-727.54
23	SubTotal (L)			2,910.16
24	REAR NUMBER PLATE <i>11</i>	1.0	PCS 35.00	35.00 X
25	SEALANT (WINDSCREEN) <i>nee</i>	2.0	PCS 35.00	70.00 40
26	REVERSE SENSOR <i>short</i>	1.0	SET 280.00	280.00 200



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000231

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

BLK 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924
 ATTN: MOTOR CLAIM DEPARTMENT

TEL : 62212199/65402199 FAX : 67250853

Your Ref. : SJB870B
 Vehicle No. : SMQ3035L
 Make & Model : HONDA JAZZ
 Chasis No. : JHMGK5850FX202571
 Engine No. : L15B31000365
 Accident Date : 10/12/2020
 Policy No. : 5114268197-01
 Date : 14/12/2020
 Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
27	REVERSE CAMERA 11	1.0 PCS	450.00	450.00 X
28	REAR END PANEL SEALANT 11	1.0 BTL	50.00	50.00 X
29	SubTotal (S)			885.00
30	PANEL BEAT & REPAIR FRONT DAMAGE	1.0 X	550	900.00
31	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	600	750.00
32	TO PROVIDE UNDER TURFCODE	1.0 X	30	180.00
33	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0 X	30	50.00
34	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0 X	120	150.00
35	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X	80	150.00
36	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X	Repels X	80.00
37	TO REMOVE REVERSE SENSOR/CAMERA	1.0 X	520	150.00
38	TO TRANSFER REAR BOOT FITTING	1.0 X	60	120.00
39	SubTotal (LABOUR)			2,530.00

SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED TWENTY FIVE AND CENTS SIXTEEN ONLY

E. & O.E

Total S\$ 6,325.16

Discount S\$ 0.00

Net Total S\$ 6,325.16

Customer's Signature/Co. Stamp

ZERO GRAVITY

LKK Auto Consultants

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- charges must be made seven (7) days from the date of this invoice otherwise if is assumed that this bill is accepted as correct.

Terms: C.O.D.

Acknowledged by Repairer

Signature:

Date:

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise if is assumed that this bill is accepted as correct.

P-2025-80
 201
 P-1620-64
 S.N.-240
 L-1520
 3380-64
 2704