

ASS. REC. BY:

REF:

CE31AIG 2001 3766/A+L3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: _____

Policy No. 2070026602Claims No. 401057142356Sum Insured: _____ Excess: \$0-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 880 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMS2762S Yr Regn: 2020 Feb.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 C.C. 1395Colour: Black A/C: Insured / Std / NI / NASp. Reading: 11541 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222F38L1048800Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 235/50R19R: 235/50R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/12/20Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

07 AIG.Confirm final figure @ \$15964.80, 3 days
(Recd. 20.15.20: 77%)MV: 135KPV: 54.1KNett: 80.9K

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format:

Lump Sum / L.B.T. \$15964.80

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2020 15:27
Date Of Accident	04/11/2020 21:10
Exact Location Of Accident	2 GEYLANG LORONG 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMS2762S
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	PHUA CHENG MIEN(PAN ZHENGMIAN)
NRIC No	SXXXX440J
Email Address	DCMPHUA@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-81388397
Alternative Phone No	OFFICE-81388397

Vehicle Particulars

Manufacturer	AUDI
Model	Q3 SPORTSBACK 1.4 TFS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO Yes.
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2070026602
Cover Note Number	


Driver

Name of Driver	PHUA CHENG MIEN(PAN ZHENGMIAN)
NRIC No	SXXXX440J
Date Of Birth	18/08/1976
Occupation	INDOOR
Date Of Driving Pass	16/09/1997
Driving Experience	23 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81388397
Fax Number	
Contact Number	OFFICE-81388397
EMail Address	DCMPHUA@YAHOO.COM.SG

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

5 May 20 / 1240 pm

GARNC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature
Name: Wong Kuei Shuen
NRIC/FIN No.: GXXXX569M

Police Report



**SINGAPORE
POLICE FORCE**



T/20201104/2144

Police Station Of Origin:
Geylang N.P.C
1 Cassia Link SINGAPORE 397618
Tel No. 1800-8485999

2 of 3

Report No. T/20201104/2144

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMS2762S	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2070026602	18/02/2020	18/02/2022

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	PHUA CHENG MIEN		ID No. S7625440J
Related Vehicle	SMS2762S (Car)		Contact No. 81388397
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 04/11/2020 at about 2110hrs, I was driving along Lor 10 Geylang towards Talma Rd when suddenly one motorcycle bearing a local registration number came out from a backlane. I applied my brakes however the said motorcycle did not brake in time and the front part of the motorcycle hit the front right of my car.

I then went out from my car and asked the rider for his driving license however he told me that his license was with Traffic Police. As I turned away, the rider suddenly rode off and I lost sight of him. I then called police for assistance and shortly after, one traffic police officer came to scene and advised me to lodge a traffic accident report.

I wished to state that I did not sustain any injuries and there were damages on the front right bumper as well as the right side of my car. I also wished to state that there is an in-car camera in my car.

GUARANTEED DISCOUNT OF
UP TO \$43,000

SALE



OPEL

Audi Q3 Min Price to No Max Depreciation Vehicle Type Category

Advanced Search

New Audi Q3 Cars for Sale (5 vehicles)

Sort by Most Popular

15 results/page

Car Model	Price	Dealer	Built in	User Rating
Audi Q3 SPOTLIGHT 	\$158,800 \$14,300 /yr ?	Premium Automobiles	Hungary	2 User Reviews
1.4 TFSI S tronic [17\" Rim] (A)		* 14.3km/l 148bhp 6-speed (A) S tronic		
1.4 TFSI S tronic S line (A)	\$182,800 \$16,500 /yr ?	* 13.9km/l 148bhp 6-speed (A) S tronic		
	Promotion available			
Audi Q3 Sportback 	\$168,711 \$15,100 /yr ?	Premium Automobiles	Hungary	2 User Reviews
1.4 TFSI S tronic [17\" Rim] (A)		* 14.2km/l 148bhp 6-speed (A) S tronic		
2.0 TFSI qu S tronic (A)	\$200,161	* 12.7km/l 177bhp 7-speed (A) S tronic		
	Promotion available			
Audi Q3 - Audi festive deals, effective price from \$139,999.		Audi - It's a time of giving & sharing at Audi. Purchase an Audi now & we will donate \$200 in your name to a charity this festive season.		PROMOTION View All
Audi RS Q3 Sportback NEW MODEL 	POA	Premium Automobiles	Germany	Rate it!
2.5 TFSI qu S tronic (A)		* 11.1km/l 394bhp 7-speed (A) S tronic		
Audi Q3 Sportback Mild Hybrid 	\$162,000	Parallel Importers	Hungary	2 User Reviews
1.4 35 TFSI S tronic (A)		* 14.2km/l 148bhp 7-speed (A) S tronic		
Audi RS Q3 NEW MODEL 	POA	Premium Automobiles	Germany	Rate it!
2.5 TFSI qu S tronic (A)		* 11.1km/l 394bhp 7-speed (A) S tronic		

Car Model Price Dealer Built in User Rating

15 results/page

There are 2 **Past New Audi Q3 Cars for Sale** no longer being sold by local distributors
View all [past Audi cars](#)



Audi Q3 2016
(2011-2019)



Audi Q3
(2012-2018)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0847/2020/NS
DATE	:	4-Nov-20
WIP	:	56644

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : FBA 7945 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

OWNER'S NAME	:	MR PHUA CHENG MIEN(PAN ZHENGMIAN)
ADDRESS	:	BLK 31 JALAN RAMA RAMA #12-03 SINGAPORE 32911
TELEPHONE	:	HP +65 81388397
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	2070026602
VEHICLE NO	:	SMS 2762 S
MODEL CODE	:	AUDI Q3 SPORTSBACK 1.4 TFS
MODEL YEAR	:	19/2/2020
ENGINE NO	:	CZD 888513
CHASSIS NO	:	WAUZZZF38L1048800
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	4-Nov-20
PLACE OF ACCIDENT	:	2 GEYLANG LORONG 10



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 2762 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	X
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$	400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	500 ✓
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,700.00	1250 ✓ Bumper 550 Spoiler 300 Wheel Arch x2 = 200 x 2 2400 1250
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 8,572.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Del'd</i>		\$ 2,615.00	✓ 2091-60
2	FRONT BUMPER FIXING PARTS		\$ 410.00	✓
3	FRONT BUMPER CLOSING ELEMENT - RH		\$ 58.00	✓
4	FRONT BUMPER TRIM		\$ 352.00	✓
5	FRONT BUMPER GRILLE - CENTRE		\$ 215.00	✓
6	ULTRASOUND SENSOR SUPPORT - LH/RH	2	\$ 50.00	✓
7	FRONT BUMPER CLOSING ELEMENT		\$ 188.00	✓
8	FRONT SPOILER <i>Del'd</i>		\$ 754.00	✓ 603-20
9	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 151.00	✓
10	AIR GUIDE GRILLE TRIM - RH		\$ 162.00	✓
11	AIR GUIDE GRILLE ULTRASOUND SENSOR SUPPORT - RH		\$ 25.00	✓
12	RADIATOR GRILLE		\$ 1,907.00	✓
13	RADIATOR GRILLE STRIKER PLATE		\$ 241.00	✓
14	RADIATOR GRILLE INNER COVER		\$ 241.00	✓
15	FRONT PARKING AID SENSOR		\$ 242.00	✓
16	FRONT PARKING AID SEAL RING	4	\$ 14.00	✓
17	FRONT BUMPER FOAM FILLER PIECE		\$ 101.00	✓
18	FRONT BUMPER CARRIER		\$ 834.00	✓
19	FRONT BUMPER GUIDE SECTION - RH		\$ 38.00	✓
20	FRONT FENDER - RH		\$ 1,271.00	✓
SUB TOTAL SPARE PARTS		:	\$ 9,869.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS		\$ 62.00	X
22	FRONT FENDER BRACKET - RH		\$ 31.00	X
23	FRONT FENDER BRACE - RH		\$ 87.00	X
24	FRONT WHEEL HOUSING LINER - RH		\$ 237.00	X
25	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 100.00	X
26	LED HEADLIGHT - RH		\$ 5,526.00	X
27	LIFT CYLINDER - RH		\$ 208.00	X
28	FRONT WHEEL COVER - LH/RH	2	\$ 1,060.00	✓ 248.00
29	FRONT NO PLATE	S/N	\$ 60.00	X
30	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 17,540.00	
TOTAL LABOUR CHARGES		:	\$ 8,572.00	
GRAND TOTAL		:	\$ 26,112.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian
11/12/20

At Antlense, 03 Days ✓

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 440J

Vehicle Details

Vehicle No.: SMS2762S
Vehicle to be Exported: No
Intended Deregistration Date: 12 Dec 2020
Vehicle Make: AUDI
Vehicle Model: Q3 SPORTBACK 1.4 TFSI S TRONIC (17")
Primary Colour: Black
Manufacturing Year: 2019
Engine No.: CZD888513
Chassis No.: WAUZZZF38L1048800
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$30,143.00
Original Registration Date: 19 Feb 2020
First Registration Date: 19 Feb 2020
Transfer Count: 0
Actual ARF Paid: \$34,201.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Feb 2030
PARF Rebate Amount: \$25,650.00

Intended COE Rebate Details

COE Expiry Date: 18 Feb 2030
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$30,890.00
COE Rebate Amount: \$28,370.00
Total Rebate Amount: \$54,020.00

The information contained herein is correct as at 12 Dec 2020

OK



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0847/2020/NS
DATE : 4-Nov-20
WIP : 56644

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : FBA 7945 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb - 22 Mar 21

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

OWNER'S NAME : MR PHUA CHENG MIEN(PAN ZHENGMIAN)
ADDRESS : BLK 31 JALAN RAMA RAMA
#12-03
SINGAPORE 32911
TELEPHONE : HP +65 81388397
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070026602
VEHICLE NO : **SMS 2762 S**
MODEL CODE : AUDI Q3 SPORTSBACK 1.4 TFS
MODEL YEAR : 19/2/2020
ENGINE NO : CZD 888513
CHASSIS NO : WAUZZZF38L1048800
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Nov-20
PLACE OF ACCIDENT : 2 GEYLANG LORONG 10

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 2762 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES			
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$	400.00	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N	\$	400.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	2,400.00	\$ 500.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.		\$	4,700.00	\$ 1,250.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$	8,572.00	\$ 2,422.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,615.00	\$ 2,091.60
2	FRONT BUMPER FIXING PARTS		\$ 410.00	
3	FRONT BUMPER CLOSING ELEMENT - RH		\$ 58.00	
4	FRONT BUMPER TRIM		\$ 352.00	
5	FRONT BUMPER GRILLE - CENTRE		\$ 215.00	
6	ULTRASOUND SENSOR SUPPORT - LH/RH	2	\$ 50.00	
7	FRONT BUMPER CLOSING ELEMENT		\$ 188.00	
8	FRONT SPOILER		\$ 754.00	\$ 603.20
9	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 151.00	
10	AIR GUIDE GRILLE TRIM - RH		\$ 162.00	
11	AIR GUIDE GRILLE ULTRASOUND SENSOR SUPPORT - RH		\$ 25.00	
12	RADIATOR GRILLE		\$ 1,907.00	
13	RADIATOR GRILLE STRIKER PLATE		\$ 241.00	
14	RADIATOR GRILLE INNER COVER		\$ 241.00	
15	FRONT PARKING AID SENSOR		\$ 242.00	
16	FRONT PARKING AID SEAL RING	4	\$ 14.00	
17	FRONT BUMPER FOAM FILLER PIECE		\$ 101.00	
18	FRONT BUMPER CARRIER		\$ 834.00	
19	FRONT BUMPER GUIDE SECTION - RH		\$ 38.00	
20	FRONT FENDER - RH		\$ 1,271.00	
SUB TOTAL SPARE PARTS		:	\$ 9,869.00	\$ 2,694.80

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 2,694.80
21	FRONT FENDER ATTACHMENT PARTS		\$ 62.00	
22	FRONT FENDER BRACKET - RH		\$ 31.00	
23	FRONT FENDER BRACE - RH		\$ 87.00	
24	FRONT WHEEL HOUSING LINER - RH		\$ 237.00	
25	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 100.00	
26	LED HEADLIGHT - RH		\$ 5,526.00	
27	LIFT CYLINDER - RH		\$ 208.00	
28	FRONT WHEEL COVER - LH/RH	2	\$ 1,060.00	\$ 848.00
29	FRONT NO PLATE	S/N	\$ 60.00	
30	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 17,540.00	\$ 3,542.80
TOTAL LABOUR CHARGES		:	\$ 8,572.00	\$ 2,422.00
GRAND TOTAL		:	\$ 26,112.00	\$ 5,964.80

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

bl-03/03/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 6864 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REFRIGERANT LINER (A/C CONDENSER >CUT OFF POINT) <i>Neu</i>		\$	619.00	+
42	A/C SEAL RING <i>Neu</i>	2	\$	14.00	+
43	FRONT WHEEL COVER-LH/RH <i>LH cut, RH Neu</i>	2	\$	644.00	✓ 514.40
44	FRONT ALUMINIUM RIM-LH <i>Neu</i>		\$	949.00	+
45	FRONT NO. PLATE <i>Neu</i>	S/N	\$	60.00	+
46	SUNDRIES <i>Nec.</i>		\$	300.00	✓ 36.40
TOTAL SPARE PARTS		:	\$	18,276.00	
TOTAL LABOUR CHARGES		:	\$	11,484.00	
GRAND TOTAL		:	\$	29,760.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 6864 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X ✓
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X X
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNI AND POWER MODULE.	S/N \$ 400.00	250 ✓
4	TO RENEW AIRCON CONDENSER REFRIGERANT PIPE.	S/N \$ 280.00	X
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR COVER.	S/N \$ 280.00	✓ ✓
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000 ✓
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 3,300.00	1650 ✓
8	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓ ✓
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓ ✓
SUB TOTAL LABOUR CHARGES		: \$ 11,484.00	