

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 2762 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,700.00	1250 Bumper 550 Spoiler 300 Wheel Arch x2 = 200 x 2 = 400
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,572.00	1250

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>del d</i>		\$	2,615.00	✓
2	FRONT BUMPER FIXING PARTS		\$	410.00	+
3	FRONT BUMPER CLOSING ELEMENT - RH		\$	58.00	+
4	FRONT BUMPER TRIM		\$	352.00	+
5	FRONT BUMPER GRILLE - CENTRE		\$	215.00	+
6	ULTRASOUND SENSOR SUPPORT - LH/RH	2	\$	50.00	+
7	FRONT BUMPER CLOSING ELEMENT		\$	188.00	+
8	FRONT SPOILER <i>del d</i>		\$	754.00	✓
9	FRONT BUMPER AIR GUIDE GRILLE - RH		\$	151.00	+
10	AIR GUIDE GRILLE TRIM - RH		\$	162.00	+
11	AIR GUIDE GRILLE ULTRASOUND SENSOR SUPPORT - RH		\$	25.00	+
12	RADIATOR GRILLE		\$	1,907.00	+
13	RADIATOR GRILLE STRIKER PLATE		\$	241.00	+
14	RADIATOR GRILLE INNER COVER		\$	241.00	+
15	FRONT PARKING AID SENSOR		\$	242.00	+
16	FRONT PARKING AID SEAL RING	4	\$	14.00	+
17	FRONT BUMPER FOAM FILLER PIECE		\$	101.00	+
18	FRONT BUMPER CARRIER		\$	834.00	+
19	FRONT BUMPER GUIDE SECTION - RH		\$	38.00	+
20	FRONT FENDER - RH		\$	1,271.00	+
SUB TOTAL SPARE PARTS		:	\$	9,869.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 2762 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS		\$ 62.00	X
22	FRONT FENDER BRACKET - RH		\$ 31.00	X
23	FRONT FENDER BRACE - RH		\$ 87.00	X
24	FRONT WHEEL HOUSING LINER - RH		\$ 237.00	X
25	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 100.00	X
26	LED HEADLIGHT - RH		\$ 5,526.00	X
27	LIFT CYLINDER - RH		\$ 208.00	X
28	FRONT WHEEL COVER - LH/RH	2	\$ 1,060.00	✓
29	FRONT NO PLATE	S/N	\$ 60.00	X
30	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 17,540.00	
TOTAL LABOUR CHARGES		:	\$ 8,572.00	
GRAND TOTAL		:	\$ 26,112.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adam
11/12/20**SURVEYED DATE**

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

No Antihisel, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGERALLAN WU
CLAIMS CONSULTANT