



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107620

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 05/11/2021
Reference CC4/FCI20013767/R1es3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SGP 1603L
Insured Veh. SHA 1539G
Claim No. D20004924MFSH
Policy No. D-20094922MFSH
Accident Date 01/12/2020
Inspection Date 14/12/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20013767/R1es3q2	
			Date: 05/11/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1539G	Veh. Inspected	SGP 1603L	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20004924MFSH	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	14/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. M3 AUTO	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBS8M920X05J91236	Colour	WHITE	
Odometer	22683 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/35Z R19	CONTINENTAL	6 mm	
L/H Front Tyre	275/35Z R19	CONTINENTAL	6 mm	
R/H Rear Tyre	275/35Z R19	CONTINENTAL	6 mm	
L/H Rear Tyre	275/35Z R19	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2020	Inspection Date	14/12/2020	
Survey held at	BIS AUTOMOBILES PTE LTD 30 TEBAN GARDENS CRESCENT, SINGAPORE 608927			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 1603L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRY (SN)	NOT NECESSARY	150.00	50.00
2	TAILPIPE TIP (SN)	NOT NECESSARY	336.59	-
1	REAR EXHAUST SYSTE (SN)	BENT	2,712.11	2,712.11
1	CARRIER (SN)	BENT	446.74	446.74
1	BUMPER GUIDE (SN)	SERVICEABLE	63.56	-
1	BUMPER GUIDE (SN)	SERVICEABLE	63.56	-
1	BUMPER TRIM (SN)	DEFORMED	1,455.88	1,455.88
1	COVER LATERA (SN)	SERVICEABLE	45.98	-
1	GRID LATERAL (SN)	CRACKED	78.85	78.85
1	INSERT FOR B (SN)	DEFORMED	122.08	122.08
1	R-OFFICE ADHESIVE SE (SN)	NECESSARY	50.40	50.40
1	FLAP ,TOWING (SN)	MISSING	49.59	49.59
1	HEAT SHIELD (SN) (ADDITIONAL)	BENT	67.22	67.22
2	TAILPIPE TIPE BLACK (SN) (ADDITIONAL)	BENT	370.22	370.22
1	SET OF MOUNT PDC SEN (SN) (ADDITIONAL)	NECESSARY	55.96	55.96
1	CLAMPING BUSH (D=65M) (SN) (ADDITIONAL)	NECESSARY	57.86	57.86
1	CLAMPING BUSH (D=65M) (SN) (ADDITIONAL)	NECESSARY	57.86	57.86
			6,184.46	5,574.77
	<u>LABOUR</u>			
	REMOVE & INSTALL COMPLETE EXHAUST SYSTEM. (ADDITIONAL)		169.00	169.00
	REPLACING REAR SILENCER .	NOT NECESSARY	100.00	-
	VEHICLE DIAGNOSIS -CARRYING OUT THE ABL .		600.00	400.00
	TO REMOVE AND REPLACE REAR BUMPER AND ALL AFFECTED PARTS.		3,200.00	1,200.00
	TO REMOVE AND REFIX REAR BUMPER ,END PANEL TRIM ,WIRING PARKING SENSOR REPLACE ASSIST.		1,200.00	1,000.00
	TO PUTTY AND RESPRAY PAINT REAR END PANEL ,BUMPER AND ACCIDENT AFFECTED AREA.		2,500.00	1,800.00
			7,769.00	4,569.00
	GRAND TOTAL		13,953.46	10,143.77



RECOMMENDED COST OF REPAIRS			10,143.77
------------------------------------	--	--	------------------

Report Ref No. CC4/FCI20013767/R1es3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGP 1603L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGP 1603L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

