

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20013775/UPA3Q2

**Date:** 16/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993808

**Claimant**  
**Vehicle No :** SML6949G **Insured Vehicle No :** GBF78X

Date of Loss: 11/12/2020 Nature of Claim: TP Claim No: 0223416906SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML6949G</b>	Engine No:	CVK037174
Make & Model:	AUDI A5, 2.0 (A)	Chassis No:	WAUZZZF53HA037860
Reg. Date:	20/07/2017 (Man. Year: 2017)	Odometer:	66416 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,016.00	844.00	5,172.00	85.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,182.00	1,852.00	3,330.00	64.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,198.00</b>	<b>2,696.00</b>	<b>8,502.00</b>	<b>75.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	783.86	188.72	595.14	75.92
<b>Nett Amount (S\$)</b>	<b>11,981.86</b>	<b>2,884.72</b>	<b>9,097.14</b>	<b>75.92</b>
<b>+ Car Rental (3.0 x S\$150.00/day) (S\$)</b>		450.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,342.17</b>		

### INSPECTION

Date of Assignment: 17/12/2020

Date Inspected: 17/12/2020 Inspected At:

Premium Automobiles Pte Ltd (HQ)  
55 UBI ROAD 1  
Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,504.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	163.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS
4	1		*CHROME TRIM MOULDING	Scratched / Cracked	1,005.00 FS	*804.00 FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	886.00 FS	*- FS
7	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	44.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	484.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
11	1		*PACKING ADHESIVE	Not Necessary	18.00 FS	*- FS
12	1		*AUDI EMBLEM	Not Necessary	138.00 FS	*- FS
13	1		*A5 INSCRIPTION	Not Necessary	95.00 FS	*- FS
14	1		*TFSI INSCRIPTION	Not Necessary	95.00 FS	*- FS
15	1		*REAR NO PLATE (BY OWNER)	Scratched	40.00 FS	*40.00 FS
16	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **6,016.00** **844.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR REAR LID .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR LID	New	2,400.00	550.00
4	TO APPLY COATING TO AFFECTED PANELS	New	250.00	100.00
5	TO APPLY STICKER ON AFFECTED CHROME TRIMS	New	380.00	150.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>5,182.00</b>	<b>1,852.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**