

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0973/2020/NS
DATE : 14-Dec-20
WIP : 62364

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : GBF 78 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LAM YANG SAN(LAN YANGSHAN)
ADDRESS : BLK 272B PUNGGOL WALK
#15-571
SINGAPORE 822272
TELEPHONE : HP +65 96674617
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900111835-01
VEHICLE NO : **SML 6949 G**
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 20/7/2017
ENGINE NO : CVK 037174
CHASSIS NO : WAUZZZF53HA037860
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Dec-20
PLACE OF ACCIDENT : NORTH BRIDGE RD AND CANTONMENT
RD JUNCTION

Not Addressed

Alm

Marcus

Take photo After repair

3 day

HP 90096608

2/2 & 2696

LRCA Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 6949 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500
3	TO RESPRAY REAR BUMPER AND REAR LID. ✓ X	\$ 2,400.00	550
4	TO APPLY COATING TO AFFECTED PANELS. ✓	S/N \$ 250.00	100
5	TO APPLY STICKER ON AFFECTED CHROME TRIMS.	S/N \$ 380.00	180
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,182.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 6949 G

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER	✓	\$	2,504.00	X
2	REAR BUMPER FIXING PARTS	✓	\$	163.00	X
3	REAR BUMPER SECURING STRIP	✓	\$	220.00	X
4	CHROME TRIM MOULDING	scr/cr	\$	1,005.00	✓ 80%
5	REAR LIGHT REFLECTOR - LH/RH	✓	2	\$ 82.00	X
6	REAR BUMPER CARRIER	✓	\$	886.00	X
7	REAR BUMPER CARRIER SEAL	✓	2	\$ 28.00	X
8	REAR BUMPER GUIDE SECTION - LH/RH	✓	2	\$ 44.00	X
9	REAR PARKING AID SENSOR - INNER/OUTER	✓	2	\$ 484.00	X
10	REAR PARKING AID SEAL RING	✓ NN	4	\$ 14.00	✓ X
11	PACKING ADHESIVE	✓	\$	18.00	X
12	AUDI EMBLEM	✓	\$	138.00	X
13	A5 INSCRIPTION	✓	\$	95.00	X
14	TFSI INSCRIPTION	✓	\$	95.00	X
15	REAR NO PLATE (BY OWNER))	scr	S/N	\$ 40.00	✓
16	SUNDRIES	✓	\$	200.00	X
TOTAL SPARE PARTS			:	\$	6,016.00
TOTAL LABOUR CHARGES			:	\$	5,182.00
GRAND TOTAL			:	\$	11,198.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT