

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ISKANDAR BIN MOHAMED
BLK 448 PASIR RIS DRIVE 6
#04-146
S 510448

TPMS16
Veron.

Vehicle No :SMM 8381 A
Make/Model :TOYOTA SIENTA
Accident date :09.12.2020

No	DESCRIPTION	Qty	Amount (\$S)
----	-------------	-----	--------------

List Items

1	Rear bumper <i>Repair</i>	1	\$ 640.10 <i>+</i>
			\$ 640.10
	Less 25% Disc		\$ 160.03
	Total		\$ 480.08

Special Nett Items

1	Rear LH sport rim <i>cat</i>	1	\$ 880.00 <i>400(su)</i>
2	Rear LH tyre <i>new</i>	1	\$ 320.00 <i>x</i>
	Total		\$ 1200.00

Labour Cost

1	To check wheel alignment	<i>450</i>	\$ 100.00 <i>80</i>
2	Remove ,replace & repair consistent to the accident		\$ 700.00 <i>200</i>
3	Respray painting		\$ 800.00 <i>200</i>
	Total		\$ 1600.00

Grand Total \$ 3280.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 880

L/S: 700

02 Days