

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMQ7561H [YOUR INSURED] & SKX5515S [OUR CLIENT]
ON 12/12/2020.

ESTIMATED REPAIR COSTS FOR SKX5515S

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BOOTLID <i>2H1</i>	\$ 1,204.00	X
1PC	BOOTLID MAZDA LOGO <i>2H1</i>	\$ 97.00	X
1PC	BOOTLID 'MAZDA 3' EMBLEM <i>2H1</i>	\$ 78.00	X
1PC	BOOTLID 'SKYACTIV' EMBLEM <i>2H1</i>	\$ 86.00	X
1PC	BOOTLID LAMP LH <i>2H1</i>	\$ 499.00	X
1PC	TAIL LAMP LH <i>cut / scratched</i>	<i>473.00</i> \$ 1,190.00	✓
1PC	TAIL LAMP PANEL LH <i>2H1</i>	\$ 495.00	X
1PC	TAIL LAMP LOWER BRACKET LH <i>2H1</i>	\$ 175.00	X
1PC	REAR BUMPER <i>Revised / cut</i>	<i>998.00</i> \$ 1,227.00	✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$76.00 EACH <i>4/5 at 0/5H</i>	\$ 152.00	✓
1PC	REAR FENDER LH <i>Revised</i>	<i>1129.30</i> \$ 1,832.00	✓
1PC	REAR FENDER INNER SHIELD LH <i>2H1</i>	\$ 236.00	X
1PC	REAR FENDER AIR DUCT LH <i>original</i>	\$ 91.70	✓
1PC	REAR FENDER INNER TRIM LH <i>2H1</i>	\$ 446.00	X
1PC	REAR WHEEL HOUSING LH <i>2H1</i>	\$ 1,482.00	X
1PC	REAR RIM LH <i>distorted / cut</i>	<i>SN 500.00</i> \$ 1,560.00	✓
1PC	REAR WHEEL BEARING & HUB ASSY LH <i>2 Driv</i>	<i>256.20</i> \$ 573.00	✓
1PC	REAR LOWER ARM LH <i>2 distorted</i>	\$ 313.00	✓
1PC	REAR KNUCKLE ARM LH <i>2 distorted</i>	\$ 498.00	✓
1PC	REAR ABSORBER LH <i>2 distorted</i>	\$ 383.00	✓
1PC	REAR DOOR LH <i>2H1</i>	\$ 1,284.00	X
1PC	REAR DOOR WINDOW MOULDING LH <i>2H1</i>	\$ 312.00	X
1PC	REAR DOOR CHROME MOULDING LH <i>2H1</i>	\$ 331.00	X
1PC	REAR DOOR BLACK PLASTIC MOULDING LH <i>2H1</i>	\$ 191.00	X
2PCS	REAR DOOR HINGE LH @ \$93.00 EACH <i>2H1</i>	\$ 186.00	X
1PC	REAR DOOR WEATHER STRIP LH <i>2H1</i>	\$ 151.00	X
1PC	REAR DOOR INNER TRIM BOARD LH <i>2H1</i>	\$ 673.00	X
1PC	REAR WINDSCREEN MOULDING <i>2H1</i>	<i>559.60</i> \$ 1,284.00	✓
1PC	REAR END PANEL <i>Revised</i>	<i>5846.00</i> \$ 1,284.00	✓
1PC	REAR ASSIST ARM <i>distorted</i>	<i>357.00</i> \$ 587.90	✓
1PC	REAR UPPER ARM <i>distorted</i>	<i>224.90</i> \$ 587.90	✓
		PARTS SUM: \$ 16,064.70	
		PARTS LESS 20%: \$ 3,212.94	
		<i>5545.30</i>	
		<i>4436.24</i>	

PARTS TOTAL: \$ 12,851.76

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAIL LAMP CLIPS HW	\$	50.00	X
*	TO SUPPLY REAR FENDER SEALANT Hec	\$	80.00	40/-
*	TO SUPPLY REAR BUMPER CLIPS Hec	\$	50.00	20/-
*	TO SUPPLY REAR WINDSCREEN SEALANT Hec	\$	80.00	40/-
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL HW	\$	30.00	X
*	TO SUPPLY REAR FENDER INNER SHIELD CLIPS HW	\$	50.00	X
*	TO SUPPLY REAR DOOR INNER TRIM CLIPS HW	\$	50.00	X
*	TO SUPPLY 1PC TYRE Punctured 1 item	\$	300.00	150/-
			50% dep	
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$	300.00	80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	2,000.00	700/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00	700/-
*	TO TUFF COAT DAMAGED AREAS	\$	300.00	40/-
*	TO RNR REVERSE CAMERA	\$	100.00	HW
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$	250.00	150/-
*	TO CONDUCT COMPUTERIZED 4 WHEEL ALIGNMENT	\$	120.00	60/-
*	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	\$	250.00	120/-
			1920.00	
*	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$	200.00	HW
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$	250.00	HW
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00	HW
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$	120.00	40/-

15/12/2020 @ 1600hrs

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,931.76

LABOUR & S/N TOTAL: \$ 7,080.00

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7106.24

2/S 5600/-

LKK Andu