

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013789/DQD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001347818

Claimant
Vehicle No : SLG5155A

Insured Vehicle No : SJY2359C

Date of Loss: 05/12/2020

Nature of Claim: TP

Claim No: 250820

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG5155A**

Make & Model: KIA FORTE K3, 1.6 (A)

Engine No: G4FGGH652949

Reg. Date: 03/10/2016 (Man. Year: 2016)

Chassis No: KNAFX411MH5658092

Colour: White

Odometer: 70968 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,438.00	900.00	18,538.00	95.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,070.00	1,700.00	6,370.00	78.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,508.00	2,600.00	24,908.00	90.55
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	27,508.00	2,050.00	25,458.00	92.55
+ GST 7.00/7.00% (S\$)	1,925.56	143.50	1,782.06	92.55
Nett Amount (S\$)	29,433.56	2,193.50	27,240.06	92.55

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 15/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG5155A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	876.00 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	145.00 FL	*- FL
3	1		*FRONT RIM LH	Cut	1,386.00 FS	*450.00 FS
4	1		*FRONT WHEEL BEARING AND HUB ASSY LH	Not Necessary	524.00 FL	*- FL
5	1		*FRONT ABSORBER LH	Not Necessary	398.00 FL	*- FL
6	1		*FRONT LOWER ARM LH	Not Necessary	411.00 FL	*- FL
7	1		*FRONT KNUCKLE ARM LH	Not Necessary	523.00 FL	*- FL
8	1		*FRONT STABILIZER BAR	Not Necessary	399.00 FL	*- FL
9	1		*FRONT STABILIZER LINK LH	Not Necessary	201.00 FL	*- FL
10	1		*FRONT TIE ROD LH	Not Necessary	295.00 FL	*- FL
11	1		*FRONT TIE ROD END LH	Not Necessary	342.00 FL	*- FL
12	1		*FRONT DOOR LH	Repair	1,689.00 FL	*- FL
13	1		*FRONT DOOR WEATHER STRIP LH	Serviceable	258.00 FL	*- FL
14	1		*FRONT DOOR WINDOW MOULDING LH	Serviceable	195.00 FL	*- FL
15	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	725.00 FL	*- FL
16	1		*ROCKER PANEL LH	Not Necessary	1,253.00 FL	*- FL
17	1		*REAR DOOR LH	Repair	1,701.00 FL	*- FL
18	1		*REAR DOOR WEATHERSTRIP LH	Serviceable	255.00 FL	*- FL
19	1		*REAR DOOR WINDOW MOULDING LH	Serviceable	198.00 FL	*- FL
20	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	752.00 FL	*- FL
21	1		*REAR FENDER LH	Repair	1,980.00 FL	*- FL
22	1		*REAR FENDER INNER SHIELD LH	Not Necessary	185.00 FL	*- FL
23	1		*REAR RIM LH	Punctured	1,386.00 FS	*450.00 FS
24	1		*REAR WHEEL BEARING & HUB ASSY LH	Not Necessary	549.00 FL	*- FL
25	1		*REAR LOWER ARM LH	No such part	432.00 FL	*- FL
26	1		*REAR ABSORBER LH	Not Necessary	401.00 FL	*- FL
27	1		*REAR AXLE	Not Necessary	1,980.00 FL	*- FL
28	1		*REAR BUMPER	Repair	785.00 FL	*- FL
29	2		*REAR BUMPER SIDE RETAINER LH /RH	Serviceable	178.00 FL	*- FL
30	1		*REAR WINDSCREEN MOULDING	Not Necessary	310.00 FL	*- FL
31	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*REAR DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,232.00 900.00
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,794.00 0.00

Total Parts (\$\$) 19,438.00 900.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	800.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	0.00
6	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
7	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
8	TO CONDUCT COMPUTERIZED 4 WHEEL ALIGNMENT	New	120.00	60.00
9	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
10	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
11	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
12	TO RNR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	0.00
13	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
14	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			8,070.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >