



# GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**  
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500  
Website: www.goldbell.com.sg  
Co. Reg No. 198003963G

Page 1 / 3

## ESTIMATE

Date : 25/11/2020  
To : EQ INSURANCE COMPANY LTD.  
Attn. :  
Office / Mobile : *Not Withhold*  
Email Address : *11 Day & After Rain*  
From : GOLDBELL ENGINEERING PTE LTD  
Attn. : KONYINSIEW  
Office / Mobile : +65 6861 0007  
Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : SGS3631B  
Model : MITSUBISHI LANCER 1.6 A  
Chassis No : JMYSTCS3A7U005354  
Engine No : 4G18HS0321  
Quotation No. : 122537  
Ref. No. :  
D.O.A. : 24/11/2020  
Policy No. : DMPCSNAA00022712006  
Claim Type : TP CLAIM - EQ  
Workshop : 8 TUAS AVE 18

| S/N | Part No | Description                  | Qty | U/Price | %   | Net Price | Ext Price |   |
|-----|---------|------------------------------|-----|---------|-----|-----------|-----------|---|
| 1   |         | BONNET                       | 1   | 986.30  | -10 | 887.67    | 887.67    | ✓ |
| 2   |         | BONNET LOCK                  | 1   | 256.30  | -10 | 230.67    | 230.67    | ✓ |
| 3   |         | BONNET HINGE LH              | 1   | 155.10  | -10 | 139.59    | 139.59    | ✓ |
| 4   |         | BONNET HINGE RH              | 1   | 155.10  | -10 | 139.59    | 139.59    | ✓ |
| 5   |         | FRONT GRILLE                 | 2   | 223.50  | -10 | 201.15    | 402.30    | ✓ |
| 6   |         | FRONT EMBLEM                 | 1   | 65.80   | -10 | 59.22     | 59.22     | ✓ |
| 7   |         | FRONT BUMPER                 | 1   | 796.30  | -10 | 716.67    | 716.67    | ✓ |
| 8   |         | FRONT BUMPER RETAINER LH     | 1   | 35.00   | -10 | 31.50     | 31.50     | ✓ |
| 9   |         | FRONT BUMPER RETAINER RH     | 1   | 35.00   | -10 | 31.50     | 31.50     | ✓ |
| 10  |         | FRONT FOG LAMP LH            | 1   | 240.00  | -10 | 216.00    | 216.00    | ✓ |
| 11  |         | FRONT FOG LAMP RH            | 1   | 240.00  | -10 | 216.00    | 216.00    | ✓ |
| 12  |         | FRONT FOG LAMP COVER LH      | 1   | 75.00   | -10 | 67.50     | 67.50     | ✓ |
| 13  |         | FRONT FOG LAMP COVER RH      | 1   | 75.00   | -10 | 67.50     | 67.50     | ✓ |
| 14  |         | FRONT BUMPER LOWER SKIRT     | 1   | 480.00  | -10 | 432.00    | 432.00    | ✓ |
| 15  |         | HEADLAMP LH                  | 1   | 875.00  | -10 | 787.50    | 787.50    | ✓ |
| 16  |         | HEADLAMP RH                  | 1   | 875.00  | -10 | 787.50    | 787.50    | ✓ |
| 17  |         | HEADLAMP BRACKET PANEL LH    | 1   | 199.60  | -10 | 179.64    | 179.64    | ✓ |
| 18  |         | HEADLAMP BRACKET PANEL RH    | 1   | 199.60  | -10 | 179.64    | 179.64    | ✓ |
| 19  |         | FRONT REINFORCEMENT          | 1   | 497.60  | -10 | 447.84    | 447.84    | ✓ |
| 20  |         | FRONT FENDER LH              | 1   | 480.00  | -10 | 432.00    | 432.00    | ✓ |
| 21  |         | FRONT FENDER INNER SHEILD LH | 1   | 178.40  | -10 | 160.56    | 160.56    | ✓ |

PARTS TOTAL : 6,612.39

### SPECIAL NETT ITEMS

|   |                                       |   |        |   |
|---|---------------------------------------|---|--------|---|
| 1 | FRONT FENDER INNER SHIELD CLIPS (SET) | 1 | 30.00  | ✓ |
| 2 | FRONT BUMPER CLIPS (SET)              | 1 | 30.00  | ✓ |
| 3 | FRONT TYRE LH (195/60 R15)            | 1 | 150.00 | ✓ |
| 4 | FRONT RIM LH                          | 1 | 250.00 | ✓ |
| 5 | FRONT GRILLE CLIPS (SET)              | 1 | 30.00  | ✓ |

PARTS TOTAL: 490.00

Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

Page 2 / 3

## ESTIMATE

|                          |                              |                        |                         |
|--------------------------|------------------------------|------------------------|-------------------------|
| <b>Date</b> :            | 25/11/2020                   | <b>Reg No</b> :        | SGS3631B                |
| <b>To</b> :              | EQ INSURANCE COMPANY LTD.    | <b>Model</b> :         | MITSUBISHI LANCER 1.6 A |
| <b>Attn.</b> :           |                              | <b>Chassis No</b> :    | JMYSTCS3A7U005354       |
| <b>Office / Mobile</b> : |                              | <b>Engine No</b> :     | 4G18HS0321              |
| <b>Email Address</b> :   |                              | <b>Quotation No.</b> : | 122537                  |
|                          |                              | <b>Ref. No.</b> :      |                         |
| <b>From</b> :            | GOLDBELL ENGINEERING PTE LTD | <b>D.O.A.</b> :        | 24/11/2020              |
| <b>Attn.</b> :           | KONYINSIEW                   | <b>Policy No.</b> :    | DMPCNA00022712006       |
| <b>Office / Mobile</b> : | +65 6861 0007                | <b>Claim Type</b> :    | TP CLAIM - EQ           |
| <b>Email / Fax No.</b> : | KonYinSiew@goldbell.com.sg   | <b>Workshop</b> :      | 8 TUAS AVE 18           |

### LABOUR CHARGES

|   |                                                                                                                           |              |
|---|---------------------------------------------------------------------------------------------------------------------------|--------------|
| 1 | TO REMOVE, REFIX & REPAIR<br>AFFECTED DAMAGED PARTS.<br>INCLUDING KNOCK OUT, WELD AND<br>STRAIGHTEN ON THE AFFECTED PARTS | 2400.00      |
| 2 | TO REPAIR AND ALIGN RH FRONT<br>FENDER                                                                                    | nn 150.00 X  |
| 3 | TO CHECK AND RECONNECT ALL<br>NECESSARY WIRING                                                                            | 201 150.00   |
| 4 | TO PUTTY, CLEAN, SPRAY PAINT AND<br>POLISH, ETC                                                                           | 1400 2100.00 |
| 5 | TO CONDUCT FOUR WHEEL ALIGNMENT                                                                                           | nn 100.00 X  |

|                            |                  |
|----------------------------|------------------|
| LABOUR TOTAL :             | 4,900.00         |
| SUB-TOTAL :                | 12,002.39        |
| GST @ 7% for \$ 12,002.39  | 840.17           |
| <b>GRAND TOTAL (S\$) :</b> | <b>12,842.56</b> |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: