

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	Document No.	: SQT20004035	Page	1
Registration No	: SLJ3660E	Date	: 10. Dec 2020		
Chassis No	: JHMGK5850HX200868	Customer No.	: WZF002		
Model	: JAZZ 1.5VTIR CVT 17YM	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: GABRIEL CHOONG CHEE WEI	Engine No	: L15B31190615		
Ins Policy No.	:	Date Time	: 10. Dec 2020 9:43:48 AM		
Date of Accident	: 8/12/2020	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: GABRIEL CHOONG CHEE WEI OWNER INSURER: MSIG ACC DATE: 08/12/2020 SURVEYED BY: DATE: REF NO: TP INSURER: MSFIRST CAPITAL TP VEH: SHD4700X						
68100-TAS-Z50ZZ	TAILGATE COMP	1	749.60	25	562.20	39.35	601.55
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE	1	86.20	25	64.65	4.53	69.18
75722-T5L-T01	EMBLEMRR.	1	11.90	25	8.92	0.62	9.54
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.70	25	8.77	0.61	9.38
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	7.10	25	10.65	0.75	11.40
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
04715-T5B-000ZZ	FACERR.BUMPER	1	515.50	25	386.62	27.06	413.68
71502-T5A-000	GARNISHR.RR.BUMPER	1	14.60	25	10.95	0.77	11.72
71507-T5A-000	GARNISHL.RR.BUMPER	1	14.60	25	10.95	0.77	11.72
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	5	2.30	25	8.62	0.60	9.22
66100-TAR-T10ZZ	PANEL COMPRR.	1	328.60	25	246.45	17.25	263.70
				Sum Item	1471.76	103.02	1,574.78
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00

Printed on 10/12/2020 10:06:39 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	Document No.	: SQT20004035	Page	2
Registration No	: SLJ3660E	Date	: 10. Dec 2020		
Chassis No	: JHMGK5850HX200868	Customer No.	: WZF002		
Model	: JAZZ 1.5VTIR CVT 17YM	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: GABRIEL CHOONG CHEE WEI	Engine No	: L15B31190615		
Ins Policy No.	:	Date Time	: 10. Dec 2020 9:43:48 AM		
Date of Accident	: 8/12/2020	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00		560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	3250.00		3250.00	227.50	3477.50
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	3120.00		3120.00	218.40	3338.40
Sum Labor					9360.00	655.20	10,015.20

Survey By					
Date & Time					
Excess					
Status					
Signature					
			Total Amount	10,831.76	758.22
			Total (Inclusive of GST)		11,589.98

Printed on 10/12/2020 10:06:39 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.