

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

TO	: ECICS	DATE	: 15/12/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SMV1241U		<i>Denise</i>
VEHICLE MODEL	: KIA CERATO		
CHASSIS NO	: KNAF5416ML5064431		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XAVIER / 90079247	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Rebond</i>	1	\$ 633.00	\$ 633.00
2	FRONT BUMPER SIDE HOLDER <i>New</i>	2	\$ 28.00	\$ 56.00
3	FRONT BUMPER TOW COVER <i>Rebond</i>	1	\$ 29.00	\$ 29.00
4	FRONT BUMPER LOGO <i>New</i>	1	\$ 38.00	\$ 38.00
5	FRONT BUMPER LOWER GARNISH <i>Rebond</i>	1	\$ 241.00	\$ 241.00
6	FRONT BUMPER LAMP RH <i>Cracked</i>	1	\$ 143.00	\$ 143.00
7	FRONT BUMPER LAMP COVER RH <i>Cracked</i>	1	\$ 89.00	\$ 89.00
8	FRONT BUMPER AIR GUIDE RH <i>Rebond</i>	1	\$ 45.00	\$ 45.00
9	FRONT BUMPER FOG LAMP RH <i>Cracked</i>	1	\$ 303.00	\$ 303.00
10	FRONT BUMPER LOWER GRILLE <i>Rebond</i>	1	\$ 262.00	\$ 262.00
11	FRONT BUMPER SENSOR <i>1 piece damaged</i>	2	\$ 225.00	\$ 450.00
12	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 497.00	\$ 497.00
13	FRONT BUMPER LOWER BEAM <i>Cracked</i>	1	\$ 114.00	\$ 114.00
14	FRONT BUMPER SPONGE <i>Cracked</i>	1	\$ 105.00	\$ 105.00
15	FRONT GRILLE <i>Cracked</i>	1	\$ 328.00	\$ 328.00
16	HEADLAMP <i>Rit Cracked</i>	2	\$ 2,210.00	\$ 4,420.00
17	FRONT RH FENDER <i>Repair</i>	1	\$ 430.00	\$ 430.00
18	FRONT RH FENDER INNER SHIELD <i>torn</i>	1	\$ 156.00	\$ 156.00

TOTAL PRICE: \$ 8,339.00
LESS 10% \$ 833.90
SUB TOTAL PRICE: \$ 7,505.10

5474
4926.60

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00
2	FRONT NUMBER PLATE HOLDER <i>Debond</i>	1	\$ 30.00	\$ 30.00
3	FRONT BUMPER CLIPS <i>Nec</i>	1 SET	\$ 50.00	\$ 50.00
4	FRONT BUMPER LOWER SPOILER <i>Debond</i>	1	\$ 800.00	\$ 800.00
5	FRONT GRILLE CLIPS <i>Nec</i>	1 SET	\$ 20.00	\$ 20.00
6	FRONT RH FENDER INNER SHIELD CLIPS <i>Nec</i>	1 SET	\$ 30.00	\$ 30.00
			TOTAL :	\$ 960.00

840

✓
✓
30
200
1

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 600.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 600.00	250	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 100.00	X	
5	TO REMOVE FRONT BUMPER SENSOR	\$ 100.00	50	
		TOTAL: \$ 1,450.00	730	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 8,465.10
 TOTAL LABOUR COST: \$ 1,450.00
 TOTAL REPAIR COST: \$ 9,915.10

total: 6490.60
 L/S: 5.2K
 04 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:
 Signature:
 Date: