

SOMPO

|                |                   |
|----------------|-------------------|
| Vehicle number | SLJ436G           |
| Make / Model   | TOYOTA/COROLLA    |
| Chassis number | MR053REH104556708 |
| Accident date  | 5/12/20           |
| Reference      | 2012-08           |

| Qty                                           | Particulars                 | Unit Price - SGD \$   |         |
|-----------------------------------------------|-----------------------------|-----------------------|---------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |                             |                       |         |
| 1                                             | BOOTLID                     | 822.50 X nn           |         |
| 1                                             | BOOTLID EMBLEM LOGO         | 69.00 X nn            |         |
| 1                                             | BOOTLID EMBLEM -COROLLA     | 46.00 X nn            |         |
| 1                                             | BOOTLID EMBLEM - ALTIS      | 50.60 X nn            |         |
| 1                                             | BOOTLID CHROME GARNISH      | 265.65 X nn           |         |
| 1                                             | BOOTLID LICENCE PLATE LAMP  | 72.40 X nn            |         |
| 2                                             | BOOTLID LAMP                | 763.36 X nn           |         |
| 2                                             | BOOTLID LAMP INNER SEAL     | 64.40 X nn            |         |
| 1                                             | BOOTLID LOCK                | 437.00 X nn           |         |
| 1                                             | BOOTLID LOCK CATCH          | nn 23.00 X            |         |
| 1                                             | BOOTLID INNER TRIM          | 396.75 X nn           |         |
| 1                                             | BOOTLID WEATHERSTRIP        | 281.30 X nn           |         |
| 1                                             | END PANEL                   | 672.75 X nn           |         |
| 1                                             | END PANEL TOP GARNISH       | 241.50 X nn           |         |
| 1                                             | REAR BUMPER                 | 557.75 de             |         |
| 2                                             | REAR BUMPER RETAINER        | 130.00 LH-104 RH X nn |         |
| 2                                             | REAR BUMPER REFLECTOR       | 181.20 X nn           |         |
| 2                                             | REAR BUMPER BRACKET         | 149.50 LH-104 RH X nn |         |
| 1                                             | REAR BUMPER REINFORCEMENT   | bt ✓ 453.20 X ?       |         |
| 4                                             | PDC SENSOR                  | 722.20 200? plus nw ✓ |         |
| 1                                             | SENSOR WIRE HARNESS         | 381.00 X nn           |         |
|                                               |                             | 6781.06               | 1275.95 |
|                                               | Less 25 %                   | 1695.26               | 956.96  |
|                                               | Subtotal                    | 5085.80               |         |
|                                               | Balance C/F                 | 5085.80               |         |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                             |                       |         |
| 1 SET                                         | REAR BUMPER CLIP            | 40.00 30 net ✓        |         |
| 1 SET                                         | REAR FENDER INNER TRIM CLIP | 30.00 X nn            |         |
| 1 SET                                         | REAR NUMBER PLATE           | 70.00 X nn            |         |
| 1 SET                                         | END PANEL GARNISH CLIP      | 30.00 X nn            |         |
| 1 SET                                         | BOOTLID INNER TRIM CLIP     | 30.00 X nn            |         |
| 1                                             | JOINT SEALANT               | 100.00 X nn           |         |
|                                               | Subtotal                    | 300.00                |         |
|                                               | Balance C/F                 | 5385.80               |         |

| <u>LABOUR AND MISCELLANEOUS CHARGES</u> |                                                    |             |
|-----------------------------------------|----------------------------------------------------|-------------|
| 1                                       | CHEECK REAR WIRING AND LIGHTNING SYSTEM            | 60.00 30    |
| 2                                       | REMOVE, REFIT REAR LINING , TRIM AND GARNISH       | 200.00 Xnn  |
| 3                                       | REMOVE, RENEW REAR REVERSE SENSOR                  | 120.00 30   |
| 4                                       | REMOVE AND RENEW REAR EXHAUST                      | 120.00 X nn |
| 5                                       | TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW | 200.00 X nn |
| 6                                       | PANEL BEATING ON AFFECTED AREAS                    | 1200.00 200 |
| 7                                       | SPRAY PAINTING ON AFFECTED AREAS                   | 1200.00 200 |
| 8                                       | APPLY ANTI RUST ON AFFECTED AREAS                  | 100.00 X nn |
| Subtotal                                |                                                    | 3200.00 490 |
| Grand total                             |                                                    | 8585.80     |

1446.96

l/s\$1100

2 days.

Taufik 97445449  
 -WP 14/12/200 545pm  
 l/s Resurvey after repair  
 2 days  
 Taufik @ 11/12/2000

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: