



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8785E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	PRIG4Q8 COVER FRONT BUMPER	DEFORMED	499.90	499.90
10	PRIVC BUMPER PIECE	NECESSARY	22.00	22.00
1	RADIATOR GRILLE LOWER	DEFORMED	438.00	438.00
	LESS 25% DISCOUNT		-239.98	-239.98
			719.92	719.92
<u>NETT ITEMS</u>				
1	NO PLATE (S) WITH TRIM COV (N)	BENT	55.00	55.00
	LESS 10% DISCOUNT		-5.50	-5.50
			49.50	49.50
<u>LABOUR</u>				
	PANEL BEATING.		350.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
			600.00	520.00
GRAND TOTAL			1,369.42	1,289.42

RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,289.42
--	--	--	-----------------

Report Ref No. NS/INC20013798/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.