

## Shiau Chan (LKKAuto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Tuesday, 19 January 2021 11:09 AM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: NTUC-TP SHC 8785E SURVEYED BY TAUFIKH

Dear Shiau Chan,

AUDIT CHECK DONE FOR SHC8785E, FOUND WRONG PART REAR BUMPER WAS QUOTED IN THE REPAIR ESTIMATE INSTEAD OF FRONT BUMPER.  
ALREADY TOLD TAUFIKH.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 19 January, 2021 10:13 AM  
**To:** Simon Ho (LKKAuto)  
**Subject:** NTUC-TP SHC 8785E SURVEYED BY TAUFIKH

Dear Simon,

For your audit.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)