

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN2893Z**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 13:25HRS

28	FRONT SUPPORT PANEL TOP GARNISH <i>Deformed</i>	1	\$ 155.00	\$ 155.00	✓
29	FRONT BRACE PANEL <i>Best</i>	1	\$ 105.00	\$ 105.00	✓
30	RADIATOR <i>Best</i>	1	\$ 1,493.70	\$ 1,493.70	✓
31	RADIATOR SIDE GARNISH <i>Deformed</i>	2	\$ 75.80	\$ 151.60	✓
32	RADIATOR RUBBER MOUNTING <i>NEW</i>	4	\$ 40.00	\$ 160.00	+.
33	RADIATOR TOP HOSE <i>3mm</i>	1	\$ 85.00	\$ 85.00	+.
34	RADIATOR LOWER HOSE	1	\$ 85.00	\$ 85.00	+.
35	RADIATOR TOP BRACKET <i>Cracked</i>	2	\$ 40.00	\$ 80.00	✓
36	RADIATOR FAN MOTOR <i>new</i>	1	\$ 493.20	\$ 493.20	+.
37	RADIATOR FAN COWLING <i>cracked</i>	1	\$ 278.60	\$ 278.60	✓
38	RADIATOR FAN BLADE <i>cracked</i>	1	\$ 178.60	\$ 178.60	✓
39	RADIATOR SPARE TANK <i>Deformed</i>	1	\$ 195.30	\$ 195.30	✓
40	AIR CON CONDENSER <i>Best</i>	1	\$ 1,355.32	\$ 1,355.32	✓
41	AIR CON CONDENSER MOUNTING RUBBER <i>M</i>	4	\$ 24.70	\$ 98.80	+.
42	AIR CON CONDENSER BRACKET <i>new</i>	2	\$ 38.60	\$ 77.20	+.
43	AIR CON FAN BLADE <i>new</i>	1	\$ 171.20	\$ 171.20	+.
44	AIR CON FAN MOTOR <i>new</i>	1	\$ 493.70	\$ 493.70	+.
45	AIR CON FAN COWLING <i>cracked</i>	1	\$ 278.60	\$ 278.60	✓
46	AIR CON COMPRESSOR <i>new</i>	1	\$ 2,762.90	\$ 2,762.90	+.
47	AIR CON COMPRESSOR HOSE (PRESSURE) <i>new</i>	1	\$ 379.20	\$ 379.20	+.
48	AIR CON COMPRESSOR HOSE (SUCTION) <i>Best</i>	1	\$ 365.90	\$ 365.90	✓
49	AIR CON PIPE (OUTLET) <i>new</i>	1	\$ 380.00	\$ 380.00	+.
50	FRONT TEMPERATURE SENSOR <i>New</i>	1	\$ 128.60	\$ 128.60	+.
51	HORN <i>Deformed</i>	2	\$ 120.61	\$ 241.22	✓
52	ABS PUMP <i>cracked</i>	1	\$ 5,400.30	\$ 5,400.30	✓
53	ABS PUMP BRACKET <i>new</i>	1	\$ 135.70	\$ 135.70	+.
54	ABS PUMP BRAKE PIPE <i>new</i>	4	\$ 250.00	\$ 1,000.00	+.
55	BATTERY BRACKET <i>new</i>	1	\$ 57.60	\$ 57.60	+.
56	FRONT INTAKE MANIFOLD <i>3mm</i>	1	\$ 987.40	\$ 987.40	+.
57	ENGINE MOUNTING (SET) <i>3mm</i>	1	\$ 850.90	\$ 850.90	+.
58	FRONT CHASSIS MEMBER LH <i>Repair</i>	1	\$ 1,653.10	\$ 1,653.10	+.
59	TAILGATE <i>Distorted</i>	1	\$ 1,290.00	\$ 1,290.00	✓
60	TAILGATE DETECTOR <i>Smashed</i>	1	\$ 174.80	\$ 174.80	✓
61	TAILGATE DAMPER <i>new</i>	2	\$ 229.60	\$ 459.20	+.
62	TAILGATE HINGE <i>new</i>	2	\$ 74.50	\$ 149.00	+.
63	TAILGATE LOGO <i>new</i>	1	\$ 65.00	\$ 65.00	✓
64	TAILGATE LAMP <i>cracked</i>	2	\$ 298.00	\$ 596.00	✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN2893Z**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 13:25HRS

65	TAILGATE NUMBER PLATE LAMP	New	2	\$ 62.00	\$ 124.00	+	
66	TAILGATE OUTER MOULDING	Cruld	1	\$ 290.00	\$ 290.00	✓	
67	TAILGATE SWITCH BUTTOM	New	1	\$ 496.20	\$ 496.20	+	
68	TAILGATE INNER LOCK	Dangd	1	\$ 398.00	\$ 398.00	✓	
69	TAILGATE LOCK CATCH	New	1	\$ 35.00	\$ 35.00	x.	
70	TAILGATE WEATHER STRIP	lt	1	\$ 320.00	\$ 320.00	✓	
71	TAILGATE INNER HOLDER	New	1	\$ 118.10	\$ 118.10	+	
72	TAILGATE INNER BOARD	Cruld	1	\$ 450.00	\$ 450.00	✓	
73	TAILGATE INNER TOP GARNISH	ZMP	1	\$ 320.00	\$ 320.00	+	
74	TAILGATE INNER SIDE GARNISH	JM	2	\$ 280.00	\$ 560.00	+	
75	TAILGATE WINDSCREEN MOULDING	New	1	\$ 140.00	\$ 140.00	✓	
76	REAR BUMPER	Distorted	1	\$ 694.30	\$ 694.30	579	
77	REAR BUMPER REFLECTOR	Cruld	2	\$ 68.00	\$ 136.00	✓	
78	REAR BUMPER BRACKET	Dented	2	\$ 95.20	\$ 190.40	—	
79	REAR BUMPER SIDE RETAINER	m	2	\$ 60.00	\$ 120.00	—	
80	REAR BUMPER CORNER RETAINER	New	2	\$ 65.10	\$ 130.20	x.	
81	TAILLAMP	Cruld	2	\$ 520.00	\$ 1,040.00	643.	
82	TAILLAMP PANEL	Repair	2	\$ 398.10	\$ 796.20	+	
83	REAR DOOR LH	Repair	1	\$ 1,280.00	\$ 1,280.00	+	
84	REAR DOOR OUTER MOULDING LH	} AP m	1	\$ 118.00	\$ 118.00	+	
85	REAR DOOR LOWER CHROME MOULDING LH		1	\$ 225.00	\$ 225.00	+	
86	REAR DOOR WEATHER STRIP LH		1	\$ 198.00	\$ 198.00	+	
87	REAR DOOR LOCK CATCH LH		1	\$ 45.00	\$ 45.00	+	
88	REAR DOOR INNER TRIM BOARD LH		1	\$ 785.00	\$ 785.00	+	
89	REAR DOOR FRAME WEATHER STRIP LH		1	\$ 160.00	\$ 160.00	+	
90	REAR DOOR INNER LOCK LH		1	\$ 485.00	\$ 485.00	+	
91	REAR FENDER		LH Buckled	2	\$ 940.00	\$ 1,880.00	940.
92	REAR FENDER INNER COWLING		New	2	\$ 380.00	\$ 760.00	x.
93	REAR FENDER INNER TRIM		Cruld	2	\$ 738.10	\$ 1,476.20	1358
94	REAR FENDER GLASS W/MOULding	New	2	\$ 560.00	\$ 1,120.00	+	
95	REAR FENDER INNER PANEL LH	Repair	1	\$ 765.30	\$ 765.30	+	
96	FUEL TANK	New	1	\$ 1,230.80	\$ 1,230.80	+	
97	FUEL TANK INSULATOR	New	1	\$ 253.20	\$ 253.20	+	
98	REAR ABS SENSOR	New	2	\$ 325.00	\$ 650.00	+	
99	REAR AXLE	ZMP	1	\$ 1,289.10	\$ 1,289.10	+	
100	REAR SHOCK ABSORBER LH	New	1	\$ 225.10	\$ 225.10	+	
101	REAR WHEEL HUP LH	New	1	\$ 525.00	\$ 525.00	+	

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN2893Z**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 13:25HRS

102	REAR END PANEL	Distorted	1	\$ 495.00	\$ 495.00	✓
103	REAR END PANEL TOP GARNISH	crack	1	\$ 245.00	\$ 245.00	✓
104	REAR END PANEL BOTTOM (CENTRE)	Distorted	1	\$ 420.00	\$ 420.00	✓
105	REAR FLOOR PANEL	Repair	1	\$ 975.40	\$ 975.40	+
106	REAR FLOOR PANEL TOP BOARD	Delud	1	\$ 425.00	\$ 425.00	✓
107	REAR FLOOR PANEL SIDE BOARD	new	2	\$ 125.00	\$ 250.00	+
108	REAR FLOOR SIDE PANEL LH	Distorted	1	\$ 347.60	\$ 347.60	✓
109	REAR FLOOR TOP BOARD INNER SUPPORT	new	1	\$ 596.80	\$ 596.80	+
110	REAR FLOOR PANEL CROSS MEMBER	Repair	1	\$ 598.60	\$ 598.60	+
111	REAR SPARE TYRE CHAIN	Damaged	1	\$ 330.00	\$ 330.00	✓
112	REAR CHASSIS MEMBER LH	Repair	1	\$ 1,966.10	\$ 1,966.10	+
113	REAR CHASSIS CROSS MEMBER	Repair	1	\$ 2,210.30	\$ 2,210.30	+
114	CENTER EXHAUST (W/CATALYTIC CONVERTER)	Best	1	\$ 3,290.70	\$ 3,290.70	1250.
115	CENTER EXHAUST INSULATOR	new	1	\$ 271.80	\$ 271.80	+
116	CENTER EXHAUST GASKET (SET)	new	1	\$ 60.00	\$ 60.00	✓
117	REAR EXHAUST BOX	Best	1	\$ 990.00	\$ 990.00	685
118	REAR EXHAUST GASKET (SET)	new	1	\$ 85.00	\$ 85.00	✓
119	REAR EXHAUST MOUNTING	1 piece	4	\$ 60.00	\$ 240.00	60
120	REVERSE SENSOR	Damaged	4	\$ 220.00	\$ 880.00	300 (SN)
121	REVERSE SENSOR HOLDER	new	4	\$ 55.00	\$ 220.00	+
122	REVERSE SENSOR WIREHANESS	snapped	1	\$ 565.00	\$ 565.00	✓

2975170 TOTAL PRICE \$ 74,676.01
 2231377 LESS 25% \$ 18,669.00
 S.N:300 SUB TOTAL PRICE \$ 56,007.01

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT		
1	FRONT NUMBER PLATE	Best	1	\$ 80.00	\$ 80.00	50
2	FRONT BUMPER CLIP (SET)	new	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER BOTTOM GARNISH CLIP (SET)	new	1	\$ 60.00	\$ 60.00	30
4	FRONT BUMPER LOWER SIDE GRILLE CLIP (SET)	new	1	\$ 60.00	\$ 60.00	+
5	FRONT BUMPER LOWER SIDE GARNISH CLIP (SET)	new	1	\$ 60.00	\$ 60.00	+
6	CENTRE GRILLE CLIP (SET)	new	1	\$ 30.00	\$ 30.00	10
7	BONNET INSULATOR CLIP (SET)	new	1	\$ 50.00	\$ 50.00	30
8	FRONT SUPPORT PANEL SEALANT	new	1	\$ 80.00	\$ 80.00	+
9	FRONT SUPPORT PANEL TOP GARNISH (SET)	new	1	\$ 50.00	\$ 50.00	20
10	FRONT FENDER COWLING CLIP (SET)	new	1	\$ 80.00	\$ 80.00	+
11	FRONT QUARTER GLASS SEALANT	new	2	\$ 60.00	\$ 120.00	+
12	FRONT QUARTER GLASS INNER SEAL	new	2	\$ 40.00	\$ 80.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN2893Z**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 13:25HRS

13	FRONT QUARTER GLASS SOLAR FILM <i>Men</i>	2	\$ 150.00	\$ 300.00	<i>+</i>
14	COOLANT <i>Me</i>	1	\$ 60.00	\$ 60.00	<i>40.</i>
15	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	<i>50</i>
16	REAR BUMPER CLIPS (SET) <i>me</i>	1	\$ 80.00	\$ 80.00	<i>30.</i>
17	TAILGATE INNER TOP GARNISH CLIP (SET) <i>Me</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
18	TAILGATE INNER SIDE GARNISH CLIP (SET) <i>Me</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
19	TAILGATE EMBLEM 'VALVE MATIC' (SPECIAL TYPE) <i>Me</i>	1	\$ 120.00	\$ 120.00	<i>50</i>
20	TAILGATE EMBLEM 'ELEGANCE'(SPECIAL TYPE) <i>Me</i>	1	\$ 120.00	\$ 120.00	<i>50</i>
21	TAILGATE WINDSCREEN SEALANT <i>Me</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
22	TAILGATE WINDSCREEN INNER SHIELD <i>Me</i>	1	\$ 60.00	\$ 60.00	<i>40</i>
23	TAILGATE WINDSCREEN SOLAR FILM <i>Me</i>	1	\$ 550.00	\$ 550.00	<i>+</i>
24	TAILLAMP CLIP (SET) <i>Me</i>	1	\$ 40.00	\$ 40.00	<i>20.</i>
25	TAILLAMP PANEL SEALANT <i>Me</i>	2	\$ 60.00	\$ 120.00	<i>+</i>
26	REAR FENDER SEALANT <i>Me</i>	2	\$ 150.00	\$ 300.00	<i>+</i>
27	REAR FENDER INNER COWLING CLIP (SET) <i>Me</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
28	REAR FENDER INNER TRIM CLIP (UPPER) (SET) <i>Me</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
29	REAR FENDER INNER PANEL SEALANT LH <i>Me</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
30	REAR FENDER QUARTER GLASS SEALANT <i>Me</i>	2	\$ 60.00	\$ 120.00	<i>40.</i>
31	REAR FENDER QUARTER GLASS INNER SEAL <i>Me</i>	2	\$ 40.00	\$ 80.00	<i>+</i>
32	REAR FENDER QUARTER GLASS SOLAR FILM <i>Me</i>	2	\$ 80.00	\$ 160.00	<i>+</i>
33	REAR WHEEL HOUSE PANEL SEALANT <i>Me</i>	2	\$ 150.00	\$ 300.00	<i>+</i>
34	REAR WHEELTYRE <i>LH RHT Punctured</i>	1	\$ 480.00	\$ 480.00	<i>200.</i>
35	REAR END PANEL INSULATION SEAL <i>me</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
36	REAR END PANEL TOP GARNISH CLIP (SET) <i>me</i>	1	\$ 50.00	\$ 50.00	<i>10</i>
37	REAR END PANEL BOTTOM (CENTRE) SEALANT <i>Me</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
38	REAR FLOOR PANEL INSULATION SEAL <i>Me</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
39	REAR FLOOR SIDE PANEL SEALANT LH <i>Me</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
40	REAR SPARE TYRE (SPECIAL TYPE) <i>Me</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
41	REVERSE CAMERA <i>Me</i>	1	\$ 480.00	\$ 480.00	<i>+</i>

800

TOTAL \$5,890.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	<i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>800.</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN2893Z**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 13:25HRS

3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
5	REFOCUS HEADLAMP BEAM	\$ 60.00	X
6	REMOVE AND REFIX FRONT FENDER QUARTER GLASS	\$ 200.00	40.
7	REMOVE AND REFIX INTAKE MANIFOLD	\$ 350.00	X
8	TO LIFT UP AND REFIX ENGINE	\$ 650.00	X
9	RESET ENGINE LIGHT	\$ 350.00	X
10	RESET ABS LIGHT	\$ 350.00	X.

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 3,500.00	1600.
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,600.00	1400.
3	TUFF COAT	\$ 450.00	120.
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	120.
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50.
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	50.
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
9	CONDUCT WATER LEAKAGE TEST	\$ 250.00	X
10	TRANSFER REAR DOOR MECHANISM	\$ 160.00	X.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN2893Z**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 13:25HRS

11	REMOVE & REINSTALL REAR WINDOW GLASS	\$ 120.00	120 +
12	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	+
13	FOUR WHEEL ALIGNMNET	\$ 120.00	+
14	REMOVE AND REFIX FENDER QUARTER GLASS X2	\$ 200.00	60
15	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	+ -

TOTAL \$14,550.00

5410

ESTIMATE REPORT

TOTAL PARTS COST : \$61,897.01
 TOTAL LABOUR COST : \$14,550.00
 TOTAL REPAIR COST : \$76,447.01

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE
 SERVICE ADVISOR
 MICHELLE
 HP : 9856 4815

total: 28523.77
 L/S: 22.8K (Nett Value)
 Nett Value: 22.8K.

18 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signatures:
 Date: