

FOCUS AUTO PTE LTD*Not Authorised*

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg**M/S : AIG ASIA PACIFIC INSURANCE PTE LTD**

ATTN : Motor Claim Department

Your Ref No: : **SJE 7535 H**Claim Type : **THIRD PARTY**

Accident Date : 07/12/2020

Not Authorised
14/12/20
2/5 2600
3275
Estimate No : **M001726**

Date: : 09/12/2020

Veh Reg No : **SJE 7535 H**Make/Model : **HONDA STREAM**Chassis No : **RN61046118**Engine No: **R18A1751771**

Reg. Date : 06/05/2008

Estimate Repair Cost for Vehicle No. : SJE 7535 H

PAGE : 1/2

S/N	Description	Quantity	Unit	Price	Amount
	<u>LIST PRICE</u>			<u>S\$</u>	<u>S\$</u>
1	Rear Boot <i>Bodily 12</i>	1	PCS	903.50	903.50 ✓
2	Rear Boot Lock <i>should 10age</i>	1	PCS	183.20	183.20 ✓
3	Rear Boot Rubber <i>YWI</i>	1	PCS	126.60	126.60 ✓
4	Rear Boot Emblem <i>neu</i>	1	PCS	32.70	32.70 ✓
5	Rear Boot Inner Board <i>De/cru</i>	1	PCS	267.40	267.40 ✓
6	Rear Boot Handle Garnish <i>scr</i>	1	PCS	38.20	38.20 X
7	Rear End Panel <i>n</i>	1	PCS	326.70	326.70 X
8	Rear End Panel Top Garnish <i>11</i>	1	PCS	85.20	85.20 X
9	Rear Bumper <i>De/cru</i>	1	PCS	588.90	588.90 ✓
10	Rear Bumper Side Retainer <i>11</i>	2	PCS	42.50	85.00 X
11	Rear Bumper Lower Bracket <i>11</i>	2	PCS	18.40	36.80 X
12	Rear Bumper Clip <i>neu</i>	2	PCS	5.50	11.00 ✓
13	Rear Exhaust Silencer <i>11</i>	1	PCS	586.40	586.40 X
14	Rear Exhaust rubber <i>11</i>	1	PCS	48.20	48.20 X

TOTAL :	3319.80
DISCOUNT 20% :	663.96
SUB TOTAL :	2655.84

SPECIAL NET

Rear Bumper Sensor <i>shrub</i>	1	SET	300.00	300.00 200
Rear Bumper Camera <i>11</i>	1	PCS	450.00	450.00 X
Rear Windscreen Gum <i>neu</i>	1	PCS	80.00	80.00 40

TOTAL :	830.00
----------------	---------------

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

Estimate No : M001726

Date: : 09/12/2020

Veh Reg No : SJE 7535 H

Make/Model : HONDA STREAM

Chassis No : RN61046118

Engine No: R18A1751771

Reg. Date : 06/05/2008

ATTN : Motor Claim Department

Your Ref No: : SJE 7535 H

Claim Type : THIRD PARTY

Accident Date : 07/12/2020

Estimate Repair Cost For Vehicle No. : SJE 7535 H

PAGE : 2/2

LABOUR CHARGES

<u>S\$</u>	<u>S\$</u>
500	950.00
20	60.00
30	80.00
50	250.00
120	160.00
600	820.00

Panel Beating

Check Wiring

Rust Proofing

To Remove & Replace Bumper Sensor & Camera

To Remove & Refix Rear Windscreen

To Spray Painting

TOTAL	1500.00
GRAND TOTAL	4985.84

FOR FOCUS AUTO PTE LTD

Jenny Koh
Claims Executive
HP: 8139 9800

AUTHORISE SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

9-2113.30
20%
9-1690.64
5-N-240.00
L-1320.00
3250.64
20%
2600