

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD0923X**AAD2012-068***Not Authored
L/Ring B*

Vehicle No.:
 Chassis No.: **10 DEC 2020**
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD0923X
VF1ABL15AUC283389
RENAULT
LATITUDE
09/12/2020
AIG
29/12/2017

	PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 561.70 ✓	
2	1 BUMPER LOWER REAR	\$	<i>Bu</i> 411.90 ✓	
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10 X	
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10 X	
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80 X	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80 X	
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20 X	
10	1 BUMPER BEAM REAR	\$	<i>B</i> 547.80 ✓	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50 X	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50 X	
13	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 16.60 X	
14	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 16.60 ✓	
15	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80 X	
16	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i> 404.56 ✓	
17	1 BOOT REAR	\$	<i>R</i> 1,677.20	} X
18	1 BOOT WEATHERSTRIP	\$	<i>SL</i> 178.20	
19	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70	
20	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70	
21	1 BOOT HINGE LH	\$	<i>R</i> 254.20	
22	1 BOOT HINGE RH	\$	<i>R</i> 254.20	
23	1 BOOT LOCK	\$	<i>R</i> 246.60	
24	1 BOOT LOCK CATCH	\$	<i>R</i> 41.70	
25	1 BOOT FINISHER	\$	<i>SL</i> 344.70	
26	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 82.40	
27	1 BOOT BADGE	\$	<i>na</i> 95.80	
28	1 BOOT FINISHER	\$	<i>SL</i> 344.70	
		\$	7,384.06	

Trans-cab Auto Services Pte Ltd

AAD2012-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD0923X

10%	\$	738.41
	\$	<u>6,645.65</u>

Specical Nett

1 1SET PARKING AID	\$	<i>Per</i> 700.00 X
2 1 BOOT FINISHER NUT L70Y	\$	<i>nn</i> 60.00 X
3 1SET REAR BUMPER CLIP	\$	<i>nn</i> 66.00 ✓
4 1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00 X
5 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00 X
6 1SET BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00 X
7 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00 X
8 1SET BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 20.00 X
9 1SET BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00 X
10 1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00 ✓
11 1SET WHEELARCH CLIP	\$	<i>nn</i> 60.00
12 1SET FENDER CLIP	\$	<i>nn</i> 35.00
13 1 EXHAUST MOUNTING REAR	\$	<i>nn</i> 17.82
14 1 REAR NUMBER PLATE WITH HOLDER	\$	<i>Per</i> 120.00 } X
15 1 REAR BOOT STICKER 'Trans-cab'	\$	<i>nn</i> 80.00
16 1 REAR BOOT STICKER '6555-3333'	\$	<i>nn</i> 80.00
TOTAL	\$	1,399.82
TOTAL PARTS	\$	<u>8,045.47</u>

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>4001</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 <i>3001</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 300.00 X
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>

Trans-cab Auto Services Pte Ltd

AAD2012-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD0923X

To transfer of bootlid fittings, attachments and
perform water seepage test. \$ *NA* 170.00 X

To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ *4* 170.00 X

To check steering geometry and computer wheel
alignment \$ *4* 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 *15/*

TOTAL \$ 7,370.00

Over All Total \$ 22,061.13

(LUMP SUM)

Repair Days

20 DAYS

2 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: