

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD0923X**AAD2012-068***Not Authorised
11/12/2017*

Vehicle No.:

Chassis No.:

10 DEC 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD0923X

VF1ABL15AUC283389

RENAULT

LATITUDE

09/12/2020

AIG

29/12/2017

PART

- | | |
|----|------------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMPER BRACKET SIDE RH REAR |
| 5 | 1 BUMPER RETAINER RH REAR |
| 7 | 1 BUMPER BRACKET SIDE LH REAR |
| 8 | 1 BUMPER RETAINER LH REAR |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 BUMPER REFLECTOR LH |
| 14 | 1 BUMPER REFLECTOR RH |
| 15 | 1 OUTER PANEL REAR (End Panel) |
| 16 | 1 OUTER PANEL REAR (End Panel)TRIM |
| 17 | 1 BOOT REAR |
| 18 | 1 BOOT WEATHERSTRIP |
| 19 | 1 BOOT REFLECTOR LAMP LH |
| 20 | 1 BOOT REFLECTOR LAMP RH |
| 21 | 1 BOOT HINGE LH |
| 22 | 1 BOOT HINGE RH |
| 23 | 1 BOOT LOCK |
| 24 | 1 BOOT LOCK CATCH |
| 25 | 1 BOOT FINISHER |
| 26 | 1 BOOT BADGE 'RENAULT' |
| 27 | 1 BOOT BADGE |
| 28 | 1 BOOT FINISHER |

LIST

\$	<i>Bu</i>	561.70	✓
\$	<i>Bu</i>	411.90	✓
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	54.20	X
\$	<i>Bz</i>	547.80	✓
\$	<i>N</i>	114.50	X
\$	<i>N</i>	114.50	X
\$	<i>SL</i>	16.60	X
\$	<i>CM</i>	16.60	✓
\$	<i>N</i>	745.80	X
\$	<i>CM</i>	404.56	✓
\$	<i>N</i>	1,677.20	} X
\$	<i>SL</i>	178.20	
\$	<i>SL</i>	277.70	
\$	<i>SL</i>	277.70	
\$	<i>N</i>	254.20	
\$	<i>N</i>	254.20	
\$	<i>N</i>	246.60	
\$	<i>N</i>	41.70	
\$	<i>SL</i>	344.70	
\$	<i>na</i>	82.40	
\$	<i>na</i>	95.80	
\$	<i>SL</i>	344.70	

\$

7,384.06

Trans-cab Auto Services Pte Ltd

AAD2012-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD0923X

10%	\$	738.41
	\$	<u>6,645.65</u>

Special Nett

1 1SET PARKING AID	\$	<i>pu</i> 700.00	X
2 1 BOOT FINISHER NUT L70Y	\$	<i>na</i> 60.00	X
3 1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	✓
4 1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	X
5 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	X
6 1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00	X
7 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	X
8 1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00	X
9 1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	X
10 1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	✓
11 1SET WHEELARCH CLIP	\$	<i>na</i> 60.00	} X
12 1SET FENDER CLIP	\$	<i>na</i> 35.00	
13 1 EXHAUST MOUNTING REAR	\$	<i>na</i> 17.82	
14 1 REAR NUMBER PLATE WITH HOLDER	\$	<i>pu</i> 120.00	
15 1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i> 80.00	
16 1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i> 80.00	
TOTAL	\$	1,399.82	
TOTAL PARTS	\$	<u>8,045.47</u>	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>4001</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>3001</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 300.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>

Trans-cab Auto Services Pte Ltd**AAD2012-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD0923X

To transfer of bootlid fittings, attachments and
perform water seepage test. \$ *nn* 170.00 X

To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ *4* 170.00 X

To check steering geometry and computer wheel
alignment \$ *4* 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 *15/*

TOTAL \$ 7,370.00**Over All Total \$ 22,061.13****(LUMP SUM)****Repair Days***20 DAYS**2 days***For Official Use**

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: