

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E
 8 Kaki Bukit Avenue 4
 #08-09 Premier @ Kaki Bukit
 Singapore 415875
 Tel: 6341 6789 Fax: 6341 6778
 Email: smartoneauto@gmail.com



DATE : 14.12.20

TO : **NTUC MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SLG6422Y**
 MODEL : **HYUNDAI ELANTRA**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 19:30HRS

Denise

KMH D841CMHU219694

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>del</i>	1	\$ 757.40	\$ 757.40
2	REAR BUMPER REFLECTOR <i>crackd LH</i>	2	\$ 72.50	\$ 145.00
3	REAR BUMPER LOWER LIP <i>del</i>	1	\$ 395.10	\$ 395.10
4	REAR BUMPER RETAINER <i>new</i>	2	\$ 57.30	\$ 114.60
5	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 494.81	\$ 494.81
6	REAR BUMPER BRACKET <i>Damaged</i>	5	\$ 35.40	\$ 177.00
7	REAR BUMPER INNER GRANISH RH <i>new</i>	1	\$ 87.50	\$ 87.50
8	REAR BUMPER INNER GARNISH LH <i>torn</i>	1	\$ 98.60	\$ 98.60
9	REAR BLIND SPOT WIRE HARNESS <i>new</i>	1	\$ 425.30	\$ 425.30
10	REAR BLIND SPOT SENSOR <i>new crackd</i>	2	\$ 896.40	\$ 1,792.80
11	REAR BLIND SPOT SENSOR BRACKET <i>new</i>	2	\$ 78.10	\$ 156.20
12	REAR FENDER INNER COWLING <i>new</i>	2	\$ 146.80	\$ 293.60
13	REAR FENDER INNER TRIM <i>new</i>	2	\$ 279.80	\$ 559.60
14	TAILLAMP <i>LH crackd</i>	2	\$ 876.80	\$ 1,753.60
15	BOOTLID <i>crackd</i>	1	\$ 1,578.10	\$ 1,578.10
16	BOOTLID LAMP <i>new</i>	2	\$ 378.90	\$ 757.80
17	BOOTLID DETECTOR (INNER) <i>new</i>	1	\$ 389.10	\$ 389.10
18	BOOTLID DETECTOR (OUTER) <i>crackd</i>	1	\$ 396.40	\$ 396.40
19	BOOTLID LOGO <i>new</i>	1	\$ 59.60	\$ 59.60
20	BOOTLID EMBLEM 'ELANTRA' <i>new</i>	1	\$ 62.80	\$ 62.80
21	BOOTLID DETECTOR WIRE HARNESS <i>new</i>	1	\$ 438.10	\$ 438.10
22	BOOTLID HINGE <i>new new</i>	2	\$ 94.30	\$ 188.60
23	BOOTLID STOPPER <i>3mm</i>	2	\$ 19.20	\$ 38.40
24	BOOTLID INSULATOR <i>new</i>	1	\$ 179.80	\$ 179.80
25	BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 166.70	\$ 166.70
26	BOOTLID LOWER LOCK <i>new</i>	1	\$ 19.10	\$ 19.10
27	BOOTLID WEATHER STRIP <i>cut</i>	1	\$ 152.60	\$ 152.60
28	REAR END PANEL <i>Dented</i>	1	\$ 569.40	\$ 569.40

474
72.50
297
80
896.40
876.80
189

TO : NTUC MOTOR CLAIMS DEPTS
 VEHICLE NO : SLG6422Y
 MODEL : HYUNDAI ELANTRA
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 19:30HRS

29	REAR END PANEL TOP GARNISH <i>Rehard</i>	1	\$ 142.30	\$ 142.30	✓
30	REAR FLOOR PANEL <i>Repis</i>	1	\$ 1,179.70	\$ 1,179.70	+
31	REAR FLOOR PANEL TOP BOARD <i>Rehard</i>	1	\$ 246.60	\$ 246.60	✓
32	REAR CHASSIS RH <i>Re m</i>	1	\$ 1,249.10	\$ 1,249.10	+
33	REVERSE CAMERA <i>Re m</i>	1	\$ 875.40	\$ 875.40	+

6472.10
5177.68

TOTAL PRICE \$ 15,940.71
 LESS 20% \$ 3,188.14
 SUB TOTAL PRICE \$ 12,752.57

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Ne m</i>	1	\$ 80.00	\$ 80.00	x
2	REAR BUMPER CLIP (SET) <i>Ne</i>	1	\$ 80.00	\$ 80.00	30
3	BOOT LID INSULATOR CLIP (SET) <i>Ne m</i>	1	\$ 50.00	\$ 50.00	+
4	BOOTLID EMBLEM 'ELITE' (SPECIAL TYPE) <i>Ne</i>	1	\$ 80.00	\$ 80.00	50
5	TAIL LAMP CLIP (SET) <i>Ne</i>	1	\$ 40.00	\$ 40.00	10
6	REAR FENDER INNER COWLING CLIP (SET) <i>Ne m</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>Ne m</i>	1	\$ 80.00	\$ 80.00	+
8	REAR END PANEL SEALANT <i>Ne</i>	1	\$ 150.00	\$ 150.00	60
9	REAR END PANEL TOP GARNISH CLIP (SET) <i>Ne</i>	1	\$ 40.00	\$ 40.00	10
10	TRANGLE BREAKDOWN SIGN <i>Ne m</i>	1	\$ 180.00	\$ 180.00	x
11	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

360

TOTAL \$ 1,080.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X

TO : **NTUC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLG6422Y**
 MODEL : **HYUNDAI ELANTRA**
 DATE OF ACCIDENT : 12.12.20
 TIME OF ACCIDENT : 19:30HRS

9	TRANSFER BOOTLID MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
11	REMOVE AND REFIX AND RESET BLIND SPOT SENSOR	\$ 350.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$ 4,750.00

1930

Adrian Lij

h/s 15/12/20

06 Days!

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,832.57
 TOTAL LABOUR COST : \$ 4,750.00
 TOTAL REPAIR COST : \$ 18,582.57

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

total: 7467.68

YOURS FAITHFULLY,

h/s: 5.9K

MICHELLE

SERVICE ADVISOR
 MICHELLE
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: