

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
Kaki Bukit Autohub, Singapore 417921  
Tel No. : 67461515 / 67471787 Fax No. : 67485015  
Website : www.successunited.com.sg  
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way, #07-16  
Singapore 079120  
Attention : Motor Claim Department  
Contact : 64191053 Fax No. : 68357416

Xiao Tony.

## Estimate : TP20-113

Date : 12/12/2020  
Vehicle Num. : SFN8269U  
Make/Model : Honda Airwave-2008  
Chassis/Eng# : GJ11304260/L15A5205091  
Accident Date : 11/12/2020  
Claim No. :  
Reference :  
Policy No. : (14/11/2021)

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|              |       |                              |           |            |
|--------------|-------|------------------------------|-----------|------------|
| LIST ITEMS : |       |                              |           |            |
| 1.           | 1 pc  | Frt Bumper Assy              | Distorted | 1,150.00 ✓ |
| 2.           | 1 pc  | Frt Bumper Side Holder LH    | Disheld   | 35.20 ✓    |
| 3.           | 1 pc  | Frt Bumper Tow Hook Cover    | Del-d     | 28.00 ✓    |
| 4.           | 1 pc  | Frt Bumper Foglamp Cover LH  | cut       | 86.13 ✓    |
| 5.           | 1 pc  | Frt Bumper Reinforcement     | new       | 323.50 ✓   |
| 6.           | 1 pc  | Frt Grille Assy              | cut       | 687.80 ✓   |
| 7.           | 1 pc  | Headlamp Assy LH             | smashed.  | 725.10 ✓   |
| 8.           | 1 pc  | Headlamp Bracket LH          | cut       | 48.50 ✓    |
| 9.           | 1 pc  | Frt Fender LH                | Distorted | 655.00 ✓   |
| 10.          | 1 pc  | Frt Fender Inner Liner LH    | cut       | 121.00 ✓   |
| 11.          | 8 pcs | Frt Fender Inner Liner Clips | new       | 31.20 ✓    |
| 12.          | 1 pc  | Bonnet                       | Rep       | 800.00 ✓   |
| 13.          | 1 pc  | Bonnet Hinge LH              | new       | 47.30 ✓    |

List Total S\$ :  
20.00% Discount S\$ :

3178.63  
2542.90

4,738.73  
947.75  
3,790.98

### LABOUR :

To remove, rearrange electrical wirings, check lighting

80.00 30

To remove, instal aircon parts, vacuum, refill gas.

150.00 X

To remove, repair and replaced damaged bodyparts,  
realign bodyworks & where consistent to the accident

950.00 500

To putty and respray painting on affected area.

1,200.00 600

Labour Total S\$ :

2,380.00

Total S\$ : 6,170.98

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To inspect damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from insurance company

Acknowledged by Repairer  
Signature:  
Date:

total: 3672.90  
h/s: 2.9K

Adrian Lij  
h/s 14/12/20  
05 Days.