

China (L8um)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.12.2020

REPAIR ESTIMATE

Time: 16:45:38

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305439041
REGN NO : SHC8138Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.04.2016
DATE/TIME IN : 14.12.2020 12:35
ACCIDENT DATE : 14.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0595-G	I40VC PANEL ASSY-RR DR RH	1	2,201.10	20.00	1,760.88
0002 04-01-0103-0592-G	I40VC PANEL ASSY-FR DR RH	1	2,256.40	20.00	1,805.12
0003 04-01-0103-0810-G	I40VC MOULDING ASSY-SIDE	1	732.80	20.00	586.24
0004 28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	75.00	2.00-	75.00
0005 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00	0.20	80.00

SUB-TOTAL : 4,307.24

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 L	TRANSFER DOOR PART

600.00	280
700.00	400
240.00	60

SUB-TOTAL : 1,540.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Final
Hp 90000068
3 days
4/5
14/12/2020
@ 1745
Res after repair

1915.88
740.00
2655.88
202
2,124.70
4/5-2/100
3 day