

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 24 Dec 2020

Preliminary Advice

Insured Vehicle No : GBC1235T
TP Vehicle No : SMW7312D
Make : TOYOTA ALPHARD
Date of Inspection : 16/12/2020
Inspection At : EURO SUCCESS SERVICES PTE LTD (HQ)
1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY
SINGAPORE 417883
Accident Date : 11/12/2020
Assignment Date : 15/12/2020
Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,982.92
Revised Amount	:S\$	6,887.09
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,887.09
Lump Sum Repair	:S\$	5,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.