

# WENG KEE MOTOR

## REPAIR ESTIMATE

VEHICLE: GZ 8820 C  
MODEL: Nissan NV200

- and repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party ~~2740~~ 2827-35 Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

| S/n               | Description of part                 | Qty |            |
|-------------------|-------------------------------------|-----|------------|
| 1                 | Rear bumper / CUT                   | 1   |            |
| 2                 | Rear bumper side bracket LH/RH / RR | 2   |            |
| 3                 | Rear tailgate LH / DD               | 1   | 1,281.90 / |
| 4                 | Rear tailgate RH / DD               | 1   | 960.90 /   |
| 5                 | Rear tailgate RH rubber stripe X NM | 1   | 122.30 X   |
| 6                 | Rear tailgate LH garnish X NM       | 1   | 336.00 X   |
| 7                 | Rear tailgate logo / NK             | 1   | 75.00 /    |
| 8                 | Rear tailgate emblem 'NV200' / NK   | 1   | 75.00 /    |
| 9                 | Rear tailgate emblem 'Dci' / NK     | 1   | 32.20 /    |
| 10                | Rear tailgate lock mechanism / DD   | 1   | 150.00 /   |
| Sub-total 1       |                                     |     | 3,599.80   |
| Less Discount 10% |                                     |     | 3,239.82   |

|             |                                        |   |                    |
|-------------|----------------------------------------|---|--------------------|
| 11          | Rear Sticker '70 km/hr' / NK           | 1 | 40.00 30 /         |
| 12          | Rear Sticker '6 pax' / NK              | 1 | 40.00 30 /         |
| 13          | Rear number plate X NM                 | 1 | 50.00 X            |
| 14          | Rear LH windscreen primer / NK         | 1 | 30.00 20 /         |
| 15          | Rear LH windscreen support sponge / NK | 1 | 30.00 20 /         |
| 16          | Rear LH windscreen sealant / NK        | 1 | 45.00 30 /         |
| 17          | Rear RH windscreen primer / NK         | 1 | 30.00 20 /         |
| 18          | Rear RH windscreen support sponge / NK | 1 | 30.00 20 /         |
| 19          | Rear RH windscreen sealant / NK        | 1 | 45.00 30 /         |
| 20          | Reverse sensor / SH                    | 1 | 200.00 /           |
| Sub-total 2 |                                        |   | 540.00 (Nett item) |
| Parts total |                                        |   | 3,779.82           |

### Labour

|                      |                                                                                        |            |
|----------------------|----------------------------------------------------------------------------------------|------------|
| 21                   | To straighten and panel beating side frame members. To remove and replace above parts. | 800.00 400 |
| 22                   | To putty, re-spray painting and polish affected areas.                                 | 700.00 400 |
| 23                   | To remove and refit LH tailgate glass                                                  | 150.00 80  |
| 24                   | To remove and refit RH tailgate glass                                                  | 150.00 80  |
| 25                   | Repair wire harness                                                                    | 60.00 30   |
| Labour total         |                                                                                        | 1,860.00   |
| Parts & Labour total |                                                                                        | 5,639.82   |

5 day CLKK

11-31-14

L/S

AL dy

Labour total 1,860.00

Parts & Labour total 5,639.82

2827-35

NI-490

L-990

4217-35

L/S-3373.88

= 3350