

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 02 Jul 2021

**Preliminary Advice**

Insured Vehicle No : FBN600X  
TP Vehicle No : SLB4590J  
Make : FORD FOCUS  
Date of Inspection : 5/2/2021  
Inspection At : CHENG HOE MOTOR SERVICE

Accident Date : 09/12/2020  
Assignment Date : 15/12/2020  
Est. Duration of Repair : 4

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,492.40 |
| Revised Amount              | :S\$ | 4,129.00 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 4,129.00 |
| Lump Sum Repair             | :S\$ | 3,250.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair  
  
 ( X ) The above survey was conducted on a 'without prejudice' basis.